

ASS. REC. BY:

REF:

CS INC 1907289 / Agf3 N2

Special Instruction:

Surveyor AdrianASSIGNMENT (Office)From (Person): Theresa Vimalaof INCDate/Time: 01/10/2019

Estimated Cost:

Bill to:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLA 5802YInsured: SSD 1575Lat Workshop m/s Vision Autowork Pte LtdTel: 9856 4815of 8 Kaki Bukit Ave 4 #06-09

Policy No:

Claim No: MT/1064405-001

Sum Insured:

Excess:

Make of Veh:

D.O.A. 27/09/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time: 01/10/2019 @ 04:45pm

Person Contacted:

AbbyVehicle: ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SSD 1575L X
	SLA 5802Y X
	US \$ 3000, 3 days. (Red \$ 13411.76, 82%)

NEF:

ASSIGNMENT

Veh No: SLAS8027 Yr Regn: 2016 March

Type: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 116 D. CC: 1496

Colour Blue A/C: Insured / Std / NI / NA

Sp. Reading 69321 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA1V720XOV724158

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16-

R: 205/55R16

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO of

Front

Rear

R/Bal. *ob.* mm R/Bal. *ob.* mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 01/10/19.

Survey held at Vision 1/1/2018

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP INC.
	RECEIVED 26 NOV 2019
	MV :
	PV :
	Nett :

☐: Prel. Report

☐ : Final Report

Days Of Repair: 7

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$

☐ Interview (\$

☐ Tech. Invs. (3)

☐ Weekend (8)

Survey Fee:

Transportation

Findings

Category	Value
Category 1	Value 1
Category 2	Value 2
Category 3	Value 3
Category 4	Value 4
Category 5	Value 5
Category 6	Value 6
Category 7	Value 7
Category 8	Value 8
Category 9	Value 9
Category 10	Value 10
Category 11	Value 11
Category 12	Value 12
Category 13	Value 13
Category 14	Value 14
Category 15	Value 15
Category 16	Value 16
Category 17	Value 17
Category 18	Value 18
Category 19	Value 19
Category 20	Value 20
Category 21	Value 21
Category 22	Value 22
Category 23	Value 23
Category 24	Value 24
Category 25	Value 25
Category 26	Value 26
Category 27	Value 27
Category 28	Value 28
Category 29	Value 29
Category 30	Value 30
Category 31	Value 31
Category 32	Value 32
Category 33	Value 33
Category 34	Value 34
Category 35	Value 35
Category 36	Value 36
Category 37	Value 37
Category 38	Value 38
Category 39	Value 39
Category 40	Value 40
Category 41	Value 41
Category 42	Value 42
Category 43	Value 43
Category 44	Value 44
Category 45	Value 45
Category 46	Value 46
Category 47	Value 47
Category 48	Value 48
Category 49	Value 49
Category 50	Value 50
Category 51	Value 51
Category 52	Value 52
Category 53	Value 53
Category 54	Value 54
Category 55	Value 55
Category 56	Value 56
Category 57	Value 57
Category 58	Value 58
Category 59	Value 59
Category 60	Value 60
Category 61	Value 61
Category 62	Value 62
Category 63	Value 63
Category 64	Value 64
Category 65	Value 65
Category 66	Value 66
Category 67	Value 67
Category 68	Value 68
Category 69	Value 69
Category 70	Value 70
Category 71	Value 71
Category 72	Value 72
Category 73	Value 73
Category 74	Value 74
Category 75	Value 75
Category 76	Value 76
Category 77	Value 77
Category 78	Value 78
Category 79	Value 79
Category 80	Value 80
Category 81	Value 81
Category 82	Value 82
Category 83	Value 83
Category 84	Value 84
Category 85	Value 85
Category 86	Value 86
Category 87	Value 87
Category 88	Value 88
Category 89	Value 89
Category 90	Value 90
Category 91	Value 91
Category 92	Value 92
Category 93	Value 93
Category 94	Value 94
Category 95	Value 95
Category 96	Value 96
Category 97	Value 97
Category 98	Value 98
Category 99	Value 99
Category 100	Value 100

TOTAL

250

Nivitha (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Tuesday, 1 October 2019 10:43 AM
To: assignments
Cc: Theresa Vimala D/O Balagangadharan
Subject: RE: TP CASES FARMED OUT TO LKK ON 01/10/2019

Hi Lkk

Here is the OIC, clm ref details. Thank you.

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
T +65 6430 7898
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

From: Theresa Vimala D/O Balagangadharan
Sent: Tuesday, 1 October 2019 10:38 AM
To: assignments <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Subject: FW: TP CASES FARMED OUT TO LKK ON 01/10/2019

Dear LKK

Please assist to survey the following vehicles as per Tse Kiat instruction :-

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	DI VEH	DOA	Additional Remarks
1	chrillia	MT/1064658-001	1/10/2019	SIH8180A	DYNAMIC AUTOWORK PTE LTD	8 KAKI BUKIT AVENUE 4 #08-09 PREMIER @ KAKI BUKIT	michelle/abby / 98564815		PC2779T	30/9	
2	airwan	MT/1063358-002	1/10/2019	GBH8281L	GOLDBELL ENGINEERING PTE LTD	NO 8 KAKI BUKIT AVENUE 4 #05-24 PREMIER @ KAKI BUKIT	soo leong keat / 97397127	10:00-12:00	SGC5233M	19/9	
3	cyndia	MT/1064390-002	1/10/2019	5HB8586T	PREMIER AUTOMOTIVE SERVICES PTE LTD	23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443	LIEW / 65446689		SKH9807H	27/9	
4	rajeswary	MT/1064646-001	1/10/2019	SIJ9946R	SK AUTOMOBILE PTE LTD	8 KAKI BUKIT AVENUE 4 #08-45/46 PREMIER@KAKI BUKIT	CHRIS / 67021555		SKR4181J	24/9	
5	jared	MT/1064674-001	1/10/2019	PC1827U	SK AUTOMOBILE PTE LTD *	8 KAKI BUKIT AVENUE 4 #08-46 PREMIER@KAKI BUKIT	chris / 67021555		YP2054B	27/9	
6	Helena tan	MT/1064644-001	1/10/2019	SIK9606S	SK AUTOMOBILE PTE LTD	8 KAKI BUKIT AVENUE 4 #08-46 PREMIER@KAKI BUKIT	julie / 96234440		SKX6194X	24/9	
7	charlotte	MT/1064405-001	1/10/2019	3LA5802Y	VISION AUTOWORK PTE. LTD.	KAKI BUKIT AVENUE 4 #08-09 PREMIER @ KAKI BUKIT	abby / 98564815		SJD1575L	27/9	michelle 63416789
8	charlotte	MT/1064678-001	1/10/2019	3LR8808Y	VISION AUTOWORK PTE. LTD.	KAKI BUKIT AVENUE 4 #08-09 PREMIER @ KAKI BUKIT	abby / 98564815		SLX7139U	29/9	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
T +65 6430 7898
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at Income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/09/2019 15:47
Date Of Accident	27/09/2019 08:35
Exact Location Of Accident	TPE TOWARDS CHANGI (AT UPPER CHANGI NORTH RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA5802Y
Insured/Policyholder	
Name Of Registered Owner	PURUSHOTHAMAN EZHIL
NRIC No	S7182461F
Email Address	PEZHIL@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96525770
Alternative Phone No	OFFICE-96525770

Vehicle Particulars

Manufacturer	BMW
Model	116 D
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D19MTPV01003135
Cover Note Number	

Driver

Name of Driver	PURUSHOTHAMAN EZHIL
NRIC No	S7182461F
Date Of Birth	06/04/1971
Occupation	INDOOR
Date Of Driving Pass	12/12/1997
Driving Experience	21 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96525770
Fax Number	
Contact Number	OFFICE-96525770
Email Address	PEZHIL@GMAIL.COM

Address	BLK 649 WOODLANDS RING ROAD #04-446
Postcode	730649
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJD1575L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



A= SLA58027

B= SJD 1575L


TPE towards Changi
(At Upper Changi Road
North Exit 1)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attach

DECLARATION

(We declare the foregoing particulars are true in every respect.)



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

COMFORTCLERM ENGINEERING PTE. LTD.
330 LUN ROAD 3
SINGAPORE 100308
TEL: 6746 7556 FAX: 6743 6072

Reporting Centre Personnel's Signature
Name
NRIC/FIN No.:

On 27.09.19 at about 08:35 hours along TPE towards Changi (At Upper Changi Road North Exit 1). I was travelling straight on lane 1 and the traffic was moderate, when my front vehicle stopped hence I slowed down and stopped.

Suddenly I heard a loud bang from behind. When I alighted I realised it was vehicle (B) collided onto rear portion of my vehicle (A).

Vehicle (A): SLA 5802Y

Vehicle (B): SJD 1575L

A handwritten signature in black ink, appearing to be 'F. Ghil', is located to the right of the vehicle information.

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:visionautowork@gmail.com

DATE : 01.10.19

TO : NTUC MOTOR CLAIMS DEPTS

VEHICLE NO : SLA5802Y

MODEL : BMW 116D

DATE OF ACCIDENT : 27.09.19

TIME OF ACCIDENT : 08:35RS

XiaoChen WBA1V720X0V724158.

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Refer d</i>	1	\$ 1,064.45	\$ 1,064.45
2	REAR BUMPER REFLECTOR <i>Refer d</i>	2	\$ 102.30	\$ 204.60
3	REAR BUMPER SENSOR <i>2 pieces d</i>	4	\$ 341.60	\$ 1,366.40
4	REAR BUMPER SENSOR HOLDER <i>new</i>	4	\$ 69.35	\$ 277.40
5	REAR BUMPER SENSOR WIRE HARNESS <i>new</i>	1	\$ 444.60	\$ 444.60
6	REAR BUMPER TOWING COVER <i>new</i>	1	\$ 35.35	\$ 35.35
7	REAR BUMPER TAILGATE DETECTOR <i>new</i>	1	\$ 493.30	\$ 493.30
8	REAR BUMPER REINFORCEMENT <i>Bent</i>	1	\$ 1,043.40	\$ 1,043.40
9	REAR BUMPER NUMBER PLATE LAMP <i>new</i>	2	\$ 84.10	\$ 168.20
10	REAR FENDER INNER COWLING <i>Refer d</i>	2	\$ 236.45	\$ 472.90
11	REAR BUMPER SIDE BRACKET (PLASTIC) <i>LH cabod</i>	2	\$ 367.35	\$ 734.70
12	REAR BUMPER SIDE INNER GARNISH <i>cabod</i>	2	\$ 149.15	\$ 298.30
13	REAR BUMPER CENTER TRIM <i>cabod</i>	1	\$ 370.90	\$ 370.90
14	TAIL LAMP <i>new</i>	2	\$ 599.10	\$ 1,198.20
15	TAILGATE WEATHER STRIP <i>new</i>	1	\$ 384.60	\$ 384.60
16	REAR END PANEL <i>2 pce</i>	1	\$ 749.10	\$ 749.10
17	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 374.50	\$ 374.50
18	REAR EXHAUST PIPE WITH MUFFLER <i>new</i>	1	\$ 964.10	\$ 964.10
19	REAR EXHAUST MOUNTING <i>new</i>	4	\$ 34.85	\$ 139.40
20	REAR EXHAUST PIPE BRACKET <i>new</i>	1	\$ 96.45	\$ 96.45
21	REAR EXHAUST MUFFLER INSULATOR (REAR) <i>2 pce</i>	1	\$ 343.60	\$ 343.60
22	REAR EXHAUST CHROME PIPE <i>Bent</i>	2	\$ 188.70	\$ 377.40

3244-60
208237

TOTAL PRICE \$ 11,601.85
LESS 5% \$ 580.09
SUB TOTAL PRICE \$ 11,021.76

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Not New</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00

TO : NTUC MOTOR CLAIMS DEPTS
 VEHICLE NO : SLA5802Y
 MODEL : BMW 116D
 DATE OF ACCIDENT : 27.09.19
 TIME OF ACCIDENT : 08:35RS

3	REAR BUMPER SIDE INNER GARNISH CLIP (SET) <i>Not on</i>	1	\$ 50.00	\$ 50.00	<i>20</i>
4	REAR BUMPER CENTER TRIM CLIP (SET) <i>Not on</i>	1	\$ 50.00	\$ 50.00	<i>x</i>
5	REAR FENDER INNER COWLING <i>Not on</i>	1	\$ 60.00	\$ 60.00	<i>x</i>
6	REAR FENDER INNER TRIM CLIP (SET) <i>Not on</i>	1	\$ 60.00	\$ 60.00	<i>x</i>
7	TAILLAMP CLIP (SET) <i>Not on</i>	1	\$ 60.00	\$ 60.00	<i>x</i>
8	REAR END PANEL INSULATION SEAL <i>2x4</i>	1	\$ 150.00	\$ 150.00	<i>x</i>
9	REAR END PANEL TOP GARNISH CLIP (SET) <i>1m</i>	1	\$ 50.00	\$ 50.00	<i>x</i>

50

TOTAL \$ 610.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,400.00	<i>300</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	<i>250</i>
3	TUFF COAT	\$ 250.00	<i>x</i>
4	WIRING AND BULB CHECK	\$ 250.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	<i>x</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 150.00	<i>60</i>
7	CONDUCT WATER LEAKAGE TEST	\$ 120.00	<i>x</i>
8	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	<i>x</i>
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 680.00	<i>x</i>

640

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged parts during resurvey

• Parts prices are subject to change

• Third party liability is subject to court judgement

• No illegal works to be carried out

• Supplementary items must be resurveyed and is subject to resurvey only

• NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE

CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED

Acknowledged by Repairer

Signature: ACCORDINGLY WHICH HOWEVER YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

Date: PARTS PRICES ARE SUBJECT TO CHANGES.

TOTAL

4780

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,631.76

TOTAL LABOUR COST : \$ 4,780.00

TOTAL REPAIR COST : \$ 16,411.76

Adrian Lj
4/s 01/10/19.
032ys

total 3772.37

4/s 3K

3K



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Ref: CS/INC19017289/Aqf3n2

Date: 26-11-2019



ATTN: CHARLOTTE

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJD 1575L	Veh. Inspected	SLA 5802Y
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1064405-001	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	01/10/2019

2. Vehicle Particulars & Condition

Make & Model	B.M.W 116D	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WBA1V720X0V724158	Colour	BLUE
Odometer	69321 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm
L/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/09/2019	Inspect Date / Time	01/10/2019 (02:28 PM)
Survey held at	VISION AUTOWORK PTE LTD 8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 5802Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	1,064.45	1,064.45
2	REAR BUMPER REFLECTOR @\$102.30	N/S CRACKED	204.60	102.30
4	REAR BUMPER SENSOR @\$341.60	DAMAGED (2 PCS ONLY)	1,366.40	500.00
4	REAR BUMPER SENSOR HOLDER @\$69.35	NOT NECESSARY	277.40	-
1	REAR BUMPER SENSOR WIRE HARNESS	NOT NECESSARY	444.60	-
1	REAR BUMPER TOWING COVER	NOT NECESSARY	35.35	-
1	REAR BUMPER TAILGATE DETECTOR	NOT NECESSARY	493.30	-
1	REAR BUMPER REINFORCEMENT	BENT	1,043.40	738.00
2	REAR BUMPER NUMBER PLATE LAMP @\$84.10	NOT NECESSARY	168.20	-
2	REAR FENDER INNER COWLING @\$236.45	NOT NECESSARY	472.90	-
2	REAR BUMPER SIDE BRACKET (PLASTIC) @\$367.35	N/S CRACKED	734.70	189.00
2	REAR BUMPER SIDE INNER GARNISH @\$149.15	CRACKED	298.30	149.15
1	REAR BUMPER CENTER TRIM	CRACKED	370.90	313.00
2	TAIL LAMP @\$599.10	NOT NECESSARY	1,198.20	-
1	TAILGATE WEATHER STRIP	NOT NECESSARY	384.60	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	749.10	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	374.50	-
1	REAR EXHAUST PIPE WITH MUFFLER	NOT NECESSARY	964.10	-
4	REAR EXHAUST MOUNTING @\$34.85	NOT NECESSARY	139.40	-
1	REAR EXHAUST PIPE BRACKET	NOT NECESSARY	96.45	-
1	REAR EXHAUST MUFFLER INSULATOR (REAR)	NOT NECESSARY	343.60	-
2	REAR EXHAUST CHROME PIPE @\$188.70	BENT	377.40	188.70
	LESS 5% DISCOUNT		-580.09	-162.23
			11,021.76	3,082.37
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	80.00	30.00
1	SET REAR BUMPER SIDE INNER GARNISH CLIP (SN)	NECESSARY	50.00	20.00
1	SET REAR BUMPER CENTER TRIM CLIP (SN)	NOT NECESSARY	50.00	-

Report Ref No. CS/INC19017289/Aqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER INNER COWLING (SN)	NOT NECESSARY	60.00	-
1	SET REAR FENDER INNER TRIM CLIP (SN)	NOT NECESSARY	60.00	-
1	SET TAILLAMP CLIP (SN)	NOT NECESSARY	60.00	-
1	REAR END PANEL INSULATION SEAL (SN)	NOT NECESSARY	150.00	-
1	SET REAR END PANEL TOP GARNISH CLIP (SN)	NOT NECESSARY	50.00	-
			610.00	50.00
	LABOUR			
	TO PANEL BEAT,REMOVE AND REPLACE PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		1,400.00	300.00
	TO SPRAY PAINT AFFECTED AREA.		1,400.00	250.00
	TUFF COAT.	NOT NECESSARY	250.00	-
	WIRING AND BULB CHECK.		250.00	30.00
	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILIATE REPAIR.	NOT NECESSARY	350.00	-
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		150.00	60.00
	TO CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	120.00	-
	REMOVE AND REFIX REAR EXHAUST PIPE.	NOT NECESSARY	180.00	-
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	680.00	-
			4,780.00	640.00
GRAND TOTAL			16,411.76	3,772.37
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				3,000.00

Report Ref No. CS/INC19017289/Aqf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.