

20	REAR EXHAUST MOUNTING	<i>new</i>	2	\$ 19.20	\$ 38.40
----	-----------------------	------------	---	----------	----------

14773
1143.14

TOTAL PRICE \$ 7,279.80
LESS 20% \$ 1,455.96
SUB TOTAL PRICE \$ 5,823.84

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP <i>new</i>	10	\$ 6.50	\$ 65.00
3	REAR BUMPER LOWER SPOILER <i>Deland</i>	1	\$ 1,800.00	\$ 1,800.00
4	BOOT LID INSULATOR CLIP <i>new</i>	10	\$ 6.50	\$ 65.00
5	BOOTLID OUTER HANDLE GARNISH CLIP <i>new</i>	4	\$ 6.50	\$ 26.00
6	BOOT LID SEALANT <i>2 not</i>	1	\$ 80.00	\$ 80.00
7	TAIL LAMP CLIP <i>new</i>	4	\$ 8.00	\$ 32.00
8	TAIL LAMP PANEL SEALANT	2	\$ 80.00	\$ 160.00
9	REAR FENDER INNER COWLING RH CLIP <i>2</i>	10	\$ 6.50	\$ 65.00
10	REAR FENDER INNER TRIM RH CLIPS <i>new</i>	10	\$ 6.50	\$ 65.00
11	REAR END PANEL SEALANT	1	\$ 80.00	\$ 80.00
12	REAR FLOOR PANEL INSULATION SEAL	1	\$ 250.00	\$ 250.00
13	REVERSE SENSOR <i>Deland</i>	1	\$ 220.00	\$ 220.00

230

TOTAL \$ 2,958.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$1,600.00	<i>500</i>
2	TO SPRAY PAINT AFFECTED AREA	\$1,400.00	<i>800</i>
3	TUFF COAT	\$250.00	<i>60</i>
4	WIRING CHECK	\$60.00	<i>30</i>
5	REMOVE AND REFIX UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$180.00	<i>50</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$80.00	<i>40</i>
7	TRANSFER BOOTLID MECHANISM	\$80.00	<i>x</i>
8	CONDUCT WATER LEAKAGE TEST	\$80.00	<i>x</i>
9	REMOVE AND REFIX REAR EXHAUST PIPE	\$180.00	<i>x</i>

1480

TOTAL

\$3,910.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,781.84
TOTAL LABOUR COST : \$ 3,910.00
TOTAL REPAIR COST : \$ 12,691.84

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

Adrian King
L/S 16/06/90
04 days.

total: 3453.44.
L/S: 2.71c