

ASS. REC. BY:

REF: CS/INC/90172921 F9, f36v

Special Instruction:

Surveyor : Ram

ASSIGNMENT (Office)

From (Person): Theresa vimala of INC Date/Time: 01/10/2019

Estimated Cost: _____ Bill to: _____

OD / TR / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJS 9946R Insured: SKR 41813

at Workshop m/s SK Automobile Pte Ltd Tel: 6702 1555

of 8 Kaki Bukit Ave 4 #08-45/46

Policy No: _____ Claim No: MT1064646-001

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 24/09/2019
(Client's Record)

"WP"

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 01/10/2019 @ 04:34pm Person Contacted: Chris Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SKR 418LT : X
	STJ 4946R : X

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJJ 9946R

at Workshop m/s SK automobile

of 8 KAKI BUKT AVE 4#08-46

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle, IN / OUT

Veh No: SJJ 9946R

Yr Regn: Sep / 2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota allion 1.5A

c.c. 1496

Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 202000

T/Radio: Insured / Std / NI / NA

Eng/No: -

C/No: NZT260-3032689

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45 R17

R: 215/45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or NEXEN

Front

Rear

R/Bal. 4 mm

R/Bal. 4 mm

L/Bal. 4 mm

L/Bal. 4 mm

D.O.A. 24/09/2019

D.O.I. 2/10/19 04:00pm

Survey held at

SK automobile

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt / Rear / O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

L/S: \$8400/- confirm with Huey Lee
6 repair days 15/10/19 10:21am

RECEIVED 8 OCT 2019

MV: \$26022

RV: \$12944

NV: \$13078

Date/Time, File Pass to?

☐

: Preli. Report

1) 16/10 10:15

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Report Format: TP

Lump Sum / I.D.I. (\$) 8400

Survey Fee:

Transportation

3 + RS, 50

Photos

Others

TOTAL

290

8

290

Nivitha (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Tuesday, 1 October 2019 10:43 AM
To: assignments
Cc: Theresa Vimala D/O Balagangadharan
Subject: RE: TP CASES FARMED OUT TO LKK ON 01/10/2019

Hi Lkk

Here is the OIC, clm ref details. Thank you.

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
T +65 6430 7898
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

From: Theresa Vimala D/O Balagangadharan
Sent: Tuesday, 1 October 2019 10:38 AM
To: assignments <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Subject: FW: TP CASES FARMED OUT TO LKK ON 01/10/2019

Dear LKK

Please assist to survey the following vehicles as per Tse Kiat instruction :-

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	chryllis	MT/1064658-001	1/10/2019	SJH8180A	DYNAMIC AUTOWORK PTE LTD	8 KAKI BUKIT AVENUE 4 #08-09 PREMIER @ KAKI BUKIT	michelle/abby /98564815		PC2779T	30/9	
2	airwan	MT/1063358-002	1/10/2019	GBH8281L	GOLDBELL ENGINEERING PTE LTD	NO 8 KAKI BUKIT AVENUE 4 #05-24 PREMIER @ KAKI BUKIT	soo leong keat /97397127	10:00-12:00	SGC5233M	19/9	
3	cyndie	MT/1064390-002	1/10/2019	SHB8586T	PREMIER AUTOMOTIVE SERVICES PTE LTD	23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443	LIEW / 65446689		SKH9807H	27/9	
4	rajeswary	MT/1064646-001	1/10/2019	SJJ9946R	SK AUTOMOBILE PTE LTD	8 KAKI BUKIT AVENUE 4 #08-45/46 PREMIER@KAKI BUKIT	CHRIS / 67021555		SKR4181J	24/9	
5	jared	MT/1064674-001	1/10/2019	PC1827U	SK AUTOMOBILE PTE LTD	8 KAKI BUKIT AVENUE 4 #08-46 PREMIER@KAKI BUKIT	chris / 67021555		YP2054B	27/9	
6	Helena tan	MT/1064644-001	1/10/2019	SJK9606S	SK AUTOMOBILE PTE LTD	8 KAKI BUKIT AVENUE 4 #08-46 PREMIER@KAKI BUKIT	julie / 96234440		SKX6194X	24/9	
7	charlotte	MT/1064405-001	1/10/2019	SLA5802Y	VISION AUTOWORK PTE. LTD.	KAKI BUKIT AVENUE 4 #08-09 PREMIER @ KAKI BUKIT	abby / 98564815		SJD1575L	27/9	michelle 63416789
8	charlotte	MT/1064678-001	1/10/2019	SLR8808Y	VISION AUTOWORK PTE. LTD.	KAKI BUKIT AVENUE 4 #08-09 PREMIER @ KAKI BUKIT	abby / 98564815		SLX7139U	29/9	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Theresa Vimala
Senior Administrator
Motor Insurance
T +65 6430 7898
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 785D

Vehicle Details

Vehicle No.: SJJ9946R
Vehicle to be Exported: No
Intended Deregistration Date: 28 Sep 2019
Vehicle Make: TOYOTA
Vehicle Model: ALLION 1.5 A
Primary Colour: Black
Manufacturing Year: 2008
Engine No.: 1NZD189773
Chassis No.: NZT2603032689
Maximum Power Output: 81.0 kW (108 bhp)
Open Market Value: \$14,881.00
Original Registration Date: 30 Sep 2008
First Registration Date: 30 Sep 2008
Transfer Count: 2
Actual ARF Paid: \$13,640.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 29 Sep 2023
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$16,170.00
COE Rebate Amount: \$12,944.00
Total Rebate Amount: \$12,944.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 28 Sep 2019

Depn: \$6500/yearly \$541/monthly

4 years 5 days (48.1)

$48.1 \times \$541 = \26022

OK

~~27888~~
~~- 2176~~

~~25711~~
~~12944~~

~~12767~~

~~\$~~



**Toyota Allion 1.5A
(COE till 01/2024)**

\$27,888 \$6,530 /yr 06-Jan-2009 1,496 cc 106,000 km Sedan **Available**

High Loan Available! We Provide Various Loan Scheme Cater To All Individuals Needs, Mileage Only 10k Km Clocked Yearly, New Road T...

Creative Auto

Posted: 22-Sep-2019 Tags: 2009 Toyota Allion, 2009 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota



**Toyota Allion 1.5A
(COE till 02/2024)**

\$31,200 \$7,160 /yr 05-Feb-2009 1,496 cc - Sedan **Available**

Excellent And Original Condition, Well Maintained Interior And Exterior, Call Now For Viewing.

DIRECT OWNER

Posted: 20-Sep-2019 Tags: 2009 Toyota Allion, 2009 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota



**Toyota Allion 1.5A
(COE till 02/2024)**

\$29,800 \$6,730 /yr 13-Mar-2009 1,496 cc 125,000 km Sedan **Available**

New Road Tax. No Gimmicks. 100% Loan Available. Providing Good Services. Free 6 Months Warranty. New Mounting, New Brake Pads,...

Posted: 25-Sep-2019 Tags: 2009 Toyota Allion, 2009 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota



**Toyota Allion 1.5A
(COE till 03/2029)**

\$42,800 \$4,510 /yr 26-Mar-2009 1,496 cc - Sedan **Available**

Consignment Code: A085. Loan Packages Available To Choose From. High Trade In Value For Your Car! No Hidden Cost. For Further Inf...

PREMIUM AD

Posted: 02-Aug-2019 Tags: 2009 Toyota Allion, 2009 toyota allion, Toyota Allion, toyota allion, Toyota, Allion, allion, Used Toyota



Toyota launches fully redesigned Premio and Allion

TOYOTA MOTOR CORPORATION (TMC) announced that the nationwide launch in Japan of the completely redesigned Premio through "Toyopet" dealers, and completely redesigned Allion through "Toyota" dealers

[Read this article](#)



Kurul

MVA319126615 / VAC - Kaki Bukit
ENTRY DATE & TIME: 24/09/2019 16:38
SUBMITTED BY: SITI FADHLON BTE ABUL KADER

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 24/09/2019 16:38
Date Of Accident 24/09/2019 08:25
Exact Location Of Accident SIMS WAY
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJJ9946R

Insured/Policyholder

Name Of Registered Owner THIRUGNANAM KATHIRAVAN
NRIC No S6881785D
Email Address KATHIRYOGES@HOTMAIL.COM
Mobile Phone No (LOCAL) +65-96231437
Alternative Phone No OTHERS-96231437

Vehicle Particulars

Manufacturer TOYOTA
Model ALLION 1.5 A

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5104584086
Cover Note Number

Driver

Name of Driver THIRUGNANAM KATHIRAVAN
NRIC No S6881785D
Date Of Birth 25/04/1968
Occupation INDOOR
Date Of Driving Pass 11/05/2001
Driving Experience 18 YEARS AND 4 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-96231437
Fax Number
Contact Number OTHERS-96231437
Email Address KATHIRYOGES@HOTMAIL.COM

Address BLK 186 #06-175 BUKIT BATOK WEST AVENUE 6
 Postcode 650186
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

THE INCIDENT TOOK PLACE ON THE ABOVEMENTIONED LOCATION. TRAFFIC IS HEAVY AT THAT TIME. WHILE IN THE MIDST OF TRAVELLING ON MY LANE. VEHICLE B MAKE A LANE CHANGE DUE TO THERE IS ANOTHER VEHICLE INFRONT OF HIM AND THUS COLLIDED ONTO MY VEHICLE RIGHT HAND SIDE. AFTER THE IMPACT MY VEHICLE MOVE FORWARD TO ANOTHER LANE. WHICH RESULTED MY VEHICLE TO SUSTAIN DAMAGED.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKR4181J
 Vehicle Make/Model/Colour TOYOTA / WISH 1.8X A
 Details Of Properties
 Vehicle Category PRIVATE HIRE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Accident Sketch Plan


SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

24 SEP 2019


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)

Reporting Officer's Signature
Name: Singapore 415933
M/Tel: 67416697 Fax: 67492305
Email: yackb@singnet.com.sg

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

R.P.
 e. H.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time

Driver's Signature
 (If driver is not the policyholder)
 Date & Time

25 SEP 2019

IDAC KAKI BUKIT (VAC)
 23 Kaki Bukit Ave 4

Reporting Centre Phone No: 67416697
 Name: [Signature]
 Tel: 67416697 Fax: 67492305
 Email: yackb@singnet.com.sg

SK Automobile Pte Ltd
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO	: NTUC	DATE	: 30-Sep-19
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SJJ9946R
ADDRESS	:	MODEL	: TOYOTA ALIION
TEL. NO.	:	CHASSIS NO	:
OWNER'S INSURANCE	:		
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>	DATE :	<i>Xiongskauto@gmail.com</i>	
	TIME :		
THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER	1	\$1,021.00	\$ 1,021.00
2	FRONT BUMPER SIDE RETAINER	1	\$45.50	\$ 45.50
3	HEADLAMP	1	\$684.00	\$ 684.00
4	FRONT FENDER	1	\$412.20	\$ 412.20
5	FRONT FENDER INNER COWLING	1	\$121.30	\$ 121.30
6	FRONT DOOR VIEW MIRROR LH	1	\$329.60	\$ 329.60
7	FRONT DOOR PILLAR	1	\$796.40	\$ 796.40
8	FRONT DOOR	1	\$1,154.00	\$ 1,154.00
9	FRONT DOOR HINGE (UPPER)	1	\$120.00	\$ 120.00
10	FRONT DOOR HINGE (LOWER)	1	\$120.00	\$ 120.00
11	FRONT DOOR INNER LOCK	1	\$384.00	\$ 384.00
12	FRONT DOOR INNER TRIM	1	\$654.00	\$ 654.00
13	FRONT DOOR LOCK CATCHER	1	\$41.20	\$ 41.20
14	FRONT DOOR WEATHER STRIP	1	\$214.00	\$ 214.00
15	FRONT DOOR OUTER STRIP	1	\$142.40	\$ 142.40
16	FRONT DOOR OUTER HANDLE	1	\$212.60	\$ 212.60
17	CENTER PILLAR (OUTER)	1	\$796.30	\$ 796.30
18	CENTER PILLAR INNER TRIM	1	\$548.00	\$ 548.00

\$2855.1
\$2684.1
171

19	ROCKER PANEL (OUTER)	1	\$699.00	\$ 699.00
20	FRONT WHEEL HUP	1	\$394.60	\$ 394.60
21	FRONT KNUCKLE ARM	1	\$376.90	\$ 376.90
22	FRONT LOWER ARM	1	\$394.80	\$ 394.80
23	FRONT KNUCKLE ARM BEARING	1	\$179.80	\$ 179.80
24	FRONT STABILIZER BAR	1	\$568.70	\$ 568.70
25	FRONT STABILIZER BAR LINKAGE	1	\$149.90	\$ 149.90
26	FRONT DRIVESHAFT	1	\$946.70	\$ 946.70
27	FRONT SHOCK ABSORBER	1	\$429.90	\$ 429.90
28	FRONT STEERING RACK AND PINION	1	\$2,698.40	\$ 2,698.40
29	REAR DOOR	1	\$1,245.00	\$ 1,245.00
30	REAR DOOR LOCK CHECKER	1	\$41.20	\$ 41.20
31	REAR DOOR HINGE (UPPER)	1	\$125.00	\$ 125.00
32	REAR DOOR HINGE (LOWER)	1	\$120.00	\$ 120.00
33	REAR DOOR INNER LOCK	1	\$354.00	\$ 354.00
34	REAR DOOR LOCK CATCHER	1	\$39.00	\$ 39.00
35	TAIL LAMP	1	\$589.00	\$ 589.00
36	REAR FENDER	1	\$865.00	\$ 865.00
37	REAR FENDER INNER COWLING	1	\$58.00	\$ 58.00
38	REAR WINDSCREEN MOULDING	1	\$187.30	\$ 187.30
39	REAR BUMPER	1	\$845.00	\$ 845.00
40	REAR BUMPER SIDE RETAINER	1	\$49.70	\$ 49.70
41	REAR AXLE	1	\$1,496.70	\$ 1,496.70
42	REAR WHEEL HUP	1	\$464.70	\$ 464.70
43	REAR WHEEL HUP BEARING	1	\$198.20	\$ 198.20
44	REAR SHOCK ABSORBER	1	\$397.40	\$ 397.40

TOTAL PRICE \$ 21,710.40
LESS 25% \$ 5,427.60
SUB TOTAL PRICE \$ 16,282.80

	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIPS	10	\$ 6.50	\$ 65.00
2	FRONT FENDER SEALANT	1	\$ 80.00	\$ 80.00
3	FRONT FENDER COWLING CLIP	18	\$ 6.50	\$ 117.00
4	FRONT DOOR SEALANT	1	\$ 80.00	\$ 80.00
5	FRONT DOOR FRAME STEP GARNISH CLIP	12	\$ 6.50	\$ 78.00
6	FRONT DOOR INNER TRIM CLIP	18	\$ 6.50	\$ 117.00
7	FRONT WHEEL TYRE	1	\$ 350.00	\$ 350.00
8	FRONT WHEEL RIM	1	\$ 800.00	\$ 800.00
9	CENTER PILLAR INNER TRIM CLIP	14	\$ 6.50	\$ 91.00
10	ROCKER PANEL SEALANT LH (OUTER)	1	\$ 6.50	\$ 6.50

436.5

11	REAR DOOR SEALANT	1	\$ 80.00	\$ 80.00	xnn
12	REAR DOOR FRAME STEP GARNISH CLIP LH	6	\$ 6.50	\$ 39.00	xnn
13	REAR DOOR INNER TRIM CLIP LH	14	\$ 6.50	\$ 91.00	xnn
14	REAR FENDER SEALANT LH	1	\$ 80.00	\$ 80.00	rec
15	REAR FENDER COWLING CLIP LH	10	\$ 6.50	\$ 65.00	rec
16	REAR WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	rec 850
17	REAR WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00	rec 840
18	REAR WHEEL TYRE RH	1	\$ 450.00	\$ 450.00	xnn
19	REAR WHEEL RIM RH	1	\$ 800.00	\$ 800.00	scr 8250
20	WHEEL CAP (SET)	1	\$ 120.00	\$ 120.00	xnn
21	TAIL LAMP CLIP LH	1	\$ 12.50	\$ 12.50	rec xnn
22	REAR BUMPER CLIP	10	\$ 6.50	\$ 65.00	rec 830
23	POWER STEERING OIL	1	\$ 180.00	\$ 180.00	xnn
24	BRAKE OIL	1	\$ 30.00	\$ 30.00	xnn
TOTAL			\$ 3,937.00	\$ 4,511.50	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$1,800.00	\$1150	
2	SPRAY PAINTING TO AFFECTED AREA	\$200 \$1,800.00	\$1200	
3	TUFF COAT	90 x \$30 \$250.00	\$120	
4	WIRING CHECK	\$20 \$80.00	\$20	
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	70 x \$20 \$650.00	\$150	
6	REFOCUS HEADLAMP BEAM	xnn \$80.00		
7	REMOVE AND REFIX FRONT UNDERCARRIAGE	? \$550.00	\$200	
8	TO PRESS FRONT WHEEL BEARING	? \$80.00		
9	TRANSFER FRONT DOOR MECHANISM	30 x \$30 \$100.00	\$60	
10	REMOVE & REINSTALL FRONT WINDOW GLASS x2	\$50 \$80.00	\$50	

Labour;

11	REMOVE AND REFIX REAR UNDERCARRIAGE	X ? \$550.00		
12	TO PRESS REAR WHEEL BEARING	? \$80.00	\$30	
13	FOUR WHEEL ALIGNMENT	\$80 \$120.00	\$80	
14	TRANSFER REAR DOOR MECHANISM	30 X \$30 \$100.00	\$60	
15	REMOVE & REINSTALL REAR WINDOW GLASS	X \$50 Xnn \$100.00		
16	REMOVE AND REFIX REAR WINDSCREEN	\$80 \$120.00	\$80	
17	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	50 Xnn \$80.00	\$50	
18	CONDUCT WATER LEAKAGE TEST	X Xnn \$120.00		
19	RESET ABS LIGHT	X Xnn \$350.00		

TOTAL

\$

7,090.00

Labour: \$338

ESTIMATE REPORT

TOTAL PARTS COST : \$ 20,219.80
TOTAL LABOUR COST : \$ 7,090.00
TOTAL REPAIR COST : \$ 27,309.80

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAY: :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ram (LKK)
Repair days (14) All 6 days
88622778
L/S
Rasuran@lkkautocam
2/10/19 1600hrs

List item: \$6316.65

Net item: \$1951.50

labour: \$3250

Total: \$10518.15

att 20% L/S: \$8400.00

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19017292/Fqf3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 22-10-2019



ATTN: RAJESWARY

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKR 4181J	Veh. Inspected	SJJ 9946R
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1064646-001	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	01/10/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALLION 1.5 A	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	NZT2603032689	Colour	BLUE
Odometer	202000 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45 R17	NEXEN	4 mm
L/H Front Tyre	215/45 R17	NEXEN	4 mm
R/H Rear Tyre	215/45 R17	NEXEN	4 mm
L/H Rear Tyre	215/45 R17	NEXEN	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY, FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	24/09/2019	Inspect Date / Time	02/10/2019 (03:40 PM)
Survey held at	8 KAKI BUKIT AVE 4 #08-46		
Repairer	SK AUTOMOBILE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJJ 9946R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	SHORT CIRCUIT	1,021.00	850.00
1	FRONT BUMPER SIDE RETAINER	NECESSARY	45.50	45.50
1	HEADLAMP	NOT NECESSARY	684.00	-
1	FRONT FENDER	DENTED	412.20	412.20
1	FRONT FENDER INNER COWLING	DISTORTED	121.30	80.00
1	FRONT DOOR VIEW MIRROR LH	NOT NECESSARY	329.60	-
1	FRONT DOOR PILLAR	NOT NECESSARY	796.40	-
1	FRONT DOOR	DENTED	1,154.00	1,154.00
1	FRONT DOOR HINGE (UPPER)	NOT NECESSARY	120.00	-
1	FRONT DOOR HINGE (LOWER)	NOT NECESSARY	120.00	-
1	FRONT DOOR INNER LOCK	NOT NECESSARY	384.00	-
1	FRONT DOOR INNER TRIM	NOT NECESSARY	654.00	-
1	FRONT DOOR LOCK CATCHER	NOT NECESSARY	41.20	-
1	FRONT DOOR WEATHER STRIP	NOT NECESSARY	214.00	-
1	FRONT DOOR OUTER STRIP	NECESSARY	142.40	142.40
1	FRONT DOOR OUTER HANDLE	TO REPAIR SEE LABOUR	212.60	-
1	CENTER PILLAR (OUTER)	NOT NECESSARY	796.30	-
1	CENTER PILLAR INNER TRIM	NOT NECESSARY	548.00	-
1	ROCKER PANEL (OUTER)	BENT	699.00	280.00
1	FRONT WHEEL HUP	NOT NECESSARY	394.60	-
1	FRONT KNUCKLE ARM	NOT NECESSARY	376.90	-
1	FRONT LOWER ARM	NOT NECESSARY	394.80	-
1	FRONT KNUCKLE ARM BEARING	NECESSARY	179.80	128.00
1	FRONT STABILIZER BAR	NOT NECESSARY	568.70	-
1	FRONT STABILIZER BAR LINKAGE	BROKEN	149.90	149.90
1	FRONT DRIVESHAFT	BROKEN	946.70	600.00
1	FRONT SHOCK ABSORBER	NOT NECESSARY	429.90	-
1	FRONT STEERING RACK AND PINION	NOT NECESSARY	2,698.40	-
1	REAR DOOR	DENTED	1,245.00	1,245.00
1	REAR DOOR LOCK CHECKER	NOT NECESSARY	41.20	-

Report Ref No. CS/INC19017292/Fqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR DOOR HINGE (UPPER)	NOT NECESSARY	125.00	-
1	REAR DOOR HINGE (LOWER)	NOT NECESSARY	120.00	-
1	REAR DOOR INNER LOCK	NOT NECESSARY	354.00	-
1	REAR DOOR LOCK CATCHER	NOT NECESSARY	39.00	-
1	TAIL LAMP	SCRATCHED	589.00	589.00
1	REAR FENDER	DENTED	865.00	865.00
1	REAR FENDER INNER COWLING	NOT NECESSARY	58.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	187.30	187.30
1	REAR BUMPER	CRACKED	845.00	845.00
1	REAR BUMPER SIDE RETAINER	NECESSARY	49.70	49.70
1	REAR AXLE	NOT NECESSARY	1,496.70	-
1	REAR WHEEL HUP	DENTED	464.70	350.00
1	REAR WHEEL HUP BEARING	NECESSARY	198.20	198.20
1	REAR SHOCK ABSORBER	BENT	397.40	251.00
	LESS 25% DISCOUNT		-5,427.60	-2,105.55
			16,282.80	6,316.65
	SPECIAL NETT ITEMS			
10	FRONT BUMPER CLIPS @\$6.50 (SN)	NECESSARY	65.00	50.00
1	FRONT FENDER SEALANT (SN)	NECESSARY	80.00	80.00
18	FRONT FENDER COWLING CLIP @\$6.50 (SN)	NECESSARY	117.00	50.00
1	FRONT DOOR SEALANT (SN)	NOT NECESSARY	80.00	-
12	FRONT DOOR FRAME STEP GARNISH CLIP @\$6.50 (SN)	NOT NECESSARY	78.00	-
18	FRONT DOOR INNER TRIM CLIP @\$6.50 (SN)	NOT NECESSARY	117.00	-
1	FRONT WHEEL TYRE (SN)	NOT NECESSARY	350.00	-
1	FRONT WHEEL RIM (SN)	SCRATCHED	800.00	250.00
14	CENTER PILLAR INNER TRIM CLIP @\$6.50 (SN)	NOT NECESSARY	91.00	-
1	ROCKER PANEL SEALANT LH (OUTER) (SN)	NECESSARY	6.50	6.50
1	REAR DOOR SEALANT (SN)	NOT NECESSARY	80.00	-
6	REAR DOOR FRAME STEP GARNISH CLIP LH @\$6.50 (SN)	NOT NECESSARY	39.00	-
14	REAR DOOR INNER TRIM CLIP LH @\$6.50 (SN)	NOT NECESSARY	91.00	-
1	REAR FENDER SEALANT LH (SN)	NECESSARY	80.00	80.00
10	REAR FENDER COWLING CLIP LH @\$6.50 (SN)	NECESSARY	65.00	65.00

Report Ref No. CS/INC19017292/Fqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	60.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR WHEEL TYRE RH (SN)	NOT NECESSARY	450.00	-
1	REAR WHEEL RIM RH (SN)	SCRATCHED	800.00	250.00
1	SET WHEEL CAP (SN)	NOT NECESSARY	120.00	-
1	TAIL LAMP CLIP LH (SN)	NOT NECESSARY	12.50	-
10	REAR BUMPER CLIP @\$6.50 (SN)	NECESSARY	65.00	30.00
1	POWER STEERING OIL (SN)	NOT NECESSARY	180.00	-
1	BRAKE OIL (SN)	NOT NECESSARY	30.00	-
			3,937.00	951.50
	LABOUR			
	PANEL BEATING, REMOVING AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF FRONT DOOR OUTER HANDLE.		1,800.00	1,150.00
	SPRAY PAINTING TO AFFECTED AREA.		1,800.00	1,200.00
	TUFF COAT.		250.00	120.00
	WIRING CHECK. }		80.00	20.00
	REFOCUS HEADLAMP BEAM. }		80.00	-
	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR.		650.00	150.00
	REMOVE AND REFIX FRONT UNDERCARRIAGE.		550.00	200.00
	TO PRESS FRONT WHEEL BEARING.	NOT NECESSARY	80.00	-
	TRANSFER FRONT DOOR MECHANISM.		100.00	60.00
	REMOVE & REINSTALL FRONT WINDOW GLASS X2.		80.00	50.00
	REMOVE AND REFIX REAR UNDERCARRIAGE.	NOT NECESSARY	550.00	-
	TO PRESS REAR WHEEL BEARING.		80.00	30.00
	FOUR WHEEL ALIGNMENT.		120.00	80.00
	TRANSFER REAR DOOR MECHANISM.		100.00	60.00
	REMOVE & REINSTALL REAR WINDOW GLASS.	NOT NECESSARY	100.00	-
	REMOVE AND REFIX REAR WINDSCREEN.		120.00	80.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	50.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	120.00	-

Report Ref No. CS/INC19017292/Fqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	RESET ABS LIGHT.	NOT NECESSARY	350.00	-
			7,090.00	3,250.00
	GRAND TOTAL		27,309.80	10,518.15
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				8,400.00

Report Ref No. CS/INC19017292/Fqf3e2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.