

HIN LUNG WORKSHOP

Blk 1008 Bukit Merah Lane 3 #01-20, S'pore 159722. Tel: 68583000 Fax: 64760075
Website: www.hinlung.com.sg GST Regn. No: M2-0065859-X

Your Ref:
Our Ref : 0672/09/19
M/s : INDIA INTERNATIONAL INSURANCE P.LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711
Attn : MOTOR CLAIM DEPARTMENT

Page: 1
Date: 30/09/2019

Dear Sir/Madam,

ACCIDENT REPAIR ON : SLG5160J - 316I 0
INSURED : ZHANG YUYANYAN
DATE OF ACCIDENT : 26/09/2019
YOUR INSURED VEH NO: SHA4822T

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

		S\$	S\$	S\$
REPLACEMENT OF PARTS				
1 FRONT BUMPER <i>scr</i>	1 @	1,040.00	1,040.00	
2 BOTH FRONT GRILLE <i>RH-scr/LH-?</i>	1 @	128.00	128.00	
3 FRONT BUMPER LOWER LIPS <i>scr</i>	1 @	98.00	98.00	
4 BUMPER CLIPS <i>scr</i>	10 @	3.50	35.00	
5 FRONT NUMBER PLATE GARNISH <i>?</i>	1 @	70.00	70.00	
6 REINFORCEMENT <i>?</i>	1 @	378.00	378.00	
7 SPONGE <i>?</i>	1 @	45.00	45.00	
SUB-TOTAL				1,794.00
*SPECIAL NETT				
8 FRONT NUMBER PLATE WITH CASING <i>scr</i>	1 @	35.00	35.00	

LABOUR CHARGES

- 1 REMOVE, REPAIR AND REPLACE PARTS FOR THE EFFECTED AREAS.
- 1
- 2 SPRAY PAINT ON THE EFFECTED AREAS WITH 2K PAINT.
- 2
- 3 CHECK WIRING AND PROPER FUNCTIONING

Nett Total Before GST

Rasul 900.00 *250*
Hp 90010068 300.00 *250*
3 days 80.00 *X*
4/8 3,109.00

Yours faithfully,


(Workshop Manager)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

02/10/19 @ 1400hrs
Resurvey after repair