

ASS. REC. BY:

REF:


TP / CS / TP19017311 / kyf307

Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 QD / TP / WS / TP RES / QD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Hui Yang
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SMH 4657H Regn: 01, 19
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Traller or Wagon
 Make: Toy Noah c.c. 1797
 Colour: M. Black A/C: Insured / Std / NI / NA
 Sp. Reading: 55137 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: ZWR80 . 0354748
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modl: Nil / S/R/m / STD A/R/m or
 Tyre Size: F: 195/65R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front R/Bal. 6 mm Rear R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 28/9/11 D.O.I. 1/10/19
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 06 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
/	File pass to SMH 4657H - X
	GZ 9216 R - N/S / INC 13000237 / High
	MOA 28/12/2012
1/10	PIP \$8940-91 Confirm 6 day by Marc (Red \$4849-33, 35%)

RECEIVED 08 OCT 2019

Date/Time, File Pass to? : Prell. Report
 : Final Report

1) _____
 2) 7/10/19 Typist

Report Format: _____
 Lump Sum / I.B.I: (\$) PIP = \$8940-91

Days Of Repair: 6
 Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$) : Interview (\$) : Tech Invs (\$) : Weekend (\$)

Survey Fee: 3x15=45

Transportation:	<u>49+170</u>
S - RS - SI	<u>50</u>
Fuel	<u>50</u>
Others	<u>36</u>
	<u>80</u>
TOTAL	<u>431</u>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/09/2019 16:04
Date Of Accident	28/09/2019 18:20
Exact Location Of Accident	TAMPINES AVE 10 TWDS BARTLEY RD EAST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMH4657H
Insured/Policyholder	
Name Of Registered Owner	VFM PTE. LTD.
Co Reg No	201523773K
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-87181515
Alternative Phone No	OFFICE-62913113

Vehicle Particulars

Manufacturer	TOYOTA
Model	NOAH
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5076629069-03 (DRIVO CLASSIC)
Cover Note Number	

Driver

Name of Driver	KHOO SIONG HUI
NRIC No	S7023046A
Date Of Birth	17/07/1970
Occupation	OUTDOOR
Date Of Driving Pass	18/11/1988
Driving Experience	30 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87181515
Fax Number	
Contact Number	OTHERS-87181515
EEmail Address	NOEMAIL

Address	15 TUA KONG TERRACE
Postcode	455042
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	7
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 3	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 4	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 5	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 6	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES

Remarks/ Reasons: UNABLE TO UPLOAD
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBC247R
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number GZ9216R
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 28/09/2019 @ about 18:20hrs, I vehicle A SMH 265711 was travelling along Tompkins Ave to take Bartley Rd east to drop off my passengers. while waiting @ the cross junction of Tompkins Ave to Ave 5 & Tompkins and Ave 3 for the traffic light to turn green.

Suddenly, I felt a very huge impact from the rear & look into the rear view mirror then realise that vehicle B GBC 247R had collided onto my vehicle.

After I get off from vehicle to check on the damage then to realise that vehicle C GZ 926R had hit into vehicle B which lead to a chain collision.

DECLARATION


I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

30 SEP 2019



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

*To Rio mare
Veh In
(L11C) -*

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST & Reg No. 201629438M

*Not Authorized
L11m 87
Resurvey the Paint
6 days*

28/09/2019

Owner: VFM PTE LTD

ESTIMATE TO REPAIR TOYOTA NOAH 1.8X - SMH4657H

1pc	rear tailgate	<i>B1</i>	\$ 1,712.85	✓
1pc	rear tailgate "HYBRID" emblem	<i>M</i>	\$ 85.25	✓
1pc	rear tailgate windscreen moulding	<i>M</i>	\$ 181.50	✓
1pc	rear tailgate outer chrome		\$ 781.50	?
1pc	rear tailgate inner lock	<i>M</i>	\$ 561.25	✓
1pc	rear tailgate inner rubber	<i>DIY M</i>	\$ 371.85	✓
1pc	rear tailgate inner garnish	<i>Bu</i>	\$ 781.90	✓
1pc	rear bumper	<i>Bu</i>	\$ 1,217.45	✓
1pc	rear bumper RH side retainer 1	<i>DIY</i>	\$ 171.45	✓
1pc	rear bumper RH side retainer 2	<i>DIY</i>	\$ 182.10	✓
1pc	rear bumper RH side reflector	<i>S</i>	\$ 171.10	X
2pcs	rear taillamp @\$781.55	<i>old M</i>	\$ 1,563.10	✓
2pcs	rear taillamp lower garnish @\$371.85		\$ 743.70	?
2pcs	rear taillamp lower garnish side retainer @\$172.25		\$ 344.50	?
1pc	rear end panel	<i>B1</i>	\$ 781.10	✓
1pc	rear end panel inner garnish	<i>M</i>	\$ 378.85	✓
1pc	rear end panel sensor	<i>Shan</i>	\$ 381.50	✓
1pc	rear float panel LH side trim		\$ 581.50	?
1pc	rear float panel RH side trim		\$ 581.00	?
2pcs	rear fender inner trim @\$681.10		\$ 1,362.20	?
			\$ 12,935.65	
	less 25%		\$ 3,233.91	
			\$ 9,701.74	
1set	rear parking sensor	<i>Shan</i>	\$ 280.00	<i>2000</i>
	remove & refit rear windscreen glass		\$ 120.00	✓
	wiring		\$ 80.00	<i>201</i>
	tuffkote		\$ 80.00	<i>601</i>
	spray painting		\$ 1,400.00	<i>9001</i>
	labour charges		\$ 1,200.00	<i>7001</i>
	Total		\$ 12,861.74	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



辉陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST & Reg No. 201629438M

To Rio man
Veh In
(LICK)

28/09/2019

Owner: VFM PTE LTD

Not authorized
HSA 813.1
Respray the Paint
6 days

ESTIMATE TO REPAIR TOYOTA NOAH 1.8X - SMH4657H

1pc	rear tailgate	B1	\$ 1,712.85	✓
1pc	rear tailgate "HYBRID" emblem	M	\$ 85.25	✓
1pc	rear tailgate windscreen moulding	M	\$ 181.50	✓
*1pc	rear tailgate outer chrome	Myc M	\$ 781.50	✓
1pc	rear tailgate inner lock	RU	\$ 561.25	✓
1pc	rear tailgate inner rubber	DIT MRS	\$ 371.85	✓
1pc	rear tailgate inner garnish	Bu	\$ 781.90	✓
1pc	rear bumper	Bu	\$ 1,217.45	✓
1pc	rear bumper RH side retainer 1	Sm DIT	\$ 171.45	X
1pc	rear bumper RH side retainer 2	Sm DIT	\$ 182.10	X
1pc	rear bumper RH side reflector	Sm	\$ 171.10	X
2pcs	rear taillamp @\$781.55	old W	\$ 1,563.10	✓
2pcs	rear taillamp lower garnish @\$371.85	Sm	\$ 743.70	X
2pcs	rear taillamp lower garnish side retainer @\$172.25	Sm	\$ 344.50	X
1pc	rear end panel	B1	\$ 781.10	✓
1pc	rear end panel inner garnish	RU	\$ 378.85	✓
1pc	rear end panel sensor	Shan	\$ 381.50	✓
1pc	rear float panel LH side trim	Sm	\$ 581.50	X
1pc	rear float panel RH side trim	Sm	\$ 581.00	X
2pcs	rear fender inner trim @\$681.10	Sm	\$ 1,362.20	X

less 25%

\$ 12,935.65

\$ 3,233.91

\$ 9,701.74

1set rear parking sensor

Shan s.nett \$ 280.00 2015

remove & refit rear windscreen glass
wiring
tuffkote
spray painting
labour charges
Total



\$ 120.00 ✓

\$ 80.00 201

\$ 80.00 601

\$ 1,400.00 9001

\$ 1,200.00 7001

\$ 12,861.74

13700.24

輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

28/09/2019

Owner: VFM PTE LTD

SUPPLEMENTRY TO REPAIR TOYOTA NOAH 1.8X - SMH4657H

1pc rear floor panel top board tirm

Return \$ 1,238.00 ✓

less 25%

\$ 1,238.00

\$ 309.50

\$ 928.50





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HUI YANG MOTOR PTE LTD		Ref : CS/TP19017311/Kyf3e2	
BLK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721		Date : 11-10-2019	
ON BEHALF OF VFM PTE. LTD.		Code : TP034	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.		Veh. Inspected	SMH 4657H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	01/10/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA NOAH (A)	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	ZWR800354748	Colour	METALLIC BLACK
Odometer	55137	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	28/09/2019	Inspection Date	01/10/2019
Survey held at	HUI YANG MOTOR PTE LTD BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 4657H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAILGATE	BENT	1,712.85	1,712.85
1	REAR TAILGATE "HYBRID" EMBLEM	NECESSARY	85.25	85.25
1	REAR TAILGATE WINDSCREEN MOULDING	NECESSARY	181.50	181.50
1	REAR TAILGATE OUTER CHROME	MTG CRACKED	781.50	781.50
1	REAR TAILGATE INNER LOCK	DENTED	561.25	561.25
1	REAR TAILGATE INNER RUBBER	DISTORTED / DENTED	371.85	371.85
1	REAR TAILGATE INNER GARNISH	BUCKLED	781.90	781.90
1	REAR BUMPER	BUCKLED	1,217.45	1,217.45
1	REAR BUMPER RH SIDE RETAINER 1	SERVICEABLE	171.45	-
1	REAR BUMPER RH SIDE RETAINER 2	SERVICEABLE	182.10	-
1	REAR BUMPER RH SIDE REFLECTOR	SERVICEABLE	171.10	-
2	REAR TAILLAMP @\$781.55	O/S CUT	1,563.10	781.55
2	REAR TAILLAMP LOWER GARNISH @\$371.85	SERVICEABLE	743.70	-
2	REAR TAILLAMP LOWER GARNISH SIDE RETAINER @\$172.25	SERVICEABLE	344.50	-
1	REAR END PANEL	BENT	781.10	781.10
1	REAR END PANEL INNER GARNISH	DENTED	378.85	378.85
1	REAR END PANEL SENSOR	SHORTED	381.50	381.50
1	REAR FLOOR PANEL LH SIDE TRIM	SERVICEABLE	581.50	-
1	REAR FLOOR PANEL RH SIDE TRIM	SERVICEABLE	581.00	-
2	REAR FENDER INNER TRIM @\$681.10	SERVICEABLE	1,362.20	-
1	REAR FLOOR PANEL TOP BOARD TRIM (ADDITIONAL)	DEFORMED	1,238.00	1,238.00
	LESS 25% DISCOUNT		-3,543.41	-2,313.64
			10,630.24	6,940.91
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR PARKING SENSOR (SN)	SHORTED	280.00	200.00
			280.00	200.00
<u>LABOUR</u>				
	REMOVE & REFIT REAR WINDSCREEN GLASS.		120.00	120.00
	WIRING.		80.00	20.00
	TUFFKOTE.		80.00	60.00
	SPRAY PAINTING.		1,400.00	900.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR CHARGES.		1,200.00	700.00
			2,880.00	1,800.00
GRAND TOTAL			13,790.24	8,940.91
RECOMMENDED COST OF REPAIRS				8,940.91

Report Ref No. CS/TP19017311/Kyf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.