

ASS. REC. BY:

REF:

1M1/CC3/TM1 1904312/K1J-f3n2


photo ok

Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Trans Cob
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: S110 417R Yr Regn: 03/16
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Renault Latitude cc 1995
 Colour M-White/Red A/C: Insured / Std / NI / NA
 Sp. Reading 454290 T/Radio: Insured / Std / NI / NA
 Eng No: _____
 C/No: V1-1ABL15AUC 28 2733
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: M / S/Rim / STD A/Rim or
 Tyre Size: F: 215/60R16
 R: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Pailun
 Front R/Bal. 9 mm
 L/Bal. 9 mm
 D.O.A. 27/9/19
 Rear R/Bal. 9 mm
 L/Bal. 9 mm
 D.O.I. 1/10/19

Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 02 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
Rear d/s
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
1	File pass to
	1/1 Sep @ 1650 (Red \$31888.52, 95%)
	S110 417R - CC3/TM1 1904312/K1J-f3n2 DOA - 14/10/2019
	SLL 43215 - X
7/10/19	Sent E-Mail to Preli

RECEIVED 20 OCT 2019

Date/Time, File Pass to? : Prel. Report
 : Final Report

1) _____
 2) 22/10/19 Typist

Days Of Repair: 2
 Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech Invs (\$ _____)
 : Weekend (\$ _____)

Survey Fee:	
Transportation:	<u>250</u>
S - R.S. St	<u>11</u>
Others	
TOTAL	<u>261</u>

Report Format :
 Lump Sum / D.B.I. (\$ \$1650/=)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref:

Date: 07 Oct 2019

Our Ref: CC3/TMI19017312/Kyf3

The Motor Claims Department
TOKIO MARINE INSURANCE SINGAPORE LTD

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD417R.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 01/10/2019 at the premises of M/s TRANS-CAB AUTO SERVICES PTE LTD. and have the following to report:-

Workshop Estimate Amount	: S\$ <u>33,538.52</u> .
Revised Estimate Amount	: S\$ <u>1,674.41</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the o/s rear.



Yours faithfully

KENNETH KONG SENG CHEONG
Licensed Appraiser

Yvonne Wong (LKK Auto)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Tuesday, October 22, 2019 1:24 PM
To: Yvonne Wong (LKK Auto)
Cc: jasminetan@transcab.com.sg; SUR
Subject: FW: SHD417R DOA: 27/09/2019 -- AAD1909-242
Attachments: SHD417R ESTIMATE.pdf

Dear Yvonne

Amount confirmed \$ 1,650 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**

TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63
Singapore 569111
Tel: 6287 6666 Fax: 6287 7764

From: Yvonne Wong (LKK Auto) [mailto:yvonnewong@lkkauto.com]
Sent: Monday, 21 October, 2019 11:18 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Cc: 'Jasmine Tan' <jasminetan@transcab.com.sg>; SUR <sur@lkkauto.com>
Subject: SHD417R DOA: 27/09/2019

Dear Wai Yin,

WITHOUT PREJUDICE

Lump Sum \$1650 @ 2 working days.

Thank you.

Best Regards,
Yvonne Wong (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Monday, October 07, 2019 5:36 PM
To: 'motorclaims@tokiomarine.com.sg'
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 27/09/2019, SHD 417R (TP VEHICLE), SLL4321S (OI VEHICLE)
Attachments: SHD417R ESTIMATE.pdf; SHD417R GIA.pdf; SHD417R DOA 27092019.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHD 417R at M/s: TRANS-CAB AUTO SERVICES PTE LTD, 2 ANG MO KIO ST 63 SINGAPORE 569111 on 01/10/2019.

Enclosed herewith a copy of TP's GIA report, Preliminary and estimated cost of repair.

Meanwhile, kindly create claim in merimen for our necessary action.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonne.wong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHD417R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	30 Sep 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002948
Chassis No.:	VF1ABL15AUC282733
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	22 Mar 2016
First Registration Date:	22 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Mar 2024
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	
COE Expiry Date:	21 Mar 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$39,633.00
COE Rebate Amount:	\$22,160.00
Total Rebate Amount:	\$37,158.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 30 Sep 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/09/2019 17:05
Date Of Accident	27/09/2019 01:00
Exact Location Of Accident	TPE SLIP ROAD TOWARDS TAMPINES AVENUE 7
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD417R
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 D DCI (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P1680520
Cover Note Number	

Driver

Name of Driver	TAN HONG SIANG
NRIC No	S0463874C
Date Of Birth	09/04/1951
Occupation	OUTDOOR
Date Of Driving Pass	13/11/1968
Driving Experience	50 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81388267
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 297A COMPASSVALE STREET #01-26
Postcode	541297
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 27/09/2019 AT ABOUT 0100HRS, I WAS TRAVELLING STRAIGHT ALONG THE SLIP ROAD OF TPE TOWARDS TAMPINES AVE 7. I SLOWED MY TAXI DOWN AS THERE WERE ON-COMING VEHICLES COMING FROM TAMPINES AVENUE 7. I THEN SUDDENLY FELT AN IMPACT FROM THE REAR OF MY TAXI. VEHICLE B(SLL4321S) HAS FAILED TO STOP IN TIME AND COLLIDED ONTO THE REAR RIGHT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL4321S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Trans-cab Auto Services Pte Ltd

AAD1909-242

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 417R

Not Authorized
U/Smp @ 1650/.

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

4.1 OCT 2019

SHD 417R

VF1ABL15AUC282733

RENAULT

LATITUDE

27.9.19

TOKIO MARINE

22/3/2016

		PART		LIST	
1	1	BUMPER COVER REAR	\$	CM 561.70	✓
2	1	BUMPER LOWER REAR	\$	CM 411.90	✓
3	1	BUMPER BRACKET CTR REAR	\$	SL 98.10	X
4	1	BUMPER BRACKET SIDE RH REAR	\$	SL 82.10	X
5	1	BUMPER RETAINER RH REAR	\$	DI 59.80	✓
6	1	BUMPER REFLECTOR RH	\$	CM 16.60	✓
7	1	BUMPER BRACKET SIDE LH REAR	\$	R 80.80	X
8	1	BUMPER RETAINER LH REAR	\$	SL 54.20	X
9	1	BUMPER REFLECTOR LH	\$	SL 16.60	X
10	1	BUMPER BEAM REAR	\$	AR 547.80	✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	R 114.50	X
12	1	BUMPER BEAM BRACKET RH REAR	\$	R 100.90	X
13	1	OUTER PANEL REAR (End Panel)	\$	R 745.80	} X
14	1	OUTER PANEL REAR (End Panel) TRIM	\$	SL 404.56	
15	1	TAILLAMP RH	\$	SL 313.10	
16	1	TAILLAMP PANEL RH	\$	R 401.40	
17	1	TAILLAMP LH	\$	SL 401.40	
18	1	TAILLAMP PANEL LH	\$	R 401.40	
19	1	BOOT REAR	\$	R 1,677.20	
20	1	BOOT FINISHER	\$	SL 344.70	
21	1	BOOT WHEATERSTRIP	\$	SL 178.20	
22	1	BOOT REFLECTOR LAMP LH	\$	SL 277.70	
23	1	BOOT REFLECTOR LAMP RH	\$	SL 277.70	
24	1	BOOT BADGE 'RENAULT'	\$	RR 82.40	
25	1	BOOT BADGE	\$	RR 95.80	
26	1	BOOT STRUT LH	\$	SL 145.10	
27	1	BOOT STRUT RH	\$	SL 145.10	
28	1	BOOT HINGE LH	\$	R 254.20	
29	1	BOOT HINGE RH	\$	R 253.80	

Trans-cab Auto Services Pte Ltd

AAD1909-242

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 417R

30	1	BOOT INNER TRIM BOARD	\$	Sm	611.00	}
31	1	BOOT SWITCH	\$	Sm	113.00	
32	1	BOOT LOCK	\$	Sm	246.60	
33	1	BOOT LOCK CATCH	\$	Sm	41.70	
34	1	EXHAUST CAP REAR	\$	Sm	125.40	
35	1	EXHAUST REAR	\$	A	5,263.60	
36	1	FENDER PANEL REAR RH	\$	M	1,933.20	
37	1	WHEELARCH REAR RH	\$	Sm	275.40	
38	1	FENDER PANEL INNER TRIM REAR RH	\$	Sm	671.45	X
TOTAL			\$		17,825.91	
10%			\$		1,782.59	
			\$		16,043.32	

Special Nett

1	1SET	PARKING AID	\$	Sm	700.00	X
2	1SET	REAR BUMPER CLIP	\$	na	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	—
4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET	BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET	BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1	BOOT STICKER "Trans-cab"	\$	na	30.00	}
11	1	BOOT STICKER "6555-3333"	\$	na	30.00	
12	1	EXHAUST MOUNTING REAR	\$	Sm	16.00	
13	2	REAR WINDSCREEN SEALANT	\$	na	80.00	
14	1	WINDSCREEN MOULDING	\$	na	100.00	
15	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
16	1	BOOT INNER TRIM CLIP	\$	na	45.00	
17	1SET	BOOT FINISHER CLIP	\$	na	24.20	
18	1	TAILLAMP CLIP LH	\$	na	5.00	
19	1	TAILLAMP CLIP RH	\$	na	5.00	
20	1	Rear Bumper Protector	\$	na	100.00	
21	1SET	FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	
22	1	FENDER INNER TRIM CLIP RH	\$	na	28.00	
23	1	REAR RIGHT TYRE	\$	Sm	300.00	
24	1	REAR RIGHT TYRE RIM	\$	Sm	380.00	X

Trans-cab Auto Services Pte Ltd

AAD1909-242

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 417R

TOTAL	\$	2,225.20
--------------	-----------	-----------------

TOTAL PARTS	\$	18,268.52
--------------------	-----------	------------------

LABOUR

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>~</i> 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>~</i> 380.00	X
To Rust-Proofing Of The Affected Areas.	\$	<i>~</i> 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	<i>10d</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>~</i> 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	<i>6d</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>20d</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>~</i> 170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>~</i> 170.00	X
To check steering geometry and computer wheel alignment	\$	<i>~</i> 220.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>~</i> 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>~</i> 380.00	X
Putty and spray painting of the affected portion.	\$	6,000.00	<i>22d</i>

Trans-cab Auto Services Pte Ltd

AAD1909-242

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 417R

To repair and realign rear exhaust pipe.	\$	<i>na</i> 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>na</i> 170.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	X
TOTAL	\$	15,270.00	
Over All Total	\$	33,538.52	

LUMP SUM (REPAIR DAY)

~~20 DAYS~~

2 days

LKK Auto Consultants hence notify the Customer of the following:

- To ensure no further repair, welding
- To ensure complete repair & satisfactory
- Parts prices are based on market
- Total cost will be based on actual cost
- No work is done without approval
- All work is done in accordance with the relevant laws & regulations of Singapore & Malaysia Company

Acknowledged by customer:

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19017312/KYF3N2

Date: 25/10/2019

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MS002925
Claimant Vehicle No :	SHD417R	Insured Vehicle No :	SLL4321S
Date of Loss:	30/09/2019	Nature of Claim:	TP
		Claim No:	M1907641

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD417R	Engine No:	M9R8839C002948
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Chassis No:	VF1ABL15AUC282733
Reg. Date:	22/03/2016 (Man. Year: 2015)	Odometer:	454290 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 9 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %	
Parts	18,268.52	1,603.02	16,665.50	91.23	
Miscellaneous Items	0.00	0.00	0.00		
Labour	15,270.00	490.00	14,780.00	96.79	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	33,538.52	2,093.02	31,445.50	93.76	
Approved Total (Overridden) (S\$)		1,650.00			
	(S\$)	33,538.52	1,650.00	31,888.52	95.08
+ GST 7.00/7.00% (S\$)	2,347.70	115.50	2,232.20	95.08	
Nett Amount (S\$)	35,886.22	1,765.50	34,120.72	95.08	

INSPECTION

Date of Assignment:	08/10/2019	Inspected At:	Trans-Cab Services Pte Ltd (HQ)
Date Inspected:	01/10/2019		2 Ang Mo Kio Street 63
			Singapore 569111
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 25 Oct 2019)
Parts: 143	RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD417R)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Cracked	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Cracked	411.90 FL	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*-FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*-FL
5	1		*BUMPER RETAINER RH REAR	Distorted	59.80 FL	*59.80 FL
6	1		*BUMPER REFLECTOR RH	Cracked	16.60 FL	*16.60 FL
7	1		*BUMPER BRACKET SIDE LH REAR	Repair	80.80 FL	*-FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*-FL
9	1		*BUMPER REFLECTOR LH	Serviceable	16.60 FL	*-FL
10	1		*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	114.50 FL	*-FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	100.90 FL	*-FL
13	1		*OUTER PANEL REAR (END PANEL)	Repair	745.80 FL	*-FL
14	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	*-FL
15	1		*TAILLAMP RH	Serviceable	313.10 FL	*-FL
16	1		*TAILLAMP PANEL RH	Repair	401.40 FL	*-FL
17	1		*TAILLAMP LH	Serviceable	401.40 FL	*-FL
18	1		*TAILLAMP PANEL LH	Repair	401.40 FL	*-FL
19	1		*BOOT REAR	Repair	1,677.20 FL	*-FL
20	1		*BOOT FINISHER	Serviceable	344.70 FL	*-FL
21	1		*BOOT WEATHERSTRIP	Serviceable	178.20 FL	*-FL
22	1		*BOOT REFLECTOR LAMP LH	Serviceable	277.70 FL	*-FL
23	1		*BOOT REFLECTOR LAMP RH	Serviceable	277.70 FL	*-FL
24	1		*BOOT BADGE RENAULT	Not Necessary	82.40 FL	*-FL
25	1		*BOOT BADGE	Not Necessary	95.80 FL	*-FL
26	1		*BOOT STRUT LH	Serviceable	145.10 FL	*-FL
27	1		*BOOT STRUT RH	Serviceable	145.10 FL	*-FL
28	1		*BOOT HINGE LH	Repair	254.20 FL	*-FL
29	1		*BOOT HINGE RH	Repair	253.80 FL	*-FL
30	1		*BOOT INNER TRIM BOARD	Serviceable	611.00 FL	*-FL
31	1		*BOOT SWITCH	Serviceable	113.00 FL	*-FL
32	1		*BOOT LOCK	Serviceable	246.60 FL	*-FL
33	1		*BOOT LOCK CATCH	Serviceable	41.70 FL	*-FL
34	1		*EXHAUST CAP REAR	Serviceable	125.40 FL	*-FL
35	1		*EXHAUST REAR	Repair	5,263.60 FL	*-FL
36	1		*FENDER PANEL REAR RH	Repair	1,933.20 FL	*-FL
37	1		*WHEELARCH REAR RH	Serviceable	275.40 FL	*-FL
38	1		*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	*-FL
39	1		*SET PARKING AID	Serviceable	700.00 FS	*-FS
40	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
41	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
42	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*-FS
43	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*-FS
44	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*-FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
46	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
47	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
48	1		*BOOT STICKER TRANS-CAB	Not Necessary	30.00 FS	*- FS
49	1		*BOOT STICKER 6555-3333	Not Necessary	30.00 FS	*- FS
50	1		*EXHAUST MOUNTING REAR	Serviceable	16.00 FS	*- FS
51	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
52	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
53	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
54	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
55	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
56	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*- FS
57	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
58	1		*REAR BUMPER PROTECTOR	Not Necessary	100.00 FS	*- FS
59	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
60	1		*FENDER INNER TRIM CLIP RH	Not Necessary	28.00 FS	*- FS
61	1		*REAR RIGHT TYRE	Serviceable	300.00 FS	*- FS
62	1		*REAR RIGHT TYRE RIM	Serviceable	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	20,051.11	1,762.80
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,782.59	159.78
Total Parts (\$\$)	18,268.52	1,603.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR	New	380.00	0.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
5	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
7	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	6,000.00	200.00
8	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO TRANSFER OF REAR BUMPER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
12	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR	New	380.00	0.00
13	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	220.00
14	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
15	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
16	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
Gross Labour Cost (S\$)			15,270.00	490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >