

ASS. REC. BY:

REF: CS/CTI19017319/KSD3

72

Special Instructions:

Surveyor:

Kornelth

ASSIGNMENT (Office)

From (Person):

Chung Boon Sen

of

CTI

Date/Time:

1/10/2019 @ 10:50am

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ805M

Insured:

PC726J

at Workshop m/s

Hui Yang Motor

Tel:

64515752

of

176 Sin Ming Drive # 04-02

Policy No:

Claim No:

SNM19D201576

Sum Insured:

Excess:

Make of Veh:

D.O.A.

30/09/14

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:30am @ 1/10/14

Person Contacted:

Belle

Vehicle IN OUT

Date/Time

Action/Instruction () Estimate

SLQ805M - NA / CTT19017133 / ht

D.A. 30/09/2014

PC726J - NA / CTT19017133 / ht

D.A. 30/09/2014

10/10 C/ Pay @ 6150k email & confirm

(\$ 6,148.66 Red - 50%)

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 1 October 2019 10:50 AM
To: Hui Yang Motor
Cc: assignments
Subject: RE: OUR REF: SNM19D204576-PC7262J-TKL - TP Claim for SLQ805M against PC7262J on 30/09/2019

WITHOUT PREJUDICE

Dear Sir

We will be assigning M/s LKK AUTO CONSULTANTS to survey your client's vehicle.

Aside to LKK AUTO CONSULTANTS,

Please proceed to survey the third party vehicle on WP basis. Please merimen.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Hui Yang Motor [mailto:hui_yang_motor@hotmail.com]
Sent: Tuesday, October 1, 2019 10:45 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: Re: OUR REF: SNM19D204576-PC7262J-TKL - TP Claim for SLQ805M against PC7262J on 30/09/2019
Importance: High

Hi Mr Chong,

Our choice of surveyor is Kenneth Kong from LKK.

Thank you & Regards,
Bel
Tel: 64515752

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, October 1, 2019 10:40 AM

To: hui_yang_motor@hotmail.com <hui_yang_motor@hotmail.com>

Subject: RE: OUR REF: SNM19D204576-PC7262J-TKL - TP CLaim for SLQ805M against PC7262J on 30/09/2019

Without prejudice

Dear

Sir,

LKK

STA

LBS

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Hui Yang Motor [mailto:hui_yang_motor@hotmail.com]

Sent: Tuesday, 1 October, 2019 10:31 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Subject: Re: OUR REF: SNM19D204576-PC7262J-TKL - TP CLaim for SLQ805M against PC7262J on 30/09/2019

Importance: High

Hi,

Just to check with you if the surveyor is coming down today to survey SLQ805M?
Vehicle is in our workshop.

Thank you & Regards,
Sandra

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Sent: Monday, September 30, 2019 4:30 PM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; hui_yang_motor@hotmail.com <hui_yang_motor@hotmail.com>

Subject: OUR REF: SNM19D204576-PC7262J-TKL - TP CLaim for SLQ805M against PC7262J on 30/09/2019

Dear Kah leong,

Please conduct PRS for SLQ805M.

Note : officer in charge – Kah Leong 63896193.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Hui Yang Motor [mailto:hui_yang_motor@hotmail.com]

Sent: Monday, September 30, 2019 1:31 PM

To: Claims Dept of CTI

Subject: TP CLaim for SLQ805M against PC7262J on 30/09/2019

Importance: High

Hi,

Please refer to the attached Estimate & GIA Report and help to arrange surveyor to come down to workshop to survey SLQ805M as soon as possible as the vehicle is already in our workshop.

Thank you & Regards,
Sandra

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST Reg No. 201629438M

CNR 10
Veh In-
(LXX)

30/09/2019

Owner: HYMS CAR LEASING PTE LTD

*Not Washed
11 Days @ 6150k
Purging After Painting
6 days*

ESTIMATE TO REPAIR TOYOTA PRIUS ALPHA 1.8S A - SLQ805M

1pc	rear tailgate	<i>R</i>	\$ 1,218.45	✓
1pc	rear tailgate outer garnish	<i>CM</i>	\$ 371.25	✓
1pc	rear tailgate "TOYOTA" logo	<i>re</i>	\$ 61.10	✓
1pc	rear tailgate "PRIUS" emblem	<i>re</i>	\$ 63.90	✓
1pc	rear tailgate "HYBRID" emblem	<i>re</i>	\$ 61.10	✓
1set	rear tailgate windscreen glass moulding	<i>re</i>	\$ 182.28	✓
1pc	rear tailgate inner lock	<i>re</i>	\$ 374.45	✓
1pc	rear tailgate inner rubber	<i>DIS</i>	\$ 381.90	✓
1pc	rear tailgate inner garnish	<i>Bu</i>	\$ 781.90	✓
1pc	rear tailgate inner handle	<i>re</i>	\$ 151.20	✓
2pcs	rear taillamp @\$581.90	<i>su</i>	\$ 1,163.00	X
2pcs	rear taillamp lower bracket @\$132.25	<i>su</i>	\$ 264.50	X
1pc	rear bumper <i>891.00</i>	<i>R</i>	\$ 981.90	✓
2pcs	rear bumper side retainer @\$132.45	<i>NSD</i>	\$ 264.90	✓
2pcs	rear bumper side reflector @\$181.50	<i>su</i>	\$ 363.00	X
1pc	rear end panel	<i>R</i>	\$ 781.10	✓
1pc	rear end panel outer sensor	<i>NSD</i>	\$ 260.00	X
1pc	rear end panel inner garnish	<i>Bu</i>	\$ 374.85	✓
1pc	rear floor panel	<i>R</i>	\$ 981.50	X
1pc	rear floor panel garnish box <i>425-30</i>	<i>re</i>	\$ 585.20	✓
1pc	rear floor panel garnish box top cover	<i>re</i>	\$ 381.52	✓
2pcs	rear floor panel garnish side garnish @\$321.50	<i>DIS</i>	\$ 643.00	✓
1pc	rear floor panel lower garnish	<i>NSD</i>	\$ 281.85	X
2pcs	rear fender inner garnish @\$758.85 <i>55210 NSD</i>	<i>DIS</i>	\$ 1,517.70	✓
		<i>cm</i>	\$ 12,491.55	
	less 25%		\$ 3,122.89	
			\$ 9,368.66	
1set	rear parking sensor	<i>Shan</i>	s.nett \$ 280.00	<i>200sn</i>
1set	rear number plate & casing	<i>re</i>	s.nett \$ 50.00	<i>45sn</i>
	remove & refix rear windscreen glass		\$ 120.00	✓
	sealant <i>re</i>		\$ 80.00	<i>40sn</i>
	tuffkote		\$ 120.00	<i>60</i>
	wiring		\$ 80.00	<i>20</i>
	spray painting		\$ 1,000.00	<i>800</i>
	labour charges		\$ 1,200.00	<i>800</i>
	Total		\$ 12,298.66	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No direct involvement is allowed
- Any item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____



LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119017319/KSD3N2

Date: 18/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN30351419000		
Claimant Vehicle No :	SLQ805M	Insured Vehicle No :	PC7262J		
Date of Loss:	30/09/2019	Nature of Claim:	TP	Claim No:	SNM19D204576C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ805M	Engine No:	2ZR1938902
Make & Model:	TOYOTA PRIUS ALPHA HYBRID, 1.8 S CVT (A)	Chassis No:	ZVW400024846
Reg. Date:	27/06/2017 (Man. Year: 2017)	Odometer:	257330 km
Colour:	Metallic Grey		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	AGENDA 7 mm	Rear Left Side:	AGENDA 8 mm
Front Right Side:	AGENDA 7 mm	Rear Right Side:	AGENDA 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,778.66	5,915.51	3,863.15	39.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,520.00	1,800.00	720.00	28.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,298.66	7,715.51	4,583.15	37.27
Approved Total (Overridden) (S\$)		6,150.00		
(S\$)	12,298.66	6,150.00	6,148.66	49.99
+ GST 7.00/7.00% (S\$)	860.91	430.50	430.41	49.99
Nett Amount (S\$)	13,159.57	6,580.50	6,579.07	49.99

INSPECTION

Date of Assignment:	02/10/2019		
Date Inspected:	01/10/2019	Inspected At:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare Singapore 575721

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Oct 2019)
Parts: 144	TOYOTA PRIUS ALPHA HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ805M)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,218.45 FL	*1,218.45 FL
2	1		*REAR TAILGATE OUTER GARNISH	Cracked	371.25 FL	*371.25 FL
3	1		*REAR TAILGATE TOYOTA LOGO	Necessary	61.10 FL	*61.10 FL
4	1		*REAR TAILGATE PRIUS EMBLEM	Necessary	63.90 FL	*63.90 FL
5	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	61.10 FL	*61.10 FL
6	1		*SET REAR TAILGATE WINDSCREEN GLASS MOULDING	Necessary	182.28 FL	*182.28 FL
7	1		*REAR TAILGATE INNER LOCK	Dented	374.45 FL	*374.45 FL
8	1		*REAR TAILGATE INNER RUBBER	Distorted/Dented	381.90 FL	*381.90 FL
9	1		*REAR TAILGATE INNER GARNISH	Buckled	781.90 FL	*781.90 FL
10	1		*REAR TAILGATE INNER HANDLE	Dented	151.20 FL	*151.20 FL
11	2		*REAR TAILLAMP	Serviceable	1,163.00 FL	*-FL
12	2		*REAR TAILLAMP LOWER BRACKET	Serviceable	264.50 FL	*-FL
13	1		*REAR BUMPER	Bent	981.90 FL	*891.00 FL
14	1		*REAR BUMPER SIDE RETAINER	N/s Distorted	264.90 FL	*132.45 FL
15	2		*REAR BUMPER SIDE REFLECTOR	Serviceable	363.00 FL	*-FL
16	1		*REAR END PANEL	Bent	781.10 FL	*781.10 FL
17	1		*REAR END PANEL OUTER SENSOR	No such part	260.00 FL	*-FL
18	1		*REAR END PANEL INNER GARNISH	Buckled	374.85 FL	*374.85 FL
19	1		*REAR FLOOR PANEL	Repair	981.50 FL	*-FL
20	1		*REAR FLOOR PANEL GARNISH BOX	Dented	585.20 FL	*425.30 FL
21	1		*REAR FLOOR PANEL GARNISH BOX TOP COVER	Dented	381.52 FL	*381.52 FL
22	1		*REAR FLOOR PANEL GARNISH SIDE GARNISH	O/s Dented	643.00 FL	*321.50 FL
23	1		*REAR FLOOR PANEL LOWER GARNISH	No such part	281.85 FL	*-FL
24	1		*REAR FENDER INNER GARNISH	Os Mtg Cracked/Ns Serviceable	1,517.70 FL	*552.10 FL
25	1		*SET REAR PARKING SENSOR	Shorted	280.00 FS	*200.00 FS
26	1		*SET REAR NUMBER PLATE & CASING	Dented	50.00 FS	*45.00 FS
27	1		*SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	12,901.55	7,792.35
- List Item Discount on L Items 25.00/25.00% (S\$)	3,122.89	1,876.84
Total Parts (S\$)	9,778.66	5,915.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	TUFFKOTE	New	120.00	60.00
3	WIRING	New	80.00	20.00
4	SPRAY PAINTING	New	1,000.00	800.00
5	LABOUR CHARGES	New	1,200.00	800.00
Gross Labour Cost (S\$)			2,520.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >