

12/03/2002

ASS. REC. BY:

REF:

CS/C249089231

Eq-132

Special Instruction:

SIVA/JOY: Steve

ASSIGNMENT (Office)

Date/Time: 07/10/19
25/09/2019

Merimen

From (Person): Tan Kah Leong of CTI

Bill to:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLK 5612B

Insured: SLE 913Y

at Workshop m/s Yew Tee Automobile Tech Pte Ltd

Tel: 6256 2081

of 39 Woodlands close #01-12

Policy No: DMPCSN3018341900

Claim No: SNM19D204487C02

Sum Insured:

Excess:

D.O.A. 20/09/2019

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 02/10/2019 @ 11:05a.m

Person Contacted:

Lai

H.O.D. Endorsement:

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SLE 913Y : NA/GAR 17009895/HA DOP: 22/05/2019
	SLK 5612B : X
14/10/19 @ 3.26pm	Yi Min (workshop) informed the vehicle just send in for repair.
17/10/19 @ 6.07pm	Steve finalised final fig \$3358.75, 4 days.
	(Total \$ 6875.30, 67%.)

ASS. REC. BY:

Sten

REF:

CTI

ASSIGNMENT

From:

Date:

7/10/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLK 5612B

at Workshop m/s

Yew Tee Automobile

of

39 woodlands close # 01-12

Insured:

Meyer @ woodlands

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

10-30am (waiting)

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLK 5612B

Yr Regn:

20/01/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Sienna

c.c

1496

Colour

Yellow

A/C: Insured / Std / NI / NA

Sp. Reading

46229

T/Radio: Insured / Std / NI / NA

Eng/No:

NJP170731560

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falki.

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

20/9/19

D.O.I.

7/10/19

Survey held at

Yew Tee

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-65K

RECEIVED 13 NOV 2019

Date/Time, File Pass to?



: Preli. Report

1) 2/11/19



: Final Report

Date/Time, File Return to?

2)

Rep. Form:

MER-TP

Lump Sum / E.R. / C

3358.75

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:



: Site Insp

(\$



: Interview

(\$



: Tech. Invs

(\$



: Weekend

(\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Sep 2019		02 Oct 2019 10:04 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: NGO KAI HUAT , ID: S7986984H									
Vehicle Reg. No.:		SLK5612B	Date of Loss:	20/09/2019 07:00 - :59					
Claim Type:		TP / SNM19D204487C02	Policy/Cover Note No.:	DMPCSN3018341900					
Vehicle Reg. No. (Insured):		SLE913Y	Policy No. (Claimant):	5109535181					
		Excess:	S\$1,000.00						
Repairer: Yew Tee Automobile Tech Pte Ltd (Woodlands) 39 Woodlands Close #01-12, Mega@Woodlands, 737856 Woodlands - Tel: 62562081									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/10/2019]									
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Sent: Wednesday, 2 October 2019 9:10 AM
To: 'YT(MG)'; assignments
Cc: Tan Kah Leong; Alfred Toh; Chee So Chow; 'YTKB'; 'YTHQ'; 'YTKB'; 'YTHQ'; YTHQ;
Subject: RE: OUR REF: SNM19D204487-SLE913Y-TKL & YOUR REF: SLK5612B - To Conduct PRS- Accident involving SLK5612B (NTUC) claiming against SLE913Y (China Taiping) on 20/09/2019
Attachments: OUR REF: SNM19D204487-SLE913Y-TKL & YOUR REF: SLK5612B - To Conduct PRS- ... (699 KB)

WITHOUT PREJUDICE

Dear Sky,

We refer to your email of 01.10.19.

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please refer to the email below with attachments and proceed to survey the third party vehicle.

Thank you.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6530
Fax: 6224 7478 / 6224 7175
Email: elaine.cheong@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: YT(MG) [mailto:info@yewteegroup.com]
Sent: Tuesday, 1 October, 2019 6:18 PM
To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; 'YTKB' <utauto2@singnet.com.sg>; 'YTHQ' <utauto@singnet.com.sg>; 'YTKB' <utauto2@singnet.com.sg>; 'YTHQ' <utauto@singnet.com.sg>; YTHQ <utauto@singnet.com.sg>; YTKB <utauto2@singnet.com.sg>
Subject: RE: OUR REF: SNM19D204487-SLE913Y-TKL & YOUR REF: SLK5612B - To Conduct PRS- Accident involving SLK5612B (NTUC) claiming against SLE913Y (China Taiping) on 20/09/2019
Importance: High

Hi Elaine,

URGENT!

Kindly please arrange for PRI soon.

Thanks.

Best Regards

Sky Toh

Mobile: 9747 1475

Website: www.yewteegroup.com

Email: info@yewteegroup.com

Like Us On Facebook

Director of

-YEW TEE AUTOMOBILE TECH PTE LTD



WEST HQ Office:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est

Singapore 678006

DID: 6762 2081 (3 Lines)

Fax: 6760 4895

Email: utauto@singnet.com.sg

EAST Branch Office:

Synergy@KB, 25 Kaki Bukit Road 4

Unit No #01-60/61

Singapore 417800

DID: 6702 3113 (3 Lines)

Fax: 6702 3773

Email: utauto2@singnet.com.sg

NORTH Branch Office:

Mega@Woodlands

39 Woodlands Close #01-12

Singapore 737856

DID: 6256 2081 (3 Lines)

Fax: 6256 2533

Email: info@yewteegroup.com



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: YT(MG) [<mailto:info@yewteegroup.com>]

Sent: Monday, 30 September, 2019 1:53 PM

To: 'Elaine Cheong'; 'Claims Dept of CTI'

Cc: 'Tan Kah Leong'; 'Alfred Toh'; 'Chee So Chow'; 'YTKB'; 'YTHQ'; YTKB; YTHQ

Subject: RE: OUR REF: SNM19D204487-SLE913Y-TKL & YOUR REF: SLK5612B - To Conduct PRS- Accident involving SLK5612B (NTUC) claiming against SLE913Y (China Taiping) on 20/09/2019

Resend

Hi Elaine,

Refer to the email below, we choose **LKK** to conduct the pre-repair survey.

Any updates of the survey arrangement.

Thank You ☺

Best Regards

Ms Lai Yee Meng



Yew Tee Automobile Tech Pte Ltd

Branch Office:

39 Woodlands Close,
#01-12 Mega@Woodlands
Singapore 737856
DID: 6256 2081
Email: info@yewteegroup.com

HQ:

Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895
Email: utauto@singnet.com.sg

Branch Office:

Synergy@KB, 25 Kaki Bukit Road
Unit No #01-60/61
Singapore 417800
DID: 6702 3113
Email: utauto2@singnet.com.sg



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: YT(MG) <info@yewteegroup.com>

Sent: Friday, 27 September 2019 5:37 PM

To: 'Elaine Cheong' <elaine.cheong@sg.cntaiping.com>; 'Claims Dept of CTI' <claimsdept@sg.cntaiping.com>

Cc: 'Tan Kah Leong' <KahLeong.Tan@sg.cntaiping.com>; 'Alfred Toh' <alfred.toh@sg.cntaiping.com>; 'Chee So Chow' <sochow.chee@sg.cntaiping.com>; YTKB <utauto2@singnet.com.sg>; YTHQ <utauto@singnet.com.sg>

Subject: RE: OUR REF: SNM19D204487-SLE913Y-TKL & YOUR REF: SLK5612B - To Conduct PRS- Accident involving SLK5612B (NTUC) claiming against SLE913Y (China Taiping) on 20/09/2019

Hi Elaine,

As spoken just now, from the 3 of the surveyor list you gave.

I choose **LKK** to conduct the pre-repair survey.

Please drop me a call before coming as the vehicle not in our workshop.

Kindly let me have the liability too.

Thank You ☺

Best Regards

Ms Lai Yee Meng



Yew Tee Automobile Tech Pte Ltd

Branch Office:

39 Woodlands Close,
#01-12 Mega@Woodlands
Singapore 737856
DID: 6256 2081
Email: info@yewteegroup.com

HQ:

Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895
Email: utauto@singnet.com.sg

Branch Office:

Synergy@KB, 25 Kaki Bukit Road
Unit No #01-60/61
Singapore 417800
DID: 6702 3113
Email: utauto2@singnet.com.sg



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: YT(MG) <info@yewteegroup.com>

Sent: Thursday, 26 September 2019 5:51 PM

To: 'Claims Dept of CTI' <claimsdept@sg.cntaiping.com>; 'Elaine Cheong' <elaine.cheong@sg.cntaiping.com>; 'Alfred Toh' <alfred.toh@sg.cntaiping.com>; 'Chee So Chow' <sochow.chee@sg.cntaiping.com>; 'Tan Kah Leong' <KahLeong.Tan@sg.cntaiping.com>

Cc: YTKB <utauto2@singnet.com.sg>; YTHQ <utauto@singnet.com.sg>

Subject: RE: OUR REF: SNM19D204487-SLE913Y-TKL & YOUR REF: SLK5612B - To Conduct PRS- Accident involving SLK5612B (NTUC) claiming against SLE913Y (China Taiping) on 20/09/2019

Hi Elaine,

Please let us have the list of surveyor for choose to conduct the pre-repair survey.

Hi Kah Leong,

Kindly let us have the liability too.

Thank You ☺

Best Regards

Ms Lai Yee Meng



Yew Tee Automobile Tech Pte Ltd

Branch Office:

39 Woodlands Close,
#01-12 Mega@Woodlands
Singapore 737856
DID: 6256 2081
Email: info@yewteegroup.com

HQ:

Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895
Email: utauto@singnet.com.sg

Branch Office:

Synergy@KB, 25 Kaki Bukit Road
Unit No #01-60/61
Singapore 417800
DID: 6702 3113
Email: utauto2@singnet.com.sg



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Sent: Tuesday, 24 September 2019 4:14 PM

To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>; info@yewteegroup.com; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Subject: OUR REF: SNM19D204487-SLE913Y-TKL & YOUR REF: SLK5612B - To Conduct PRS- Accident involving SLK5612B (NTUC) claiming against SLE913Y (China Taiping) on 20/09/2019

Dear Elaine,

Please conduct PRS –SLK5612B soonest possible on behalf of Kah Leong.

File with Elaine Cheong : DID: 6389 6530

Officer In Charge- Tan Kah Leong- DID: 6389 6193

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
Tel: (65) 6389 6116 - F: (65) 6224 7478

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: YT(MG) [<mailto:info@yewteegroup.com>]
Sent: Tuesday, September 24, 2019 2:25 PM
To: Claims Dept of CTI
Cc: YTKB; YTHQ
Subject: Accident involving SLK5612B (NTUC) claiming against SLE913Y (China Taiping) on 20/09/2019

Hi Claim Dept,

Attached report and estimate.

Kindly arrange PRI at 39 Woodlands Close, #01-12 Mega @ Woodlands S(737856).

Please let us have the list of surveyor for choose to conduct the pre-repair survey.

Kindly let us have the liability and officer-in-charge too.

Thank You ☺

Best Regards

Ms Lai Yee Meng



Yew Tee Automobile Tech Pte Ltd

Branch Office:

39 Woodlands Close,
#01-12 Mega@Woodlands
Singapore 737856
DID: 6256 2081
Email: info@yewteegroup.com

HQ:

Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895
Email: utauto@singnet.com.sg

Branch Office:

Synergy@KB, 25 Kaki Bukit Road

Unit No #01-60/61
Singapore 417800
DID: 6702 3113
Email: utauto2@singnet.com.sg



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Steve Chen (LKK Auto)

From: YT(MG) <info@yewteegroup.com>
Sent: Tuesday, November 12, 2019 6:02 PM
To: Steve Chen (LKK Auto)
Cc: YTKB; YTHQ
Subject: RE: SLK5612B Finalize

Hi Steve,

We confirm \$3358.25 (P/P, before GST). 4 repair days.

Thank You ☐

Best Regards

Ms Lai Yee Meng



Yew Tee Automobile Tech Pte Ltd

Branch Office:
39 Woodlands Close,
#01-12 Mega@Woodlands
Singapore 737856
DID: 6256 2081
Email: info@yewteegroup.com

HQ:
Blk 6 Woodlands Road 399F
Yew Tee Ind. Est
Singapore 678006
DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895
Email: utauto@singnet.com.sg

Branch Office:
Synergy@KB, 25 Kaki Bukit Road
Unit No #01-60/61
Singapore 417800
DID: 6702 3113
Email: utauto2@singnet.com.sg



please consider the environment before printing this email

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/09/2019 17:01
Date Of Accident	20/09/2019 07:25
Exact Location Of Accident	SLIP ROAD OF SERANGOON ROAD > CTE (AMK)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK5612B
Insured/Policyholder	
Name Of Registered Owner	NGO KAI HUAT
NRIC No	S7986984H
Email Address	VANNESS8832@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-93665399
Alternative Phone No	OFFICE-93665399

Vehicle Particulars

Manufacturer	TOYOTA
Model	SIENTA-1.5 G (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5109535181
Cover Note Number	

Driver

Name of Driver	NGO KAI HUAT
NRIC No	S7986984H
Date Of Birth	17/02/1979
Occupation	INDOOR
Date Of Driving Pass	02/11/2002
Driving Experience	16 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93665399
Fax Number	
Contact Number	OFFICE-93665399
Email Address	VANNESS8832@HOTMAIL.COM

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	984H
Vehicle Details	
Vehicle No.:	SLK5612B
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Oct 2019
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA 1.5G A
Primary Colour:	Yellow
Manufacturing Year:	2016
Engine No.:	2NR8614004
Chassis No.:	NSP1707031560
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$22,585.00
Original Registration Date:	20 Jan 2017
First Registration Date:	20 Jan 2017
Transfer Count:	1
Actual ARF Paid:	\$13,619.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jan 2027
PARF Rebate Amount:	\$10,214.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,889.00
COE Rebate Amount:	\$37,058.00
Total Rebate Amount:	\$47,272.00

The information contained herein is correct as at 07 Oct 2019

OK

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856

Tel: 62562281 Fax: Email: YTMG

INSURER : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTMG/TP/1909/014Requ
Policy No:	5109535181	Date of Loss:	20/09/2019
Vehicle Reg. No.:	SLK5612B	Driveable?	no
Driver Age:	17/02/1979	Third Party Vehicle No.:	SLE913Y
Any Injuries?	no	Contact No:	93665399
Insured/Claimant:	NGO KAI HUAT	Driver:	NGO KAI HUAT

Make/Model:	Toyota, Sienta - NSP170	Vehicle Reg. Date:	20/01/2017
Vehicle Colour:	YELLOW	Engine Number:	
Chassis No:	NSP1707031560	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

Description of Accident/loss COLLISION - HEAD TO REAR
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS

	Amount
Parts	7,433.55
Miscellaneous Items	365.00
Labour	1,290.00
Paintwork Labour	945.00
Towing	0.00
Gross Total(S\$):	10,033.55
GST 7.00%(S\$):	702.35
Nett Amount(S\$):	10,735.90

This claim is handled by: Sky Toh T C

9341.75

9541.75

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER / CR	356.00	-25.00	267.00
2	1	REAR BUMPER SIDE RETAINER LH X NAI	78.00	-10.00	70.20
3	1	REAR BUMPER SIDE RETAINER RH X NAI	78.00	-10.00	70.20
4	1	REAR BUMPER BRACKET LH X NAI	68.00	-10.00	61.20
5	1	REAR BUMPER BRACKET RH X NAI	68.00	-10.00	61.20
6	1	REAR BUMPER CENTRE PROTECTOR / CHT	182.00	-10.00	163.80
7	1	REAR BUMPER PROTECTOR LH X NAI	124.00	-10.00	111.60
8	1	REAR BUMPER PROTECTOR RH X NAI	124.00	-10.00	111.60
9	1	REAR BUMPER PROTECTOR REFLECTOR X NAI	87.00	-10.00	78.30
		LH			
10	1	REAR BUMPER PROTECTOR REFLECTOR X NAI	87.00	-10.00	78.30
		RH			
11	1	REAR BUMPER TOWING COVER LH X NAI	37.00	-10.00	33.30
12	1	REAR BUMPER INNER SPONGE X NAI	128.00	-10.00	115.20
13	1	REAR BUMPER REINFORCEMENT X NAI	330.00	-25.00	247.50
14	1	REAR TAILGATE / DO	1,086.00	-25.00	814.50
15	1	REAR TAILGATE HINGES LH X NAI	83.00	-10.00	74.70
16	1	REAR TAILGATE HINGES RH X NAI	83.00	-10.00	74.70
17	1	REAR TAILGATE LOGO / NAI	59.00	-10.00	53.10
18	1	REAR TAILGATE REFLECTOR LH X NAI	250.00	-10.00	225.00
19	1	REAR TAILGATE REFLECTOR RH X NAI	250.00	-10.00	225.00
20	1	REAR TAILGATE LOCK / BT	448.00	-10.00	403.20
21	1	REAR TAILGATE LOCK CATCH X NAI	35.00	-10.00	31.50
22	1	REAR TAILGATE INNER BOARD X NAI	235.00	-25.00	176.25
23	1	REAR TAILGATE RUBBER X NAI	357.00	-10.00	321.30
24	1	REAR TAILLAMP LH X NAI	370.00	-10.00	333.00
25	1	REAR TAILLAMP RH X NAI	370.00	-10.00	333.00
26	1	REAR FENDER INNER TRIM BOARD LH X NAI	657.00	-25.00	492.75
27	1	REAR FENDER INNER TRIM BOARD RH X NAI	657.00	-25.00	492.75
28	1	REAR END PANEL CENTRE X NAI	378.00	-25.00	283.50
29	1	REAR END PANEL LOWER X R	608.00	-10.00	547.20
30	1	REAR END PANEL TOP GARNISH X NAI	147.00	-10.00	132.30
31	1	REAR SPARE TYRE PANEL X NAI	678.00	-25.00	508.50
32	1	REAR SPARE TYRE BOARD X NAI	491.00	-10.00	441.90

8984
6744.75

Total Parts (\$\$) **7,433.55**

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIPS / NAI	45.00	0.00	45.00
2	1	REAR BUMPER SENSORS (1 SET) / SHJ	260.00	0.00	260.00
3	1	REAR WINDSCREEN GLASS SEALANT / NAI	60.00	0.00	60.00

38
200
40

Sub Total (\$\$) **365.00**

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	0.00	30.00

270

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00
3	1	To Dismantle and Refit Rear Windscreen Glass.	100.00	0.00	100.00
4	1	To Transfer Rear Tailgate.	80.00	0.00	80.00
5	1	To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section.	100.00	0.00	100.00
6	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	900.00	0.00	900.00

Gross Labour Cost (\$\$) 1,290.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	40.00	0.00	40.00
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	0.00	45.00
3	1	To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection.	60.00	0.00	60.00
4	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	800.00	0.00	800.00

Gross Labour Cost (\$\$) 945.00

< END OF ESTIMATES >

Steve (LKK) W-L Proj L 7/10/19, 10.39 am

4 day

P/P

Ry Ref Spy

P-1598.25

M-970

L-1290

Supp-200

P/P-3358.25

Insurance Company to be notified
 of the following:
 - Estimated spray painting
 - Estimated resurvey
 - Estimated confirmation
 - Estimated "Without Prejudice" basis
 - Estimated resurvey and
 - Estimated final approval from Insurance Company

Endorsed by Repairer
 Signature:
 Date:

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12
Singapore 737856

Tel: 62562281 Fax: Email: YTMG

INSURER : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

PARTICULARS OF CLAIM			
Claim Type:	TP	Ref. No:	YTMG/TP/1909/014Requ
Policy No:	5109535181	Date of Loss:	20/09/2019
Vehicle Reg. No.:	SLK5612B	Driveable?	no
Driver Age:	17/02/1979	Third Party Vehicle No.:	SLE913Y
Any Injuries?	no	Contact No:	93665399
Insured/Claimant:	NGO KAI HUAT	Driver:	NGO KAI HUAT
Make/Model:	Toyota, Sienta - NSP170	Vehicle Reg. Date:	20/01/2017
Vehicle Colour:	YELLOW	Engine Number:	
Chassis No:	NSP1707031560	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

Description of Accident/loss COLLISION - HEAD TO REAR
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

COST OF CLAIMS		Amount
Parts		0.00
Miscellaneous Items		200.00
Labour		0.00
Paintwork Labour		0.00
Towing		0.00
Gross Total(S\$):		200.00
GST 7.00%(S\$):		14.00
Nett Amount(S\$):		214.00

This claim is handled by: Lai Yee Meng

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
			Total Parts (\$\$)			0.00

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	REAR REVERSE CAMERA / Short	200.00	200.00	0.00	200.00
			Sub Total (\$\$)			200.00

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
			Gross Labour Cost (\$\$)			0.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
			Gross Labour Cost (\$\$)			0.00

< END OF ESTIMATES >

NI-200

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Sep 2019		02 Oct 2019 10:04 Edit Adj Rpt	S\$3,358.25 Edit Estimates	S\$3,358.25 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS				[Created by insurer]
Insured:	-, Co. Reg. No.: -			
Main Claimant:	NGO KAI HUAT, ID: S7986984H			
Vehicle Reg. No.:	SLK5612B	Date of Loss:	20/09/2019 07:00 - :59 [32 Months From LTA Reg Date (Man Yr)]	
Claim Type:	TP / SNM19D204487C02	Policy/Cover Note No.:	DMPCSN3018341900	
Vehicle Reg. No. (Insured):	SLE913Y	Policy No. (Claimant):	5109535181	
		Excess:	S\$1,000.00	
Repairer:	Yew Tee Automobile Tech Pte Ltd (Woodlands) 39 Woodlands Close #01-12, Mega@Woodlands, 737856 Woodlands - Tel: 62562081			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]			
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 11/10/2019]			
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail
There are no mail for this case.				
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete
Due Date:	Priority	Type	Task Group	Subject
				Handler
				Assigned By
				Completed On
				Created On
				Done?
No results.				

Claim Documents

***SLK5612B (SNM19D204487C02)**
[SLE913Y]

TP

NGO KAI HUAT

Sep 20 2019 7:00AM

[-]

Yew Tee Automobile Tech Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser ▼	
			1 per page ▼	<input checked="" type="checkbox"/>
Assessment Reports			Thumbnail	Print
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Woodlands)		Load HTM
1	20/09/19 17:22	Accident Statement		
			3 per page ▼	<input checked="" type="checkbox"/>
Photos/Images			Thumbnail	Print
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Woodlands)		Load JPG
1	20/09/19 17:06	Accident Photo [Linked Accident Report Documents]		<input checked="" type="checkbox"/>
2	20/09/19 17:06	Accident Photo [Linked Accident Report Documents]		<input checked="" type="checkbox"/>
3	20/09/19 17:06	Accident Photo [Linked Accident Report Documents]		<input checked="" type="checkbox"/>
4	20/09/19 17:06	Accident Photo [Linked Accident Report Documents]		<input checked="" type="checkbox"/>
5	20/09/19 17:06	Accident Photo [Linked Accident Report Documents]		<input checked="" type="checkbox"/>
6	20/09/19 17:06	Accident Photo [Linked Accident Report Documents]		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/11/19 14:23	General View		<input checked="" type="checkbox"/>
2	13/11/19 14:23	General View		<input checked="" type="checkbox"/>
3	13/11/19 14:23	General View		<input checked="" type="checkbox"/>
4	13/11/19 14:23	General View		<input checked="" type="checkbox"/>
5	13/11/19 14:23	General View		<input checked="" type="checkbox"/>
6	13/11/19 14:23	General View		<input checked="" type="checkbox"/>
7	13/11/19 14:23	General View		<input checked="" type="checkbox"/>
8	13/11/19 14:23	General View		<input checked="" type="checkbox"/>
9	13/11/19 14:23	General View		<input checked="" type="checkbox"/>
10	13/11/19 14:23	General View		<input checked="" type="checkbox"/>
11	13/11/19 14:23	General View		<input checked="" type="checkbox"/>
12	13/11/19 14:23	General View		<input checked="" type="checkbox"/>
13	13/11/19 14:23	General View		<input checked="" type="checkbox"/>
14	13/11/19 14:23	General View		<input checked="" type="checkbox"/>
15	13/11/19 14:23	General View		<input checked="" type="checkbox"/>
16	13/11/19 14:23	General View		<input checked="" type="checkbox"/>
17	13/11/19 14:23	General View		<input checked="" type="checkbox"/>
18	13/11/19 14:23	General View		<input checked="" type="checkbox"/>
19	13/11/19 14:23	General View		<input checked="" type="checkbox"/>
20	13/11/19 14:23	General View		<input checked="" type="checkbox"/>
21	13/11/19 14:23	General View		<input checked="" type="checkbox"/>
22	13/11/19 14:23	General View		<input checked="" type="checkbox"/>
23	13/11/19 14:23	General View		<input checked="" type="checkbox"/>
24	13/11/19 14:23	General View		<input checked="" type="checkbox"/>
25	13/11/19 14:23	General View		<input checked="" type="checkbox"/>
26	13/11/19 14:23	General View		<input checked="" type="checkbox"/>
27	13/11/19 14:23	Odometer Reading		<input checked="" type="checkbox"/>
28	13/11/19 14:23	Chassis Number		<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Woodlands)	Thumbnail	Print
29	13/11/19 14:23	General View	Load JPG	<input checked="" type="checkbox"/>
30	13/11/19 14:23	General View	Load JPG	<input checked="" type="checkbox"/>
31	13/11/19 14:23	General View	Load JPG	<input checked="" type="checkbox"/>
32	13/11/19 14:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
33	13/11/19 14:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
34	13/11/19 14:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
35	13/11/19 14:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	13/11/19 14:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	13/11/19 14:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	13/11/19 14:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	13/11/19 14:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	13/11/19 14:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	13/11/19 14:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	13/11/19 14:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	13/11/19 14:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	13/11/19 14:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	13/11/19 14:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	13/11/19 14:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	13/11/19 14:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	13/11/19 14:25	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	02/10/19 10:06	PRS - SLK5612B	Load PDF	
2	02/10/19 10:06	REPAIR ESTIMATE - SLK5612B	Load PDF	
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Woodlands)	Thumbnail	Print
1	20/09/19 17:06	Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	20/09/19 17:06	Sketch Plan #2 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/11/19 15:55	SUPPLEMENTARY	Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Woodlands)	1 per page	<input checked="" type="checkbox"/>
1	20/09/19 17:22	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Woodlands)	Thumbnail	Print
1	20/09/19 17:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	20/09/19 17:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	20/09/19 17:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	20/09/19 17:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	20/09/19 17:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	20/09/19 17:06	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (Woodlands)	Thumbnail	Print
1	20/09/19 17:06	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	20/09/19 17:06	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19017323/EQF3S2
Date: 19/11/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN3018341900
Claimant Vehicle No: SLK5612B Insured Vehicle No: SLE913Y
Date of Loss: 20/09/2019 Nature of Claim: TP Claim No: SNM19D204487C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLK5612B Engine No: 2NR8614004
Make & Model: TOYOTA SIENTA, 1.5 G (A) Chassis No: NSP1707031560
Reg. Date: 20/01/2017 (Man. Year: 2016) Odometer: 46229 km
Colour: Yellow
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
Front Left Side: Falken 5 mm Rear Left Side: Falken 5 mm
Front Right Side: Falken 5 mm Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,306.75	2,068.25	5,238.50	71.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,235.00	1,290.00	945.00	42.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,541.75	3,358.25	6,183.50	64.80
+ GST 7.00/7.00% (S\$)	667.92	235.08	432.84	64.80
Nett Amount (S\$)	10,209.67	3,593.33	6,616.34	64.80

INSPECTION

Date of Assignment: 02/10/2019
Date Inspected: 07/10/2019 Inspected At: Yew Tee Automobile Tech Pte Ltd (Woodlands)
39 Woodlands Close #01-12, Mega@Woodlands
Singapore 737856
Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Nov 2019)
Parts:	M1-MPV	TOYOTA SIENTA 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLK5612B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Crushed	356.00 FL	*356.00 FL
2	1		*REAR BUMPER REINFORCEMENT	Not Necessary	330.00 FL	*- FL
3	1		*REAR TAILGATE	Dented	1,086.00 FL	*1,086.00 FL
4	1		*REAR TAILGATE INNER BOARD	Not Necessary	235.00 FL	*- FL
5	1		*REAR FENDER INNER TRIM BOARD LH	Not Necessary	657.00 FL	*- FL
6	1		*REAR FENDER INNER TRIM BOARD RH	Not Necessary	657.00 FL	*- FL
7	1		*REAR END PANEL CENTRE	Not Necessary	378.00 FL	*- FL
8	1		*REAR SPARE TYRE PANEL	Not Necessary	678.00 FL	*- FL
9	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	78.00 FL	*- FL
10	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	78.00 FL	*- FL
11	1		*REAR BUMPER BRACKET LH	Not Necessary	68.00 FL	*- FL
12	1		*REAR BUMPER BRACKET RH	Not Necessary	68.00 FL	*- FL
13	1		*REAR BUMPER CENTRE PROTECTOR	Cut	182.00 FL	*182.00 FL
14	1		*REAR BUMPER PROTECTOR LH	Not Necessary	124.00 FL	*- FL
15	1		*REAR BUMPER PROTECTOR RH	Not Necessary	124.00 FL	*- FL
16	1		*REAR BUMPER PROTECTOR REFLECTOR LH	Not Necessary	87.00 FL	*- FL
17	1		*REAR BUMPER PROTECTOR REFLECTOR RH	Not Necessary	87.00 FL	*- FL
18	1		*REAR BUMPER TOWING COVER LH	Not Necessary	37.00 FL	*- FL
19	1		*REAR BUMPER INNER SPONGE	Not Necessary	128.00 FL	*- FL
20	1		*REAR TAILGATE HINGES LH	Not Necessary	83.00 FL	*- FL
21	1		*REAR TAILGATE HINGES RH	Not Necessary	83.00 FL	*- FL
22	1		*REAR TAILGATE LOGO	Necessary	59.00 FL	*59.00 FL
23	1		*REAR TAILGATE REFLECTOR LH	Not Necessary	250.00 FL	*- FL
24	1		*REAR TAILGATE REFLECTOR RH	Not Necessary	250.00 FL	*- FL
25	1		*REAR TAILGATE LOCK	Bent	448.00 FL	*448.00 FL
26	1		*REAR TAILGATE LOCK CATCH	Not Necessary	35.00 FL	*- FL
27	1		*REAR TAILGATE RUBBER	Not Necessary	357.00 FL	*- FL
28	1		*REAR TAILLAMP LH	Not Necessary	370.00 FL	*- FL
29	1		*REAR TAILLAMP RH	Not Necessary	370.00 FL	*- FL
30	1		*REAR END PANEL LOWER	Repair	608.00 FL	*- FL
31	1		*REAR END PANEL TOP GARNISH	Not Necessary	147.00 FL	*- FL
32	1		*REAR SPARE TYRE BOARD	Not Necessary	491.00 FL	*- FL
33	1		*REAR BUMPER CLIPS	Necessary	45.00 FS	*30.00 FS
34	1		*SET REAR BUMPER SENSORS	Shorted	260.00 FS	*200.00 FS
35	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
36	1		*REAR REVERSE CAMERA	Shorted	200.00 FS	*200.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	9,554.00	2,601.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,247.25	532.75
Total Parts (\$\$)	7,306.75	2,068.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS.	New	30.00	30.00
2	TO REMOVE AND REFIT REAR BUMPER SENSOR.	New	80.00	20.00
3	TO DISMANTLE AND REFIT REAR WINDSCREEN GLASS.	New	100.00	100.00
4	TO TRANSFER REAR TAILGATE.	New	80.00	50.00
5	TO REMOVE AND REFIT CARPET AND TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	New	100.00	30.00
6	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.	New	900.00	500.00
7	TO CARRY-OUT BODY CAVITY PRESERVATION.	New	40.00	30.00
8	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTINGS AREAS.	New	45.00	0.00
9	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.	New	60.00	30.00
10	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.	New	800.00	500.00
Gross Labour Cost (S\$)			2,235.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >