

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5770L**AAD1909-228**

Not Authored
Resurvey B4 paint

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

01 OCT 2019

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 5770L

JTDKB3FU103077053

TOYOTA

PRIUS

26.9.19

AIG

22/11/2018

PART		LIST	
1	1 PANEL SUB-ASSY, FRONT DOOR, RH	\$	1,287.40
2	1 WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH	\$	321.10
3	1 RUN, FRONT DOOR GLASS, RH	\$	153.60
4	1 WEATHERSTRIP, FRONT DOOR, RH	\$	231.30
5	1 FRONT DOOR OUTER MOULDING RH	\$	188.60
6	1 MOTOR ASSY, POWER WINDOW REGULATOR, RH	\$	926.00
7	1 REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$	238.30
8	1 TAPE, BLACK OUT, NO.1 FRT RH	\$	13.30
9	1 TAPE, BLACK OUT, NO.2 FRT RH	\$	43.50
10	1 TAPE, BLACK OUT, NO.3 FRT RH	\$	26.30
11	1 RIGHT SIDE VIEW MIRROR	\$	1,339.30
12	1 CHECK ASSY, FRONT DOOR	\$	183.80
13	1 HINGE ASSY, FRONT DOOR, LOWER RH	\$	110.60
14	1 HINGE ASSY, FRONT DOOR, UPPER RH	\$	97.50
15	1 WIRE, FRONT DOOR, RH	\$	532.80
16	1 FRONT BUMPER	\$	516.00
17	1 FRONT BUMPER SIDE RETAINER RH	\$	82.30
18	1 FRONT LED LAMP (LOWER) RH	\$	951.40
19	1 FRONT HEADLAMP RH	\$	2,637.60
20	1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	960.50
21	1 MOTOR, HEADLAMP LEVELING, RH	\$	487.50
22	1 FRONT FENDER RH	\$	977.80
23	1 LINER, FRONT FENDER, RH	\$	202.50
24	1 MOULDING ASSY, BODY ROCKER PANEL, RH	\$	583.30
25	1 FRONT BONNET	\$	983.10
26	1 HINGE ASSY, HOOD, RH	\$	58.90
TOTAL		\$	14,134.30
25%		\$	3,533.58
		\$	10,600.73

Trans-cab Auto Services Pte Ltd**AAD1909-228**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5770L**Special Nett**

1	1	FRONT DOOR STICKER 'TRANS-CAB'	\$	<i>me</i> 80.00
2	1	CLIP, FRONT FENDER LINER	\$	<i>nn</i> 22.00 X
3	1	FRONT WHEEL RIM	\$	<i>sn</i> 1,570.55 X
4	1	FRONT WHEEL RIM COVER	\$	<i>sn</i> 175.80 X
5	1	FRONT TYRE 195/65/15	\$	<i>sn</i> 350.00 X
6	1SET	BUMPER CLIP FRT	\$	<i>nn</i> 66.00 X
7	1	FRONT NUMBER PLATE WITH MOULDING	\$	<i>sn</i> 200.00 X
TOTAL			\$	2,464.35

TOTAL PARTS \$ 13,065.08**LABOUR**

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00 X
Putty And Spray Painting Of The Affected Portion.	\$	6,000.00 <i>5000</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00 <i>2000</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i> 170.00 X
To transfer of tire, rim and on wheel balancing.	\$	<i>sn</i> 170.00 X
To check steering geometry and computer wheel alignment	\$	<i>sn</i> 220.00 X
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	<i>sn</i> 380.00 X
To Check Electrical Lighting Concerned.	\$	<i>sn</i> 170.00 X
To transfer of front door fittings, attachment and perform water seepage test.	\$	<i>sn</i> 170.00 X
To transfer of front fender fittings, attachment to facilitate bodywork repair.	\$	<i>sn</i> 170.00 X

Trans-cab Auto Services Pte Ltd**AAD1909-228**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5770L

To transfer of front bumper fittings, attachment to facilitate
bodywork repair.

\$ *nn* 170.00 X

To transfer of front bonnet fittings, attachment to facilitate
bodywork repair.

\$ *nn* 170.00 X**TOTAL \$ 14,170.00****Over All Total \$ 27,235.08****(PART-BY-PART) Repair Days**~~20 days~~*2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: