

FBE 6158P 2010 June.
Yamaha Spark 135cc
5YP012387

MON TUE WED THU

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Front Fender *cracked*
Front Wheel Rim *warpped*
Front Brake Disc *warpped*
Front Cowling. *cracked*
Front Signal Lamp LH. *fine*
Headlamp *fine*
Headlamp Cowling. *cracked*
Front Fork Assy *best*
Front Fork Under Bracket *best*
Steering Cone and Bearing *new*
Handle Bar *best*
Balancer LH *cut*
Front LH Wing Mirror *cut*
Front Inner Cowling (Blue). *cracked*
Side Cowling LH. *cracked*
Front LH Foot Rest *best*
Rear LH Foot Rest.
Rear Wooden Board *cracked*
Rear Box Bracket. *new*
Speedometer *new*
Stickers *new*

✓ 75 75
880

125 ✓

135 ✓

120 x

260 x

185 ✓

480 ✓

150 ✓

70 ✓

80 ✓

25 ✓

35 ✓

125 ✓

95 ✓

38 ✓

30 ✓

50(SN) 30(SN)

100(SN) +

450 +

50(SN) 30(SN)

1803

1622 70

S.N: 60

Labour
Spray Painting.
Wiring.
Towing Fees.

400 250

400 200 520

50 30

40. ✓

total: 2202.70

L/S: 1.5K

(Nett Value)

04 Days

200