

Kg

Date: 01.10.2019
Vehicle No: SMM9729A
Model: HONDA VEZEL 1.5RS CVT
Chassis: RU11201731 - 2016
Reg.Year: L15B4401731 - 2019

Third Party Insurer: EQ
Third Party Veh No: SGY2558E
Date of Accident: 27.09.2019

Not Authored

Returning BP point 88712.32
2-3 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT HEAD LAMP RH	1		\$1,755.00
2	FRONT BUMPER	1		\$677.20
3	FRONT BUMPER SIDE BRACKET RH	1		\$38.20
4	FRONT BUMPER UPPER BRACKET RH	1		\$74.30
5	FRONT BUMPER CLIPS	8	\$5.50	\$44.00
6	FRONT BUMPER LAMP RH	1		\$234.00
7	FRONT BUMPER LAMP FINISHER RH	1		\$54.60
8	FRONT FENDER EXTENTION COVER RH	1		\$148.60
9	FRONT FENDER INNER LINER CLIPS	8	\$5.80	\$46.40
10	FRONT BUMPER LOWER COVER			REPAIR
11	FRONT FENDER RH			REPAIR
SUB TOTAL				\$3,072.30
LESS 20%				-\$614.46
PARTS TOTAL				\$2,457.84

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST FRONT ACCIDENT AREAS & ETC

\$400.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT ACCIDENT AREAS & ETC

\$700.00

TO TUFF KOTE & UNDERSEAL MATERIALS

\$120.00

TO CHECK WIRING & ELECTRICAL SYSTEMS

\$50.00

TO DIAGNOSIS FAULTY CODE & RESET MEMORY

\$120.00

LMK 4010 Consult agent to notify the Reparer in the following: • To advise (after safety system) • To advise (after safety system) • To advise (after safety system)		LABOUR TOTAL	\$1,390.00
ONG		TOTAL	\$3,847.84