

# 源摩哆廠

## GUAN MOTOR WORKS

Business Regn. No. 08102600I

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

### REPAIR ESTIMATE FOR SLR9673L

| No.      | Qty   | List Items                       |                         |
|----------|-------|----------------------------------|-------------------------|
| 1        | 1     | Front bumper                     | \$ <i>Bz</i> 421.70 ✓   |
| 2        | 2     | Front bumper fog lamp            | \$ <i>Sm</i> 473.80 X   |
| 3        | 2     | Front bumper side retainer       | \$ <i>Sm</i> 113.40 X   |
| 4        | 1 set | Front bumper clips               | \$ <i>nm</i> 40.00 ✓    |
| 5        | 1     | Front bumper inner foam          | \$ <i>Sm</i> 85.70 X    |
| 6        | 1     | Front bumper inner reinforcement | \$ <i>n</i> 387.90 ✓    |
| 7        | 1     | Front grille assy                | \$ <i>cm</i> 846.30 ✓   |
| 8        | 1     | Front "TOYOTA" logo              | \$ <i>Sm</i> 56.90 ✓    |
| 9        | 2     | Headlamp                         | \$ 6,091.60 7           |
| 10       | 1     | Front bonnet                     | \$ <i>Bz</i> 696.50 ✓   |
| 11       | 2     | Front bonnet hinge               | \$ <i>n</i> 161.80 X    |
| 12       | 1     | Front bonnet lock                | \$ <i>n</i> 162.90 X    |
| 13       | 1     | Front support panel              | \$ <i>n</i> 1,097.10 X  |
| 14       | 1     | Front intercooler                | \$ <i>Sm</i> 720.60 X   |
| 15       | 1     | Air con condenser                | \$ 1,218.00 7           |
| 16       | 1     | Radiator                         | \$ <i>Sm</i> 2,154.90 X |
| 17       | 1     | Radiator fan cowling             | \$ <i>Sm</i> 261.90 X   |
|          |       |                                  | \$ 14,991.00            |
| Less 25% |       |                                  | \$ 3,747.75             |
| Total :  |       |                                  | \$ 11,243.25            |

| Special Nett Items |   |                      |
|--------------------|---|----------------------|
| 18                 | 1 | Front number plate   |
|                    |   | \$ <i>Pm</i> 50.00 X |
| Total :            |   | \$ 50.00             |

| Labour  |                                                                          |                         |
|---------|--------------------------------------------------------------------------|-------------------------|
| 1       | Labour Charges for remove/refit and replace damage part:                 | \$ 1,000.00 <i>4501</i> |
| 2       | To putty and spray Spray Paintings charges.                              | \$ 1,000.00 <i>6001</i> |
| 3       | To check wirings and lightings.                                          | \$ 40.00 <i>201</i>     |
| 4       | To remove, refit A/C condenser, radiator etc., including refill A/C gas. | \$ <i>nm</i> 150.00 X   |
| 5       | To supply and apply anti rust treatment                                  | \$ 80.00 <i>301</i>     |
| Total : |                                                                          | \$ 2,270.00             |

Total Parts and Labour : \$ 13,563.25

*Not withash*  
*Permy B4 paint*  
*4 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: