

AIG ASIA PACIFIC INSURANCE PTE. LTD.

Attn: Motor Claims Department

Dear Sir / Madam,

ACCIDENT INVOLVING VEHICLE NO SLR 9673 L & YP 832 K ALONG PEARL'S HILL ROAD on 30/09/2019

We understand that you are the insurer of YP 832 K vehicle.


I/We wish to inform you that my/our vehicle SLR 9673 L have been completed repairs to my/our satisfaction by M/s GUAN MOTOR WORKS. I/We therefore propose to claim from your as follow:

1.	Cost of Repairs	S\$ 7,653.50
2.	Loss of Use (S\$ <u>150.00</u> x <u>07</u> days)	S\$ 1,050.00
3.	LTA Search Fee	S\$ 7.49
TOTAL		<u>S\$ 8,710.99</u>

Please let us have your reply soonest possible.

Thank you.

Yours faithfully,



源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 081026-00E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 H/P: 9742 6003

Messrs: PANG YA XUAN, SHARON

Invoice No: 5055

Date: 16-12-2019

TOYOTA SIENTA - 1.5 HYBRID (A) - SLR 9673 L

Part by part repair cost inclusive of spare parts and labour charges.

\$7,653.50

Dollars Seven thousand Six hundred Fifty-three and Cents Fifty only.



E.&O.E.

Enquire Vehicle & Owner Information (Vehicle No. YP832K As At 30 Sep 2019 / 09:47:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: TCK.WITLTA.2019 GM

Current Owner Details

Owner ID Type: Company
Owner ID: 201840763R
Owner Name: AURENTAL PTE.LTD.
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 7
Registered Street Name: MANDAI LINK
Registered Unit No.: # 03-38
Registered Building Name: MANDAI CONNECTION
Registered Postal Code: 728653
Current Vehicle Details

Vehicle No.: YP832K
Make Description/Model: MITSUBISHI / CANTER FEB21ER4SDEB
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE.LTD.