

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

LEE CHUEI YEN

c/o 46 Lenton Plain
Singapore 786548

Not Authorized
Call by 87
Running After Painting
3 days

Date: 1/10/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: LEXUS IS250C / SKQ 1889 B	
1 pc	rear bumper	1,656.40
2 pcs	rear bumper parking sensor	734.80
1 pc	rear bumper reinforcement	656.20
1 pc	rear bumper lower sponge	457.20
1 pc	rear bumper upper sponge	213.10
1 pc	rear bumper reflector	167.30
1 pc	rear bumper tow cover	67.80
2 pcs	rear bumper side retainer	130.20
1 pc	rear boot lock sensor receiver	368.30
1 pc	rear boot emblem logo	78.50
1 pc	rear boot emblem "IS250C"	76.30
1 pc	rear boot lamp	578.40
1 pc	rear boot weather strip	315.10
1 pc	rear boot lock catch	215.00
1 pc	rear boot emblem "LEXUS"	76.30
1 pc	rear end panel	785.20
1 pc	rear end panel trim	451.10
1 pc	rear tail lamp	698.40
	sub-total	7,725.60
	less 25%	1,931.40
	sub-total	5,794.20
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	1,000.00
	To check wiring system.	40.00
	To apply putty and spray painting on affected areas.	1,200.00
	To apply rust proofing on affected areas.	120.00
	To apply waterproof sealant on affected areas.	120.00
	total	8,274.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: