

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

02 OCT 2019

Estimate No. : b1 52876
Date Estimated : 26/09/2019
Prepared By : Joseph Yaguel

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -
Raymond Goh Soon Khiang (Raymond Wu)
46 Sunrise Avenue

Singapore 806694

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJD6883P	WBAJA52080WC07907	31/10/2017	530iA	0

DESCRIPTION	VALUE
Reworking right front side panel	850 1,275.00
Spray right front fender	796 885.00
Sundries	40 80.00
Total Labour 1:	2,240.00

DESCRIPTION	QTY	PRIC	VALUE
RH TRIM AIR DUCT SIDE PANEL (GLANZS) / CUT	1	68.90	68.90
Total Parts :			68.90

Steve (LKK)

WHL P/L
18/12/19, 4.30pm
P/P

By B/L S/L
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	2,240.00
Parts	:	68.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	161.62
Grand Total	:	2,470.52

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **