

22/11/2019

ASS. REC. BY:

REF: CS3/CTI19015647/Fsd3-1

ial Instruction:

Surveyor: Ram

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of

CTI

Date/Time:

2/10/2019

Estimated Cost:

Bill to:

OD ☒ TWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGS 2535C

Insured:

GBE 3500D

at Workshop in/s

King's Auto

Tel:

6457 8629

of

Blk 176 Sin Ming Drive #02-10

Policy No:

DMCVSN31110318022

Claim No:

SNM19D204028C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11:05am 4/9/19

Person Contacted:

Adeline

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

SGS 2535C - X

GBE 3500D - X

Dismantle: 5/9/2019

After repair: 9/9/2019

RECEIVED 10 OCT 2019

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: SGS 2535C

at Workshop m/s: Kings auto

of 176 SW MING DRIVE #02-10

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Source:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGS 2535C

Yr Regis:

MAR 2007

Type:

M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Primo Mover /

Truck / Trailer or

Make:

Toyota wish

cc 1794

Colour:

silver

NC:

Insured / Std / NI / NA

Sp. Reading:

256081

T/Ratio:

Insured / Std / NI / NA

Eng/No:

C/No: ZNE10-0351197

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: 195/65 R15

R: 195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

24/08/19

D.O.A.

4/9/2019

Survey held at

Kings auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & C/S rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range \$3000-\$4000

Repair days: 5 days

MV: \$21000

FV: \$12614

NV: \$8000

LS confirm with Alex on 8/10/19

LS: \$2750 * 5 repair days

(\$ 4,128.11 Red - 60%)

Date/Time, File Pass to?

10/10/19

1) Typ. 4

Date/Time, File Return to?

2)

☐

: Prel. Report

☒

: Final Report

Days Of Repair:

5

Resurvey No. of Trip:

23

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

190

Transportation:

\$ + 165.00

Photos

Others

TOTAL

190

Report Format:

PRE

Lump Sum / I.B.I. (\$

2,750/ LS

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

244G

Vehicle Details

Vehicle No.:

SGS2535C

Vehicle to be Exported:

No

Intended Deregistration Date:

05 Sep 2019

Vehicle Make:

TOYOTA

Vehicle Model:

WISH 1.8 A

Primary Colour:

Silver

Manufacturing Year:

2006

Engine No.:

1ZZ2822635

Chassis No.:

ZNE100351197

Maximum Power Output:

97.0 kW (130 bhp)

Open Market Value:

\$16,536.00

Original Registration Date:

08 Mar 2007

First Registration Date:

08 Mar 2007

Transfer Count:

2

Actual ARF Paid:

\$18,190.00

Intended PARF Rebate Details

PARF Eligibility:

Forfeited

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

07 Mar 2022

COE Category:

E - Open Category

COE Period(Years):

5

PQP Paid:

\$25,174.00

COE Rebate Amount:

\$12,614.00

Total Rebate Amount:

\$12,614.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 05 Sep 2019

Remaining: 2 years, 6 months 16 days (304) OK
Depn: \$8110/yearly \$707.90 (monthly)
30 x \$707.90 = \$21,237.00

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/08/2019 15:22
Date Of Accident	24/08/2019 20:50
Exact Location Of Accident	487 GEYLANG RD OPEN CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGS2535C
Insured/Policyholder	
Name Of Registered Owner	NURAZLIN GHULAM
NRIC No	S8036244G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-87323725
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	TOYOTA
Model	WISH 1.8 A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/00165835/05
Cover Note Number	08/03/2019 TO 07/03/2020
Driver	
Name of Driver	GHULAM MUHAMMAD BIN ABDULLAH
NRIC No	S1266852Z
Date Of Birth	07/04/1957
Occupation	INDOOR
Date Of Driving Pass	23/08/1980
Driving Experience	39 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87323725
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	AP1 BLK 888 TAMPINES ST 81 #02-1104
Postcode	520888
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PARENT
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE3500D	Kia K2500
Vehicle Make/Model/Colour		
Details Of Properties		
Vehicle Category	COMMERCIAL VEHICLE	
Name of Driver		
NRIC/Passport Number		
Contact Number		
Address		
Postcode		
Insurance Company Name		
Nature Of Damage		
No. Of Passenger (Including Driver)		

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature 24/08/19
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: 28/08/19

Date of accident: 24/8/19 Time: 2050 hrs Location: 487 Geyland Road
My Vehicle A: SGS 2535C Vehicle B: GFE 3500D Vehicle C:
SKETCH PLAN

Sketch Plan Pg. 2

Date of accident: 24/8/19 Time: 20.50 hrs Location: 487 Geyland Road
 My Vehicle A: SGS 2535C Vehicle B: GBE 3500D Vehicle C: /

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My Car SGS 2535C was park in car lot,
 I was waiting out the car when lorry GBE 3500D
 bang into my car

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop : Ken's Auto
 Email address : yenking13@hotmail.com
 & myself : yenking13@hotmail.com
 Email address : yenking13@hotmail.com

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Vehicle

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 24/8/19

Reporting Centre Person's Name:
 NRIC/FIN No.: 201819



MAKER Sketch Plan page 2/2

KING'S AUTO REPAIR & SERVICE PTE LTD

BLK 176, SIN MING DRIVE, #02-01, SINGAPORE 575721
TEL: 6457-8629 FAX: 6451-7651

DATE 27th Sept 2019
OUR REF SGS2535C

TO Nurazlin Ghulam
883 Tampines street 81,
#02-1104,
Singapore 520888
RE Quotation For Toyota Wish

Att: Nurazlin
Fax 6457-8629
62564315

02/10/2019

Quantity	Item	Unit Price (\$)	Amount (\$)
1	REAR BOOT LID		1 330.62 DD
2	REAR BOOT LID DAMPER	247.09	494.18 xnn
1	REAR BOOT LID EMBLEM- LOGO		52.44 nec
1	REAR BOOT LID GARNISH		250.33 xnn
1	REAR BOOT LID INNER BOARD		361.04 xnn
1	REAR BOOT LID LOCK		487.55 xnn
1	REAR BOOT LID CATCH		38.35 xnn
1	REAR BOOT LID SWITCH		97.41 xnn
2	REAR NO.PLATE LAMPS	58.19	116.38 xnn
1	REAR GLASS MOULDING		80.13 nec
1	REAR RUBBER SEAL		334.17 DS
2	REAR LAMP	450.59	901.18 cra
2	REAR LAMP LOWER BRACKET	30.04	120.03 nec
1	REAR BUMPER		517.43 cra
2	REAR BUMPER SIDE RETAINER	32.76	125.52 nec
SET	REAR BUMPER CLIPS		38.50 nec
2	REAR BUMPER BRACKET	53.28	106.56 DS
2	REAR BUMPER REFLECTORS	59.44	118.88 DS
SUB-TOTAL			5,570.81
LESS 25% DISCOUNT			1,392.70
TOTAL			4,178.11

SPECIAL NETT ITEMS

Quantity	Item	Unit Price (\$)	Amount (\$)
1	SEALANT FOR GLASS		80.00 nec
1	REAR NO.PLATE EMBOS		20.00 xnn
SET	REVERSE SENSOR		240.00 DS
SET	REVERSE CAMERA		360.00 DS
TOTAL			720.00

FOR LABOUR CHARGES

Quantity	Item	Unit Price (\$)	Amount (\$)
	WIRING		80.00 \$30
	REMOVE AND REFIT GLASS		140.00 \$80
	TRANSFER BOOT LID PARTS		80.00 \$50
	RUSTPROOF		80.00 \$50
	PANEL BEATING		800.00 \$250
	SPRAY PAINTING		800.00 \$450
TOTAL			1,960.00

GRAND TOTAL FOR THIS QUOTATION

6,878.11

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Parts prices are subject to confirmation
and party survey is on a "Without Prejudice" basis
Legal modification(s) is allowed
Elementary item(s) must be resurveyed and
subject to final approval from Insurance Company

Approved by Repairer

3/10/19
Ram (LKK)
3/10/19 (45)
ParaSoran@lkkauto.com
repair days (5)

20% L/S : \$2750.00

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Sep 2019		23 Sep 2019 14:38 Edit Adj Rpt	\$2,750.00 Edit Estimates	\$2,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: NURAZLIN GHULAM , ID: S8036244G									
Vehicle Reg. No.: SGS2535C		Date of Loss: 24/08/2019 20:00 - :59 [149 Months and 16 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D204028C02		Policy/Cover Note No.: DMCVSN31110318022							
Vehicle Reg. No. (Insured): GBE3500D		Policy No. (Claimant): MT/00165835/05							
		Excess: S\$0.00							
Repairer: King's Auto Repair & Service Pte Ltd (HQ) BLK 176 SIN MING DRIVE, #02-10, 575721 Sin Ming - Tel: 64578629									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Claimant's Insurer: Direct Asia Insurance (Singapore) Pte Ltd (HQ) - Tel: 65322888									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 14/10/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> CHINA_TAIPIING (10/10/2019): Report Send Back Alerts - SGS2535C (TP) 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGS2535C (SNM19D204028C02)**
[GBE3500D]

TP























































NURAZLIN GHULAM

Aug 24 2019 8:00PM

[-]

King's Auto Repair & Service Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser <input type="button" value="v"/>	
Assessment Reports				1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (Sin Ming)		Thumbnail	Print
1	28/08/19 15:33	Accident Statement		Load HTM	
Photos/Images				3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (Sin Ming)		Thumbnail	Print
1	28/08/19 15:28	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	28/08/19 15:28	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	28/08/19 15:28	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	28/08/19 15:28	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	28/08/19 15:28	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	28/08/19 15:28	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
7	28/08/19 15:28	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
8	28/08/19 15:28	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>
2	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>
3	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>
4	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>
5	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>
6	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>
7	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>
8	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>
9	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>
10	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>
11	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>
12	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>
13	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>
14	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>
15	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>
16	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>
17	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>
18	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>
19	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>
20	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>
21	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>
22	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>
23	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>
24	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>
25	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>
26	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>
27	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>
28	24/09/19 12:27	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (Sin Ming)	Thumbnail	Print
29	24/09/19 12:27	General View	 Load JPG	<input checked="" type="checkbox"/>
30	24/09/19 12:27	General View	 Load JPG	<input checked="" type="checkbox"/>
31	24/09/19 12:27	General View	 Load JPG	<input checked="" type="checkbox"/>
32	24/09/19 12:27	General View	 Load JPG	<input checked="" type="checkbox"/>
33	24/09/19 12:27	General View	 Load JPG	<input checked="" type="checkbox"/>
34	24/09/19 12:27	General View	 Load JPG	<input checked="" type="checkbox"/>
35	24/09/19 12:27	General View	 Load JPG	<input checked="" type="checkbox"/>
36	24/09/19 12:27	General View	 Load JPG	<input checked="" type="checkbox"/>
37	24/09/19 12:27	General View	 Load JPG	<input checked="" type="checkbox"/>
38	24/09/19 12:27	General View	 Load JPG	<input checked="" type="checkbox"/>
39	24/09/19 12:27	General View	 Load JPG	<input checked="" type="checkbox"/>
40	24/09/19 12:27	General View	 Load JPG	<input checked="" type="checkbox"/>
41	24/09/19 12:27	General View	 Load JPG	<input checked="" type="checkbox"/>
42	24/09/19 12:27	General View	 Load JPG	<input checked="" type="checkbox"/>
43	24/09/19 12:27	General View	 Load JPG	<input checked="" type="checkbox"/>
44	24/09/19 12:27	General View	 Load JPG	<input checked="" type="checkbox"/>
45	24/09/19 12:27	General View	 Load JPG	<input checked="" type="checkbox"/>
46	24/09/19 12:27	General View	 Load JPG	<input checked="" type="checkbox"/>
47	24/09/19 12:27	General View	 Load JPG	<input checked="" type="checkbox"/>
48	24/09/19 12:27	General View	 Load JPG	<input checked="" type="checkbox"/>
49	24/09/19 12:27	General View	 Load JPG	<input checked="" type="checkbox"/>
50	24/09/19 12:27	General View	 Load JPG	<input checked="" type="checkbox"/>
51	24/09/19 12:27	General View	 Load JPG	<input checked="" type="checkbox"/>
52	24/09/19 12:27	General View	 Load JPG	<input checked="" type="checkbox"/>
53	24/09/19 12:27	General View	 Load JPG	<input checked="" type="checkbox"/>
54	24/09/19 12:27	General View	 Load JPG	<input checked="" type="checkbox"/>
55	24/09/19 12:27	General View	 Load JPG	<input checked="" type="checkbox"/>
56	24/09/19 12:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	24/09/19 12:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	24/09/19 12:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	24/09/19 12:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	24/09/19 12:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	24/09/19 12:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	24/09/19 12:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	24/09/19 12:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	24/09/19 12:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	24/09/19 12:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	24/09/19 12:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	24/09/19 12:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	24/09/19 12:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	24/09/19 12:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	24/09/19 12:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	24/09/19 12:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	24/09/19 12:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	24/09/19 12:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	24/09/19 12:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	24/09/19 12:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	24/09/19 12:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	24/09/19 12:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	24/09/19 12:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	24/09/19 12:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	24/09/19 12:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	24/09/19 12:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	24/09/19 12:29	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	24/09/19 12:29	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
84	24/09/19 12:29	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (Sin Ming)	Thumbnail	Print
85	24/09/19 12:29	Photo After Spray		<input checked="" type="checkbox"/>
86	24/09/19 12:29	Photo After Spray		<input checked="" type="checkbox"/>
87	24/09/19 12:29	Photo After Spray		<input checked="" type="checkbox"/>
88	24/09/19 12:29	Photo After Spray		<input checked="" type="checkbox"/>
89	24/09/19 12:29	Photo After Spray		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (Sin Ming)	Thumbnail	Print
1	28/08/19 15:30	Sketch Plan [Linked Accident Report Documents]		<input type="checkbox"/>
2	28/08/19 15:30	Driver's Particulars [Linked Accident Report Documents]		<input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/10/19 11:04	PRS Invoice		<input type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (Sin Ming)	Thumbnail	Print
1	28/08/19 15:33	Accident Statement		<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (Sin Ming)	Thumbnail	Print
1	28/08/19 15:28	Accident Photo		<input checked="" type="checkbox"/>
2	28/08/19 15:28	Accident Photo		<input checked="" type="checkbox"/>
3	28/08/19 15:28	Accident Photo		<input checked="" type="checkbox"/>
4	28/08/19 15:28	Accident Photo		<input checked="" type="checkbox"/>
5	28/08/19 15:28	Accident Photo		<input checked="" type="checkbox"/>
6	28/08/19 15:28	Accident Photo		<input checked="" type="checkbox"/>
7	28/08/19 15:28	Accident Photo		<input checked="" type="checkbox"/>
8	28/08/19 15:28	Accident Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ah Lim Motor Company (Sin Ming)	Thumbnail	Print
1	28/08/19 15:30	Sketch Plan		<input type="checkbox"/>
2	28/08/19 15:30	Driver's Particulars		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19015647/FSD3E2-1

Date: 11/10/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN31110318022
 Claimant Vehicle No : SGS2535C Insured Vehicle No : GBE3500D
 Date of Loss: 24/08/2019 Nature of Claim: TP Claim No: SNM19D204028C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGS2535C**
 Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 1ZZ2822635
 Reg. Date: 08/03/2007 (Man. Year: 2006) Chassis No: ZNE100351197
 Colour: Silver Odometer: 256081 km
 Engine Capacity: 1794 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 4 mm
 Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,898.11	2,318.99	2,579.12	52.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	1,110.00	870.00	43.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,878.11	3,428.99	3,449.12	50.15
Approved Total (Overridden) (S\$)		2,750.00		
Nett Amount (S\$)	6,878.11	2,750.00	4,128.11	60.02

INSPECTION

Date of Assignment: 23/09/2019

Date Inspected: 04/09/2019 Inspected At:

King's Auto Repair & Service Pte Ltd
 (HQ)
 BLK 176 SIN MING DRIVE, #02-10
 Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Oct 2019)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGS2535C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Dented	1,330.62 FL	*1,275.00 FL
2	2		*REAR BOOT LID DAMPER	Not Necessary	494.18 FL	*- FL
3	1		*REAR BOOT LID EMBLEM - LOGO	Necessary	52.44 FL	*52.44 FL
4	1		*REAR BOOT LID GARNISH	Not Necessary	250.33 FL	*- FL
5	1		*REAR BOOT LID INNER BOARD	Not Necessary	361.04 FL	*- FL
6	1		*REAR BOOT LID LOCK	Not Necessary	487.55 FL	*- FL
7	1		*REAR BOOT LID CATCH	Not Necessary	38.35 FL	*- FL
8	1		*REAR BOOT LID SWITCH	Not Necessary	97.41 FL	*- FL
9	2		*REAR NO. PLATE LAMPS	Not Necessary	116.38 FL	*- FL
10	1		*REAR GLASS MOULDING	Necessary	80.19 FL	*80.19 FL
11	1		*REAR RUBBER SEAL	Distorted	334.17 FL	*143.00 FL
12	1		*REAR LAMP	O/S Cracked	901.18 FL	*450.59 FL
13	1		*REAR LAMP LOWER BRACKET	O/S Necessary	120.08 FL	*30.00 FL
14	1		*REAR BUMPER	Cracked	517.43 FL	*517.43 FL
15	2		*REAR BUMPER SIDE RETAINER	Necessary	125.52 FL	*65.00 FL
16	1		*SET REAR BUMPER CLIPS	Necessary	38.50 FL	*30.00 FL
17	2		*REAR BUMPER BRACKET	Distorted	106.56 FL	*75.00 FL
18	1		*REAR BUMPER REFLECTORS	O/S Scratched	118.88 FL	*40.00 FL
19	1		*SEALANT FOR GLASS	Necessary	80.00 FS	*50.00 FS
20	1		*REAR NO. PLATE EMBOSS	Not Necessary	40.00 FS	*- FS
21	1		*SET REVERSE SENSOR	Scratched	240.00 FS	*200.00 FS
22	1		*SET REVERSE CAMERA	No Damaged	360.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,290.81	3,008.65
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,392.70	689.66
Total Parts (\$\$)	4,898.11	2,318.99

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRING	New	80.00	30.00
2	REMOVE AND REFIT GLASS	New	140.00	80.00
3	TRANSFER BOOT LID PARTS	New	80.00	50.00
4	RUSTPROOF	New	80.00	50.00
5	PANEL BEATING	New	800.00	450.00
6	SPRAY PAINTING	New	800.00	450.00
Gross Labour Cost (\$\$)			1,980.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >