

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19017396/AVD3E2
Date: 13/12/2019

REFERENCE

Insured/Claimant:	STEVE CHEUNG MEI SAI	Policy No:	2100346347-06	
Date of Loss:	08/09/2019	Nature of Claim:	OD	Claim No: 3860980651SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKK6248A	Engine No:	CCZ376123
Make & Model:	AUDI Q3, 2.0 TFSI quattro (170 BHP) (A)	Chassis No:	WAUZZZ8U1DR112846
Reg. Date:	13/08/2013 (Man. Year: 2013)	Odometer:	69401 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$72,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,853.00	4,924.48	2,928.52	37.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,452.00	4,002.00	3,450.00	46.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	15,305.00	8,926.48	6,378.52	41.68
+ GST 7.00/7.00% (\$\$)	1,071.35	624.85	446.50	41.68
Nett Amount (\$\$)	16,376.35	9,551.33	6,825.02	41.68

INSPECTION

Date of Assignment:	03/10/2019		
Date Inspected:	02/10/2019	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - RH	Dented	2,412.00 FS	*1,929.60 FS
2	1		*OUTER DOOR SEAL - RH	Necessary	152.00 FS	*121.20 FS
3	1		*PROTECTIVE FILM	Necessary	24.00 FS	*18.64 FS
4	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	97.00 FS	*- FS
5	1		*BONDING AGENT	Not Necessary	45.00 FS	*- FS
6	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
7	1		*FRONT DOOR CATCH	Not Necessary	109.00 FS	*- FS
8	1		*FRONT DOOR COVER - RH	Deformed	233.00 FS	*186.00 FS
9	1		*REAR DOOR - RH	Dented	2,412.00 FS	*1,929.60 FS
10	1		*DOOR SEAL BRACKET	Not Necessary	17.00 FS	*- FS
11	1		*OUTER DOOR SEAL - RH	Necessary	157.00 FS	*125.60 FS
12	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	197.00 FS	*- FS
13	1		*BONDING AGENT	Not Necessary	45.00 FS	*- FS
14	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
15	1		*REAR DOOR CATCH	Not Necessary	109.00 FS	*- FS
16	1		*REAR DOOR COVER - RH	Cut	235.00 FS	*187.60 FS
17	2		*REAR WHEEL ARCH TRIM LH / RH	Necessary	472.00 FS	*377.60 FS
18	1		*SUNDRIES	Necessary	300.00 FS	*18.56 FS
19	1		*DOOR LOCK REAR RHS (DAMAGED)	Not Consistent With The Impact	669.00 FS	*- FS
20	1		*TYRE PRESSURE DATA PLATE	Necessary	38.00 FS	*30.08 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **7,853.00** **4,924.48**

LKK Auto Consultants Pte Ltd/SKK6248A/13/12/2019 08:40

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	560.00	560.00
2	TO DISMANTLE RHS FRONT DOOR RHS REAR DOOR AND REAR BUMPER. RENEW RHS BOTH DOORS. REINSTALL ALL PARTS REMOVED	New	3,200.00	1,500.00
3	TO RESPRAY RHS FRONT DOOR, RHS REAR DOOR, DOOR HANDLE AND REAR BUMPER	New	3,500.00	1,750.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (\$\$)			7,452.00	4,002.00

LKK Auto Consultants Pte Ltd/SKK6248A/13/12/2019 08:40

< END OF ESTIMATES >