

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 11670

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1086/2019/NS
Date : 10-Sep-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : **SJU 8915 D**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Steve Cheung Mei Sai
Address : 70 Joo Chiat Ave
Singapore 428178
Telephone : HP +65 96666980
Type of Claim : Own Damage Claims
Policy No. : 2100346347-06
Vehicle No : **SKK 6248 A**
Model Code : Q3 2.0 TFSI QU
Model / Year : Aug-13
Engine No : CCZ 376123
Chassis No : WAUZZZ8U1DR112846
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 8-Sep-19
Place of Accident : At The Junction Of Collyer / Finlayson Green

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKK 6248 A

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rhs front door and rhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 560.00 ✓	
2	To dismantle rhs front door rhs rear door and rear bumper .Renew rhs both doors.Reinstall all parts removed. ✓ ✓ ✓	\$ 3,200.00 ¹⁵⁰⁰	
3	To respray rhs front door, rhs rear door, door handle and rear bumper. ✓	\$ ¹⁷⁵⁰ 3,500.00 ^{550 x 3 = 1650} ^{handle : 1000}	
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 7,452.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKK 6248 A

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT DOOR - RH <i>Dented</i>	\$ 2,412.00	✓
2	OUTER DOOR SEAL - RH <i>Ne</i>	NEC \$ 152.00	✓
3	PROTECTIVE FILM <i>Ne</i>	\$ 24.00	✓
4	FRONT DOOR ATTACHMENT PARTS ?	\$ 97.00	?
5	BONDING AGENT ?	NEC \$ 45.00	?
6	CLEANING SOLUTION ?	NEC \$ 65.00	?
7	FRONT DOOR CATCH <i>Ne</i>	\$ 109.00	X
8	FRONT DOOR COVER - RH <i>Dented</i>	\$ 233.00	✓
9	TYRE PRESSURE DATA PLATE <i>Ne</i>	\$ 38.00	✓
10	REAR DOOR - RH <i>Dented.</i>	\$ 2,412.00	✓
11	DOOR SEAL BRACKET <i>Ne</i>	\$ 17.00	X
12	OUTER DOOR SEAL - RH <i>Ne</i>	NEC \$ 157.00	✓
13	REAR DOOR ATTACHMENT PARTS ?	\$ 197.00	?
14	BONDING AGENT ?	NEC \$ 45.00	?
15	CLEANING SOLUTION ?	NEC \$ 65.00	?
16	REAR DOOR CATCH <i>Ne</i>	\$ 109.00	X
17	REAR DOOR COVER - RH <i>Ne</i>	\$ 235.00	✓
18	REAR WHEEL ARCH TRIM LH / RH <i>Ne</i>	2 \$ 472.00	✓
19	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS CHARGES		: \$ 7,184.00	
TOTAL LABOUR CHARGES		\$ 7,452.00	
GRAND TOTAL		\$ 14,636.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adnan Y
Surveyed Date : 02/10/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 06 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant