

Beng Hai Motor Service

Bedok North Ave 4

Blk 3012 #01-2058 Bedok Industrial Park E

Singapore 489978 Tel : 64441544

Business Reg. No. 52836794C / 92253195

Lms choo

ESTIMATE

Claim Type : Third Party	Date of Accident : 18/09/2019
Vehicle Reg. No. : GBH8769Y	Claimant : Beng Hai Motor Service
Vehicle Make & Model : Toyota Hiace Manual	
Description	Amount (S\$)
1 Rear Right Tail Lamp ✓ CRA	\$ 771.00 → 600
Less 25%	(\$ 192.75)
	\$ 578.25 450 ✓
Labour charges for :-	
1) Spray painting Rear Right Fender	\$ 220.00 200 ✓
2) Remove and install Rear Right Tail Lamp + repair rear fender R/H	\$ 200.00 200 ✓
3) Check Rear lighting and wiring	\$ 50.00 20 ✓
Total	\$1,048.25 =====
Sin Dollars : One Thousand & Forty Eight & Cents Twenty Five Only.	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4/10/19

1.00pm

85311883

Hock ANN

without prejudice

Resurvey after paint

4/5 rpr

2 days

Hock ANN@lkkauto.com

parts = 600

less 25%

450

labour = 420

= 870

4/5 less 20%

Total

4/5 mant = \$ 696.00