

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub, Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way, #07-16

Singapore 079120

Attention : Motor Claim Department

Contact : 64191053 Fax No. : 68357416

Estimate : TP19-123

Date : 01/10/2019

Vehicle Num. : SME529L

Make/Model : Toyota Camry-2018

Chassis/Eng# : MR053DK5100113582/6ARP432174

Accident Date : 28/09/2019

Claim No. :

Reference : SLX8390C

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1 pc	Rear Boot Lid		1,217.45
2.	1 pc	Rear Boot Lid 'Camry' Emblem		162.10
3.	1 pc	Rear Boot Lid Toyota Logo		161.50
4.	1 pc	Rear Boot Lid 'D4S' Emblem		82.70
5.	1 pc	Rear Boot Lid Weatherstrip		278.75
6.	1 pc	Rear Boot Lid Mechanism Lock		371.70
7.	2 pcs	Rear Boot Lamp L/R	427.85	855.70
8.	1 pc	Rear Boot Chrome Trim		317.45
9.	1 pc	Rear No. Plate Lamp Garnish		281.90
10.	2 pcs	Rear Lamp Assy L/R	471.10	942.20
11.	1 pc	Rear Bumper Assy		758.45
12.	8 pcs	Rear Bumper Clips	15.90	127.20
13.	1 pc	Rear Bumper Side Holder LH		191.70
14.	1 pc	Rear Bumper Bracket LH		189.25
15.	1 pc	Rear Bumper Inner Sponge		218.90
16.	1 pc	Rear Bumper Reinforcement		431.70
17.	1 pc	Rear Bumper Side Inner Liner LH		198.05
18.	1 pc	Rear Lamp Panel LH		413.85
19.	1 pc	Rear End Panel		731.40
20.	1 pc	Rear Panel Inner Top Garnish		391.70
21.	1 pc	Rear Spare Tyre Panel		471.45
22.	1 pc	Rear Bumper Reflector LH		35.00
23.	1 pc	Rear Bumper Lower Garnish		321.05
24.	1 pc	Rear Chassis Frame LH		780.00

List TotalS\$:

25.00% Discount S\$:

9,921.15

2,480.29

7,440.86

SPECIAL NETT ITEMS :

1. 1 set

Reverse Sensor

300

880.00

Special Nett Total S\$:

880.00

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
 Kaki Bukit Autohub. Singapore 417921
 Tel No. : 67461515 / 67471787 Fax No. : 67485015
 Website : www.successunited.com.sg
 Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd
 AIG Building
 78 Shenton Way, #07-16
 Singapore 079120

Attention : Motor Claim Department
 Contact : 64191053 Fax No. : 68357416

Estimate : TP19-123

Date : 01/10/2019
 Vehicle Num. : SME529L
 Make/Model : Toyota Camry-2018
 Chassis/Eng# : MR053DK5100113582/6ARP432174
 Accident Date : 28/09/2019
 Claim No. :
 Reference : SLX8390C
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :

To remove, rearrange electrical wirings, check lighting

80.00 ³⁰

To remove, instal upholstery, inner trim garnishes.

250.00 ⁶⁰

To remove, repair and replaced damaged bodyparts,
 realign bodyworks & where consistent to the accident

1,600.00 ¹⁰⁰⁰

To putty and respray painting on affected area.

1,500.00 ⁸⁰⁰

Labour Total S\$:

3,430.00

Adrian Lj
 4/5 02/10/19
 OS Drp.

total: 4985.85
 (P/P).
 06 Days.

Total S\$: 11,750.86
 =====


 SUCCESS UNITED PTE LTD

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: