

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/FWD19017435/AGS3Q2

**Date:** 29/10/2020

### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00008946

**Claimant**  
**Vehicle No :** SJW5163R **Insured Vehicle No :** SLF3971D

Date of Loss: 28/09/2019 Nature of Claim: TP Claim No: 1201900029070

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW5163R		
Make & Model:	SUBARU IMPREZA, 1.5 (A)	Engine No:	EL15D681933
Reg. Date:	30/03/2010 (Man. Year: 2009)	Chassis No:	JF1GE3KF39G004774
Colour:	Blue	Odometer:	125645 km
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R15	Rear Tyre Size:	205/55 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>1,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>1,800.00</b>	<b>-1,800.00</b>	
<b>+ Loss of Use (14.0 x S\$50.00/day) (S\$)</b>		700.00		
<b>Nett Liability (S\$)</b>		<b>2,500.00</b>		

### INSPECTION

Date of Assignment: 02/10/2019

Date Inspected: 02/10/2019 Inspected At:

96 Motorsports Pte Ltd (HQ)  
62 Kaki Bukit Avenue 6, The Ark@KB  
Singapore 417893

Estimated Period of Repair: 0.0 days

**Adjuster:** ADRIAN LING

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

MARKET VALUE : \$10,500.00

LTA REIMBURSEMENT VALUE (RV) : \$8,700.00

NETT VALUE : \$1,800.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED.

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 Oct 2019)
<b>Parts:</b>	143	SUBARU IMPREZA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJW5163R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**