

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub, Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way, #07-16

Singapore 079120

Attention : Motor Claim Department

Contact : 64191053 Fax No. : 68357416

* Drop Claim

LKK Auto Consultants hereby notify
the Repairer of the following:
• To resurvey before and after spraying
• To display damaged parts during survey
• Parts prices are on a cost plus basis
• Third party survey on a Work or Pre-Production basis
• No illegal modification is allowed
• Supplementary work must be approved and
is subject to final approval from insurance company

Acknowledged by Repairer

Signature: Estimate : TP19-122

Date: 26/09/2019

Vehicle Num. : SKH7852P

Make/Model : M/Benz E200-2012

Chassis/Eng# : WDD2120482A740715/271860306174

Accident Date : 26/09/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1 pc	Bonnet <i>Painted Paper</i>		2,680.00 <i>X</i>
2.	1 pc	Bonnet Hinge LH <i>new</i>		260.00 <i>X</i>
3.	1 pc	Bonnet Mechanism Lock LH <i>new</i>		92.00 <i>X</i>
4.	1 pc	Headlamp Assy LH <i>new</i>		1,351.00 <i>X</i>
5.	1 pc	Headlamp Bracket LH <i>new</i>		282.00 <i>X</i>
6.	1 pc	Frt Grille Assy <i>new</i>		1,295.00 <i>X</i>
7.	1 pc	Frt Bumper Assy <i>new</i>		1,870.00 <i>X</i>
8.	10 pcs	Frt Bumper Clips <i>new</i>	11.50	115.00 <i>30</i>
9.	1 pc	Frt Bumper Side Holder LH <i>new</i>		45.00 <i>X</i>
10.	1 pc	Frt Bumper Inner Base Frame <i>new</i>		256.00 <i>X</i>
11.	1 pc	Frt Bumper Inner Sponge <i>new</i>		115.00 <i>X</i>
12.	1 pc	Frt Bumper Daylight Garnish LH <i>new</i>		110.00 <i>X</i>
13.	2 pcs	Frt Parking Sensor LH <i>new</i>	365.00	730.00 <i>365</i>
14.	1 pc	Frt Fender LH <i>new</i>		1,150.00 <i>X</i>
15.	1 pc	Frt Fender Inner Liner LH <i>new</i>		312.00 <i>X</i>
16.	1 pc	Frt Bumper Reinforcement <i>new</i>		856.00 <i>X</i>
List Total S\$:				11,519.00
10.00% Discount S\$:				1,151.90
				10,367.10

LABOUR :

To remove, rearrange electrical wirings, check lighting

80.00 *30*

To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident

850.00 *600*

To putty and respray painting on affected area.

1,000.00 *600*

Labour Total S\$:

1,930.00

Total S\$: 12,297.10

=====

SUCCESS UNITED PTE LTD

total: 4765.10

Admin Lin

n/s: 3810

H/s 02/10/19.

05 Days.