



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

Adnan, UKE
(710)

LUCKY RIDES

04/10/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP FWD

Xiao Tony

Accident date: 02/10/2019

Estimated repair cost for vehicle no: SGR2625G NISSAN LATIO 1.5 A '07

CHASSIS: JN1BAAC11Z0003929

S/N	QTY	Items / Nett	U/price	Amount
1	1	Front Bumper Repair		\$507.00 X
2	10	Front Bumper Clip 3 NP	\$6.50	\$65.00 X
3	1	Front R/H Bumper Side Retainer Nec		\$28.30 +
4	1	Front R/H Head Lamp Cracked.		\$407.50 X
5	1	Front R/H Head Lamp Lower Bracket Not Nec		\$47.00 X
6	1	Front R/H Fender Dented.		\$729.40 576
7	1	Front R/H Fender Cowling 3 NP		\$148.60 X
8	8	Front R/H Fender Cowling Clip 1 m	\$6.50	\$52.00 X
9	1	Front R/H Fender Signal Lamp Cracked.		\$66.60 ✓
10	1	Front R/H Tyre Not Nec		\$450.00 X
11	1	Front R/H Rim Lt		\$650.00 380(SN)
12	1	Front R/H Lower Arm Not m		\$207.90 X
13	1	Front R/H Side Mirror Assy Not Nec		\$561.90 X
14	1	Front R/H Door Dented.		\$1,074.20 ✓
15	2	Front R/H Door Hinge 1 piece Best	\$69.10	\$138.20 69.10
16	2	Front R/H Door Frame Sticker Nec	\$36.00	\$72.00 ✓
17	1	Front R/H Door Outer Handle Not m		\$119.10 X
18	1	Front R/H Door Inner Lock Not m		\$239.10 X
19	1	Front R/H Door Inner Trim Board Cracked.		\$915.80 691
20	8	Front R/H Door Inner Trim Board Clip Nec	\$6.50	\$52.00 30
21	1	Front R/H Door Weatherstrip Lt		\$85.40 ✓
22	1	Front R/H Door Window Regulator Not m		\$96.30 X
23	1	Front R/H Door Window Regulator Motor Assy Not m		\$687.40 X
24	1	R/H Door Pillar Trim Board Not m		\$132.20 X
25	1	Rear R/H Door Distorted.		\$1,074.20 ✓
26	2	Rear R/H Door Hinge 1 piece Best	\$69.10	\$138.20 69.10
27	2	Rear R/H Door Frame Sticker Nec	\$30.00	\$60.00 ✓
28	1	Rear R/H Door Outer Handle Not Nec		\$119.10 X

29	1	Rear R/H Door Inner Lock	<i>Al New</i>		\$259.60	X
30	1	Rear R/H Door Inner Trim Board	<i>cracked</i>		\$915.80	695
31	8	Rear R/H Door Inner Trim Board Clip	<i>new</i>	\$6.50	\$52.00	30
32	1	Rear R/H Door Weatherstrip	<i>at</i>		\$84.50	✓
33	1	Rear R/H Door Window Regulator	<i>Al New</i>		\$96.20	X
34	1	Rear R/H Door Window Regulator Motor Assy	<i>Al New</i>		\$687.40	X
35	1	Rear R/H Fender	<i>Repair</i>		\$1,057.60	X
36	10	R/H Rocker Panel Skirt Clip	<i>New</i>	\$6.50	\$65.00	30

5114.60

4603.14

Subtotal:- \$12,142.50

S/N	QTY	Items / Special Nett	U/price	Amount
1	1	Front R/H Knuckle Arm	} NP NA ↓	\$372.20 +
2	1	Front R/H Knuckle Arm Bearing		\$309.10 +
3	1	Front R/H Shock Absorber		\$287.40 +
4	1	Front R/H Drive Shaft		\$922.50 +
5	1	Front Steering Rack		\$1,617.90 x
6	1	Front R/H Door Top Visor	} NA	\$145.10 60
7	1	Rear R/H Door Top Visor		\$145.10 60
8	1	R/H Rocker Panel Skirt Delivered		\$490.00 ✓

Subtotal:- \$4,289.30

610

Labour charges

To remove & refit front R/H door, glass, regulator, motor,
frame sticker, weatherstrip & trim board

~~\$280.00~~ 80

To remove & refit front R/H door, glass, regulator, motor,
frame sticker, weatherstrip & trim board

~~\$280.00~~ 80

To remove & refit front R/H undercarriage

~~\$380.00~~ X

To remove & refit rear windscreen

~~\$120.00~~ X

Gum

~~\$50.00~~ X

To check wheel alignment

~~\$150.00~~ 80

To check wiring

~~\$100.00~~ 30

Tuff kote

~~\$150.00~~ 60

Towing fee

~~\$100.00~~ X

Panel beating

2530

~~\$1,400.00~~ 1000

Spray painting

~~\$1,800.00~~ 1200

Subtotal:- \$4,810.00

Total:- \$21,241.80

total: 7743.14.

1/s: 3.8K (Nett Value)

07 Days.

3.8K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: