

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sgESTIMATE NO. : EST1910-111
DATE : 3-Oct-2019
POLICY NO. : D13MTPV01013181
VEHICLE REG. NO. : SFF2333Z
VEHICLE MAKE : BMW 120ITO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Fender RH	1	\$ 1,500.00	\$ 1,500.00
2	Rear Bumper	1	\$ 1,200.00	\$ 1,200.00
3	Rear Bumper Clip	10	\$ 6.00	\$ 60.00
4	Rear Bumper Retainer RH	1	\$ 60.00	\$ 60.00
Total Spare Parts				\$ 2,820.00
	<u>SPECIAL NETT</u>			
Total Special Nett				\$ -
	<u>LABOUR</u>			
5	Spray painting Rear Bumper and Rear Fender RH	1	\$ 600.00	\$ 600.00
6	Repair and Replace Affected Accident Parts	1	\$ 1,000.00	\$ 800.00
7	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
8	Reset, Check Fault and Resyncing	1	\$ 150.00	\$ 150.00
9	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 1,680.00
Amount Before Excess				\$ 4,500.00
Add GST @ 7%				315.00
Total Amount Payable				\$ 4,815.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Please arrange this vehicle to be surveyed soonest possible. Thank you.