

ASS. REC. BY:

REF:

CS/SPF 19017458/71rd307

Special Instruction:

Surveyor: Tan Kah

## ASSIGNMENT (Office)

From (Person): Hafizul Fathan

of

SPF

Date/Time: 31/10/19 8.57am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SDZ 1669E

Insured:

GBC 963G

at Workshop m/s

Vin's Motor

Tel:

64532121

of

160 Sin Ming Drive #08-09

Policy No:

Claim No:

MEMD/105/009/2019/097

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

2/10/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:30am 31/10/19

Person Contacted:

Raymond

Vehicle IN/OUT

| Date/Time | Action/Instruction (✓) Estimate   |
|-----------|---|
|           | SDZ 1669E - X   |
|           | GBC 963G - X  |
| 11/11/19  | Submit LS \$12,500<br>(Red 10,223.74, 45%)<br>upper range - \$12,500 - \$13,000 |

Do Not Finalise

ASS. REC. BY: Tanjah REF: SPF

### ASSIGNMENT

From: \_\_\_\_\_ Date: 31/10/2019

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDZ1669E

at Workshop m/s: Vin's Motor

of 160 Sin Ming Drive #08-09

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$61K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS insp

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SDZ1669E Yr Regn: 2015 July

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis C.C. 1598

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 59109 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MR053REH104537929

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 25/55R16

R: 4 1/2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 3/10/19 @ 530

'Survey held at Vin's Auto

Des. of Damages Fr Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction  |
|-------------|-----------------------|
|             | Repair limit \$13,000 |

RECEIVED 12 NOV 2019

Do Not Finalise

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) 11/11 - typist

Report Format: \_\_\_\_\_

Lump Sum / LRE: \_\_\_\_\_

Days Of Repair: 10 (2 weekend)

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Insp (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S+RS, St \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL

220

220

**Nivitha (LKK Auto)**

---

**From:** Hafizul Farhan RAHMAT (SPF) <Hafizul\_Farhan\_RAHMAT@spf.gov.sg>  
**Sent:** Thursday, 3 October 2019 8:57 AM  
**To:** Admin-D (LKKAuto); assignments  
**Cc:** Frankie THAY (SPF)  
**Subject:** FW: Accident Involving Vehicles SLZ4633T & SDZ1669E & GBC963G DOA: 02/10/2019  
**Attachments:** SAS2679290.PDF

*Message Classification: Unclassified*

Ref: AEMD/105/009/2019/097

Hi,

Kindly arrange for survey for the vehicle **SDZ1669E**

DOA: 02/10/2019

Location:  
Sin Ming Autocity  
160 Sin Ming Drive #08-09  
Singapore 575722

Tel: 64532121

*Best Regards,*

*Hafizul Farhan Bin Rahmat*  
*AEMD / PLD*  
*Singapore Police Force*  
*DID: (65) 6478 4840 / FAX: (65) 6478 4848*



**WARNING** "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

**From:** Admin @ VAuG <admin@vinsautogroup.com.sg>  
**Sent:** Wednesday, 2 October 2019 5:20 PM  
**To:** Hafizul Farhan RAHMAT (SPF) <Hafizul\_Farhan\_RAHMAT@spf.gov.sg>  
**Cc:** Frankie THAY (SPF) <Frankie\_THAY@spf.gov.sg>  
**Subject:** Accident Involving Vehicles SLZ4633T & SDZ1669E & GBC963G DOA: 02/10/2019

Good afternoon,

Please help us to arrange for survey for the vehicle SDZ1669E

DOA: 02/10/2019

Location:

Sin Ming Autocity

160 Sin Ming Drive #08-09

Singapore 575722

Thanks!

Best Regards

--

**Vin's**  
AUTOMOTIVE GROUP  
#VAuG

Sin Ming AutoCity

160 Sin Ming Drive

Singapore 575722

Showroom/Office: #03-03

Workshops: #08-08/09/10

Tel: 64532121 (4 lines)

Fax: 64599795

Website: [www.vinsautogroup.com.sg](http://www.vinsautogroup.com.sg)

Email: [admin@vinsautogroup.com.sg](mailto:admin@vinsautogroup.com.sg)

Follow us on :



\*\* w.e.f 15th May 2017, we have shifted location! \*\*

\*\* w.e.f 20th November 2017, we have changed our email address! \*\*

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

| Vehicle Owner Particulars     |   |
|-------------------------------|---|
| Owner ID Type:                | Singapore NRIC                          |
| Owner ID:                     | 916J                                    |
| Vehicle Details               |   |
| Vehicle No.:                  | SDZ1669E                                |
| Vehicle to be Exported:       | No                                      |
| Intended Deregistration Date: | 07 Oct 2019                             |
| Vehicle Make:                 | TOYOTA                                  |
| Vehicle Model:                | TOYOTA COROLLA<br>ALTIS 1.6L CVT        |
| Primary Colour:               | White                                   |
| Manufacturing Year:           | 2015                                    |
| Engine No.:                   | 1ZRY204230                              |
| Chassis No.:                  | MR053REH104537929                       |
| Maximum Power Output:         | 90.0 kW (120 bhp)                       |
| Open Market Value:            | \$19,589.00                             |
| Original Registration Date:   | 29 Jul 2015                             |
| First Registration Date:      | 29 Jul 2015                             |
| Transfer Count:               | 0                                       |
| Actual ARF Paid:              | \$19,589.00                             |
| Intended PARF Rebate Details  |   |
| PARF Eligibility:             | Yes                                     |
| PARF Eligibility Expiry Date: | 28 Jul 2025                             |
| PARF Rebate Amount:           | \$14,691.00                             |
| Intended COE Rebate Details   |   |
| COE Expiry Date:              | 28 Jul 2025                             |
| COE Category:                 | A - Car up to 1600cc &<br>97kW (130bhp) |
| COE Period(Years):            | 10                                      |
| QP Paid:                      | \$55,889.00                             |
| COE Rebate Amount:            | \$32,451.00                             |
| <b>Total Rebate Amount:</b>   | <b>\$47,142.00</b>                      |

The information contained herein is correct as at 07 Oct 2019

OK

**FREE VALUATION,**  
Be informed don't get lowballed.

**Completely FREE!**

Find out your car's worth today!



**SGCARMART**  
**QUOTEZ**  
Getting More Money

toyota altis

Price Range

Depreciation

2015

Vehicle Type

**Search**

Advanced Search

Home » Used Cars » Car Buyers Automotive Pte Ltd » Toyota Corolla Altis 1.6A Classic

## Toyota Corolla Altis 1.6A Classic

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

PREMIUM AD

# CAR BUYERS

CLUB

BY CAR BUYERS AUTOMOTIVE PTE LTD

**Price** \$63,800

**Depreciation** \$10,020 /yr  
View models with similar depre

**Reg Date** 29-Jun-2015  
(5yrs 8mths 21days COE left)

**Mileage** 48,900 km (11.4k /yr)

**Manufactured** 2015

**Road Tax** \$742 /yr

**Transmission** Auto

**Dereg Value** \$48,415 as of today (change)

**OMV** \$17,804

**COE** \$67,749

**ARF** \$12,804

**Engine Cap** 1,598 cc

**Power** 90.0 kW (120 bhp)

**Curb Weight** 1,205 kg

**No. of Owners** 1

**Type of Vehicle** Mid-Sized Sedan

### Features

4-Cylinder In-Line 16-Valve DOHC Dual VVT-i Valvematic Coupled With 7-Speed (A) Super CVT-I With Sequential, High Torque Of 160Nm, Traction Control. View specs of the Toyota Corolla Altis (2014)

### Accessories

Build-In Entertainment System, Reverse Camera+Sensors, Leather Seats, Auto Retract Mirrors, Bluetooth Interface, Sports Rim, Auto Climate Aircon.

### Description

Full Agent Serviced Maintain By Borneo Motors, 1 Owner Only, Eco Driving Indicator And Graph System! Very Well Taken Care In Market! Zero Mishap! We Offer High Loan/ In House Financing, All Are Welcome Call Us For Serious Viewing Appointment Now.

### Category

PARF Car, Premium Ad Car

### Status

Available

### Resources


**Car Valuation - Free**  
Find out the market value of your existing car for free. Get started

**Compare**



### Price Chart

### Summary



Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

### Seller Information

Company

Car Buyers Automotive Pte



> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 916J

### Vehicle Details

Vehicle No.: SDZ1669E  
Vehicle to be Exported: No  
Intended Deregistration Date: 04 Oct 2019  
Vehicle Make: TOYOTA  
Vehicle Model: TOYOTA COROLLA ALTIS 1.6L  
CVT

Primary Colour: White  
Manufacturing Year: 2015  
Engine No.: 1ZRY204230  
Chassis No.: MR053REH104537929  
Maximum Power Output: 90.0 kW (120 bhp)  
Open Market Value: \$19,589.00  
Original Registration Date: 29 Jul 2015  
First Registration Date: 29 Jul 2015  
Transfer Count: 0  
Actual ARF Paid: \$19,589.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 28 Jul 2025  
PARF Rebate Amount: \$14,691.00

### Intended COE Rebate Details

COE Expiry Date: 28 Jul 2025  
COE Category: A - Car up to 1600cc & 97kW  
(130bhp)  
COE Period(Years): 10  
QP Paid: \$55,889.00  
COE Rebate Amount: \$32,496.00  
**Total Rebate Amount: \$47,187.00**

The information contained herein is correct as at 03 Oct 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |   |
|----------------------------|---|
| Date Of Report             | 02/10/2019 15:41                              |
| Date Of Accident           | 02/10/2019 12:15                              |
| Exact Location Of Accident | ALONG TELOK BLAGAH RD TWDS WEST COAST HIGHWAY |
| Country/State of Loss      | SINGAPORE                                     |

### DETAILS OF OWN VEHICLE

|  |                               |
|--|-------------------------------|
| Vehicle Registration Number  | SDZ1669E                      |
| <b>Insured/Policyholder</b>  |                               |
| Name Of Registered Owner   | LOH KOK ONN                   |
| NRIC No  | S0025916J                     |
| Email Address  | WENALDLOH@YAHOO.CO.UK         |
| Mobile Phone No  | (LOCAL) +65-93273226          |
| Alternative Phone No   | OFFICE-93273226               |
| <b>Vehicle Particulars</b>   |                               |
| Manufacturer   | TOYOTA                        |
| Model  | TOYOTA COROLLA ALTIS 1.6L CVT |
| Exact Purpose for which vehicle was being used at time of accident           |                               |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO                            |
| If No, Please state action to be taken                                       | THIRD PARTY                   |
| Vehicle Category   | PRIVATE CAR                   |

### Insurance Company

|                           |                                      |
|---------------------------|--------------------------------------|
| Name of Insurance Company | TOKIO MARINE INSURANCE SINGAPORE LTD |
| Type Of Coverage          | COMPREHENSIVE                        |
| Fleet Policy              | NO                                   |
| Policy Number             | MS009079                             |
| Cover Note Number         |                                      |

### Driver

|                      |                       |
|----------------------|-----------------------|
| Name of Driver       | LOH WEI HENG          |
| NRIC No              | S8243805Z             |
| Date Of Birth        | 30/12/1982            |
| Occupation           | INDOOR                |
| Date Of Driving Pass | 22/02/2006            |
| Driving Experience   | 13 YEARS AND 7 MONTHS |
| Gender               | MALE                  |
| Mobile Number        | (LOCAL) +65-93273226  |
| Fax Number           |                       |
| Contact Number       |                       |
| EMail Address        | WENALDLOH@YAHOO.CO.UK |



|   |                                    |
|---|------------------------------------|
| Address   | APT BLK 664A PUNGGOL DRIVE #11-212 |
| Postcode  | 821664                             |
| Was driver an employee of the Insured's Company     | NO                                 |
| If No, Relationship of the Driver with the Insured  | CHILDREN                           |
| Vehicle Registration Number of Driver's Own Vehicle | -                                  |
|   | -                                  |
|   | -                                  |
| Insurance Company of Driver's Own Vehicle           | -                                  |
|   | -                                  |
|   | -                                  |

#### General Information of the Accident

|                    |                 |
|--------------------|-----------------|
| Type Of Accident   | CHAIN COLLISION |
| Weather Conditions | CLEAR           |
| Road Surface       | DRY             |

#### Other Information

|   |    |
|---|----|
| Was any foreign vehicle involved in this accident?  | NO |
| Number of vehicles (including own vehicle) involved in the accident                         | 3  |
| Was any body injured in the Accident?   | NO |
| Was any injured conveyed to hospital by ambulance?  |    |
| Was any other material or property damaged?   | NO |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver)   | 1  |

#### Details of Police Action

|   |    |
|---|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

Same as sketch plan

#### Attachment(s)

|   |     |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | YES |
| Was there any audio recorded?                 | NO  |

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Person's Signature  
Name:  
NRIC/FIN No.:



Sketch Plan Pg. 2

SKETCH PLAN



A: SDZ1669E  
B: GBC963G  
C: SLZ4633T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 2<sup>nd</sup> of October 2019, at about 1215 hrs. I was stationary along Telok Blangah Rd towards West Coast Highway at the second right lane due to the red lights. All of a sudden, I felt an impact from my rear. The impact caused my vehicle to move forward and hit onto the vehicle SLZ4633T. After I alighted from my vehicle, I realized the van GBC963G hit onto my vehicle. It was a chain collision.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Person's Signature  
Name:  
NRIC/FIN No.:





AUTOMOTIVE GROUP

A Sin Ming Autocity,  
160 Sin Ming Drive #03-03  
Singapore 575722  
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)  
F 6459 9795 / 6459 0433  
E admin@vinsautogroup.com.sg  
W www.vinsautogroup.com.sg

Our Ref : TP/102019/4077

Tax Invoice :

Accident date: 2/10/2019

Your Ref : GBC963G

Date : 3/10/2019

SPF Accident Claims Section  
Automotive Engineering & Management Division  
Police Logistic Department  
1 Mount Pleasant Rd  
Block 8 Old Police Academy #02-12  
Singapore 298333

ESTIMATE COST OF REPAIRS TO

Vehicle No.: SDZ1669E

Model: TOYOTA COROLLA ALTIS 1.6L CVT

|        |   |              |         |
|--------|---|--------------|---------|
| 1 pc   | Front bonnet                            | \$ 1,028.10  | Rx      |
| 2 pcs  | Front bonnet hinge @ \$55.90            | \$ 111.80    | Rx      |
| 1 pc   | Front bonnet rubber                     | \$ 27.70     | x       |
| 1 pc   | Front bonnet insulator                  | \$ 253.19    | x       |
| 6 pcs  | Front bonnet insulator clips @ \$3.00   | \$ 18.00     | x       |
| 1 pc   | Front bonnet lock                       | \$ 128.90    | Rx      |
| 1 pc   | Front grille with emblem                | \$ 442.95    | ?       |
| 2 pcs  | Front headlamp @ \$2814.50              | \$ 5,629.00  | RM-? 41 |
| 2 pcs  | Front headlamp HID bulb @ \$32.70       | \$ 65.40     | x       |
| 1 pc   | Front bumper                            | \$ 458.00    | de-     |
| 1 pc   | Front bumper lower centre grille        | \$ 132.90    | ?       |
| 2 pcs  | Front bumper fog lamp @ \$248.20        | \$ 496.40    | x       |
| 2 pcs  | Front bumper fog lamp cover @ \$133.90  | \$ 267.80    | x       |
| 2 pcs  | Front bumper side retainer @ \$         | \$ 55.90     | rx      |
| 1 pc   | Front bumper reinforcement              | \$ 379.20    | ?       |
| 1 pc   | Front bumper under cover                | \$ 133.80    | x       |
| 10 pcs | Front bumper under cover clips @ \$3.00 | \$ 30.00     | x       |
| 1 pc   | Front support panel                     | \$ 788.60    | Rx?     |
| 1 pc   | Front brace panel                       | \$ 120.90    | Rx      |
| 1 pc   | Front air cond condenser                | \$ 1,048.20  | ?       |
| 1 pc   | Front radiator                          | \$ 1,490.20  | x       |
| 1 pc   | Front radiator fan motor                | \$ 362.00    | x       |
|        | Balance C/F                             | \$ 13,468.94 |         |



AUTOMOTIVE GROUP

A Sin Ming Autocity,  
160 Sin Ming Drive #03-03  
Singapore 575722  
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)  
F 6459 9795 / 6459 0433  
E admin@vinsautogroup.com.sg  
W www.vinsautogroup.com.sg

Our Ref : TP/102019/4077

Accident date: 2/10/2019

Your Ref : GBC963G

Tax Invoice :

Date : 3/10/2019

Balance B/F \$ 13,468.94

|    |     |   |    |                       |
|----|-----|---|----|-----------------------|
| 1  | pc  | Front radiator fan cowlng               | \$ | 232.00x               |
| 1  | pc  | Front radiator fan blade                | \$ | 129.30x               |
| 1  | pc  | Rear boot lid                           | \$ | 655.50 bt             |
| 1  | pc  | Rear boot lid emblem                    | \$ | 52.15 ne              |
| 1  | pc  | Rear boot lid "Corolla" name plate      | \$ | 42.35 ne              |
| 1  | pc  | Rear boot lid "Altis" name plate        | \$ | 44.15 ne              |
| 2  | pcs | Rear boot lid reflector @ \$299.80      | \$ | 599.60 cur            |
| 1  | pc  | Rear boot lid outer chrome moulding     | \$ | 301.00 ?              |
| 1  | pc  | Rear boot lid no. plate light           | \$ | 62.90x                |
| 1  | pc  | Rear boot lid reverse camera            | \$ | 350.00x               |
| 2  | pcs | Rear boot lid hinge @ \$60.20           | \$ | 120.40 R              |
| 1  | pc  | Rear boot lid inner trim                | \$ | 349.00x               |
| 15 | pcs | Rear boot lid inner trim clips @ \$3.00 | \$ | 45.00x                |
| 1  | pc  | Rear boot lid lock                      | \$ | 339.00 bt             |
| 1  | pc  | Rear boot lid rubber                    | \$ | 166.40 fu             |
| 2  | pcs | Rear tail lamp @ \$301.60               | \$ | 603.20 cur            |
| 2  | pcs | Rear tail lamp lower bracket @ \$83.60  | \$ | 167.20 de             |
| 1  | pc  | Rear bumper                             | \$ | 482.00 de             |
| 2  | pcs | Rear bumper reverse sensor @ \$170.00   | \$ | 340.00 Zoomer         |
| 2  | pcs | Rear bumper reflector @ \$56.90         | \$ | 113.80x               |
| 1  | pc  | Rear bumper side retainer               | \$ | 92.33 ne              |
| 1  | pc  | Rear bumper reinforcement               | \$ | 301.60 bt             |
| 2  | pcs | Rear bumper inner shield @ \$66.90      | \$ | 133.80x               |
| 1  | pc  | Rear end panel                          | \$ | 581.20 bt             |
| 1  | pc  | Rear end panel top trim                 | \$ | 229.40 de             |
| 2  | pcs | Rear fender @ \$1028.00                 | \$ | 2,056.00 LH-buc, RH-X |
| 2  | pcs | Rear fender inner shield @ \$108.20     | \$ | 216.40 ?              |
|    |     | Balance C/F                             | \$ | 22,274.62             |

# Vin's

AUTOMOTIVE GROUP

A Sin Ming Autocity,  
160 Sin Ming Drive #03-03  
Singapore 575722  
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)  
F 6459 9795 / 6459 0433  
E admin@vinsautogroup.com.sg  
W www.vinsautogroup.com.sg

Our Ref : TP/102019/4077  
Accident date: 2/10/2019  
Your Ref : GBC963G

Tax Invoice :

Date : 3/10/2019

Balance B/F \$ 22,274.62

|           |   |   |
|-----------|---|---|
| 20 pcs    | Rear fender inner shield clips @ \$4.00 | \$ 80.00 <sup>40<sup>c</sup></sup> <i>neu</i> |
| 1 pc      | Rear fender inner trim                  | \$ 355.20 <sup>?</sup>                        |
| 20 pcs    | Rear fender inner trim clips @ \$3.10   | \$ 62.00 <sup>?</sup>                         |
| 1 pc      | Spare tyre panel                        | \$ 702.93 <sup>Rx</sup>                       |
| 1 pc      | Spare tyre top cover                    | \$ 254.90 <sup>neu</sup>                      |
| 1 pc      | Exhaust sileneer                        | \$ 782.00 <sup>? photo</sup>                  |
|           |   | <u>\$ 24,511.65</u>                           |
| Less: 25% |   | \$ (6,127.91)                                 |
|           |   | <u>\$ 18,383.74</u>                           |

|      |                          |                           |
|------|--------------------------|---------------------------|
| 1 pc | Front no. plate          | \$ 40.00 <sup>Nbt</sup>   |
| 1 pc | Rear windsreen glass gum | \$ 60.00 <sup>N neu</sup> |
| 1 pc | Rear no. plate           | \$ 40.00 <sup>Nbt</sup>   |

|  |                             |
|--|-----------------------------|
| To remove and refix rear windscreen              | \$ 150.00 <sup>120</sup>    |
| To remove and refix petrol tank                  | \$ 150.00 <sup>x</sup>      |
| To remove and refix seat cushion and roof lining | \$ 180.00 <sup>60</sup>     |
| To refill air cond gas                           | \$ 120.00 <sup>100?</sup>   |
| To repair rear and front damages                 | \$ 1,800.00 <sup>1400</sup> |
| To spray painting (Pearl)                        | \$ 1,800.00 <sup>1600</sup> |
|  | <u>\$ 22,723.74</u>         |

VIN'S MOTOR PTE LTD



Tanfer 97495749  
WP  
3/10/19 530

Residing before repair.  
sure the auto. work  
10 days



AUTOMOTIVE GROUP

Sin Ming Autocity,  
160 Sin Ming Drive #03-03  
Singapore 575722  
6453 2121 (4 lines) / 6458 1111 (24 hrs)  
6459 9795 / 6459 0433  
admin@vinsautogroup.com.sg  
www.vinsautogroup.com.sg

Our Ref : TP/102019/4077

Accident date: 2/10/2019

Your Ref : GBC963G

Tax Invoice :

Date : 3/10/2019

SPF Accident Claims Section  
Automotive Engineering & Management Division  
Police Logistic Department  
1 Mount Pleasant Rd  
Block 8 Old Police Academy #02-12  
Singapore 298333

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

### ESTIMATE COST OF REPAIRS TO

Vehicle No. : SDZ1669E

Model : TOYOTA COROLLA ALTIS 1.6L CVT

|        |  |              |                    |
|--------|--|--------------|--------------------|
| 1 pc   | Front bonnet                                 | \$ 1,028.10  | Rx                 |
| 2 pcs  | Front bonnet hinge @ \$55.90                 | \$ 111.80    | Rx                 |
| 1 pc   | Front bonnet rubber                          | \$ 27.70     | x un               |
| 1 pc   | Front bonnet insulator                       | \$ 253.19    | x un               |
| 6 pcs  | Front bonnet insulator clips @ \$3.00        | \$ 18.00     | x un               |
| 1 pc   | Front bonnet lock                            | \$ 128.90    | Rx                 |
| 1 pc   | Front grille with emblem <i>cm</i>           | \$ 442.95    | ? /                |
| 2 pcs  | Front headlamp @ \$2814.50 <i>cm 1890.40</i> | \$ 5,629.00  | LH-cm, RH-? 5780.5 |
| 2 pcs  | Front headlamp HID bulb @ \$32.70            | \$ 65.40     | x un               |
| 1 pc   | Front bumper                                 | \$ 458.00    | de                 |
| 1 pc   | Front bumper lower centre grille <i>cm</i>   | \$ 132.90    | ? /                |
| 2 pcs  | Front bumper fog lamp @ \$248.20             | \$ 496.40    | x un               |
| 2 pcs  | Front bumper fog lamp cover @ \$133.90       | \$ 267.80    | x un               |
| 2 pcs  | Front bumper side retainer @ \$              | \$ 55.90     | un                 |
| 1 pc   | Front bumper reinforcement <i>bt</i>         | \$ 379.20    | ? /                |
| 1 pc   | Front bumper under cover                     | \$ 133.80    | x un               |
| 10 pcs | Front bumper under cover clips @ \$3.00      | \$ 30.00     | x un               |
| 1 pc   | Front support panel <i>bt</i>                | \$ 788.60    | Rx ? /             |
| 1 pc   | Front brace panel                            | \$ 120.90    | Rx                 |
| 1 pc   | Front air cond condenser <i>bt</i>           | \$ 1,048.20  | ? /                |
| 1 pc   | Front radiator <i>bt</i>                     | \$ 1,490.20  | x                  |
| 1 pc   | Front radiator fan motor                     | \$ 362.00    | x un               |
|        | Balance C/F                                  | \$ 13,468.94 |                    |



AUTOMOTIVE GROUP

Sin Ming Autocity,  
160 Sin Ming Drive #03-03  
Singapore 575722

6453 2121 (4 lines) / 6458 1111 (24 hrs)

6459 9795 / 6459 0433

admin@vinsautogroup.com.sg

www.vinsautogroup.com.sg

Our Ref : TP/102019/4077

Accident date: 2/10/2019

Your Ref : GBC963G

Tax Invoice :

Date : 3/10/2019

Balance B/F

\$ 13,468.94

|        |   |    |           |                  |
|--------|---|----|-----------|------------------|
| 1 pc   | Front radiator fan cowlng                       | \$ | 232.00    | x nn             |
| 1 pc   | Front radiator fan blade                        | \$ | 129.30    | x nn             |
| 1 pc   | Rear boot lid                                   | \$ | 655.50    | bt               |
| 1 pc   | Rear boot lid emblem                            | \$ | 52.15     | nn               |
| 1 pc   | Rear boot lid "Corolla" name plate              | \$ | 42.35     | nn               |
| 1 pc   | Rear boot lid "Altis" name plate                | \$ | 44.15     | nn               |
| 2 pcs  | Rear boot lid reflector @ \$299.80              | \$ | 599.60    | nn               |
| 1 pc   | Rear boot lid outer chrome moulding             | \$ | 301.00    | ?/               |
| 1 pc   | Rear boot lid no. plate light                   | \$ | 62.90     | x nn             |
| 1 pc   | Rear boot lid reverse camera ?                  | \$ | 350.00    | x nn             |
| 2 pcs  | Rear boot lid hinge @ \$60.20                   | \$ | 120.40    | nn               |
| 1 pc   | Rear boot lid inner trim                        | \$ | 349.00    | x nn             |
| 15 pcs | Rear boot lid inner trim clips @ \$3.00         | \$ | 45.00     | x nn             |
| 1 pc   | Rear boot lid lock                              | \$ | 339.00    | bt               |
| 1 pc   | Rear boot lid rubber                            | \$ | 166.40    | nn               |
| 2 pcs  | Rear tail lamp @ \$301.60                       | \$ | 603.20    | nn               |
| 2 pcs  | Rear tail lamp lower bracket @ \$83.60          | \$ | 167.20    | nn               |
| 1 pc   | Rear bumper                                     | \$ | 482.00    | nn               |
| 2 pcs  | Rear bumper reverse sensor @ \$170.00           | \$ | 340.00    | 200mm            |
| 2 pcs  | Rear bumper reflector @ \$56.90 LH 3u / RH-X nn | \$ | 113.80    | x 56.90          |
| 1 pc   | Rear bumper side retainer                       | \$ | 92.33     | nn               |
| 1 pc   | Rear bumper reinforcement                       | \$ | 301.60    | bt               |
| 2 pcs  | Rear bumper inner shield @ \$66.90              | \$ | 133.80    | x nn             |
| 1 pc   | Rear end panel                                  | \$ | 581.20    | bt               |
| 1 pc   | Rear end panel top trim                         | \$ | 229.40    | nn               |
| 2 pcs  | Rear fender @ \$1028.00                         | \$ | 2,056.00  | LH-bucv, RH-X nn |
| 2 pcs  | Rear fender inner shield @ \$108.20             | \$ | 216.40    | ?/               |
|        | Balance C/F                                     | \$ | 22,274.62 |                  |



# Vin's

AUTOMOTIVE GROUP

Sin Ming Autocity,  
160 Sin Ming Drive #03-03  
Singapore 575722

6453 2121 (4 lines) / 6458 1111 (24 hrs)

6459 9795 / 6459 0433

admin@vinsautogroup.com.sg

www.vinsautogroup.com.sg

Our Ref : TP/102019/4077

Accident date: 2/10/2019

Your Ref : GBC963G

Tax Invoice :

Date : 3/10/2019

Balance B/F

\$ 22,274.62

20 pcs Rear fender inner shield clips @ \$4.00

\$ 80.00 <sup>40</sup> *ner*

1 pc Rear fender inner trim *cut*

\$ 355.20 <sup>?</sup> *ner*

20 pcs Rear fender inner trim clips @ \$3.10 *ner*

\$ 62.00 <sup>?</sup> *ner*

1 pc Spare tyre panel

\$ 702.93 *Rx*

1 pc Spare tyre top cover

\$ 254.90 *ner*

1 pc Exhaust silencer *bt*

\$ 782.00 <sup>?</sup> *photo*

\$ 24,511.65

16229.23

Less: 25%

\$ (6,127.91)

12171.92

\$ 18,383.74

1 pc Front no. plate

\$ 40.00 *Nbt*

1 pc Rear windsreen glass gum

\$ 60.00 *Nner*

1 pc Rear no. plate

\$ 40.00 *Nbt* 140

To remove and refix rear windscreen

\$ 150.00 120

To remove and refix petrol tank

\$ 150.00 x

To remove and refix seat cushion and roof lining

\$ 180.00 60

To refill air cond gas

\$ 120.00 100

To repair rear and front damages

\$ 1,800.00 1400

To spray painting (Pearl)

\$ 1,800.00 1600

\$ 22,723.74

3280

VIN'S MOTOR PTE LTD



Taufik 97495749 / 67418434

WP  
3/10/19 530

Resolving before repair.  
sure to handle with

10 days

12171.92  
140

3280  
15591.92

4/5/12500  
10 days

## **Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Friday, 8 November 2019 12:02 PM  
**To:** 'Admin @ VAuG'; SUR  
**Subject:** RE: SDZ1669E - SPF TP - DOA: 02/10/2019 - Cost of Repair  
**Attachments:** MARKING.pdf

Dear Raymond,

WITHOUT PREJUDICE

For claims against Singapore Police Force, we have instruction not to finalise any COR.

However, please be informed that we will submit our recommendation as per our surveyor marking in the estimate.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Thursday, 24 October 2019 7:46 AM  
**To:** Admin @ VAuG <admin@vinsautogroup.com.sg>; SUR <sur@lkkauto.com>  
**Subject:** RE: SDZ1669E - SPF TP - DOA: 02/10/2019 - Cost of Repair

Dear Raymond,

Surveyor is on leave.

Will revert to you.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Admin @ VAuG <admin@vinsautogroup.com.sg>  
**Sent:** Wednesday, 23 October 2019 1:35 PM

To: SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>

Subject: SDZ1669E - SPF TP - DOA: 02/10/2019 - Cost of Repair

Good afternoon,

Can we confirm the cost of repair?

Thanks!

Best regards

Raymond Teo



Sin Ming AutoCity  
160 Sin Ming Drive  
Singapore 575722  
Showroom/Office: #03-03  
Workshops: #08-08/09/10  
Tel: 64532121 (4 lines)  
Fax: 64599795  
Website: [www.vinsautogroup.com.sg](http://www.vinsautogroup.com.sg)  
Email: [admin@vinsautogroup.com.sg](mailto:admin@vinsautogroup.com.sg)

Follow us on :



\*\* w.e.f 15th May 2017, we have shifted location! \*\*

\*\* w.e.f 20th November 2017, we have changed our email address! \*\*



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |                |                              |                        |   |
|--|----------------|------------------------------|------------------------|---|
| AUTOMOTIVE ENGINEERING & MGT DIVISION  |                | Ref : CS/SPF19017458/T1vd3e2 |                        |   |
| ACCIDENT CLAIM SECTION (SPORE POLICE<br>FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD<br>POLICE ACADEMY SINGAPORE 298333<br>ATTN : HAFIZUL FARHAN |                | Date : 25-11-2019            |                        |  |
|  |                | Code : SPF                   |                        |   |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |                |                              |                        |   |
|  | Insured Veh.   | GBC 963G                     | Veh. Inspected         | SDZ 1669E   |
|  | Policy No.     |                              | Coverage (\$)          | 0.00  |
|  | Claim No.      | AEMD/105/009/2019/097        | Excess (\$)            | 0.00  |
|  | Assign From    | HAFIZUL FARHAN               | Assign Date            | 03/10/2019  |
| <b>2. Vehicle Particulars &amp; Condition</b>  |                |                              |                        |   |
|  | Make & Model   | TOYOTA ALTIS                 | c.c                    | 1598  |
|  | Engine No.     | HIDDEN                       | Year of Reg.           | 2015  |
|  | Chassis No.    | MR053REH104537929            | Colour                 | WHITE   |
|  | Odometer       | 59109                        | Steering               | IN ORDER  |
|  | Brakes         | IN ORDER                     | Modification           | SPORTS RIM  |
|  | General        | GOOD                         |                        |   |
| <b>3. Conditions of Tyres</b>  |                |                              |                        |   |
|  |                | Size                         | Make                   | Balance   |
|  | R/H Front Tyre | 205/55 R16                   | YOKOHAMA               | 6 mm  |
|  | L/H Front Tyre | 205/55 R16                   | YOKOHAMA               | 6 mm  |
|  | R/H Rear Tyre  | 205/55 R16                   | YOKOHAMA               | 6 mm  |
|  | L/H Rear Tyre  | 205/55 R16                   | YOKOHAMA               | 6 mm  |
| <b>4. Description of Damages</b>   |                |                              |                        |   |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.<br>DAMAGES SEE DETAILS.   |                |                              |                        |   |
| <b>5. General Information</b>  |                |                              |                        |   |
|  | Accident Date  | 02/10/2019                   | Inspection Date        | 03/10/2019  |
|  | Survey held at | 160 SIN MING DRIVE #08-09    |                        |   |
|  | Repairer       | VIN'S MOTOR PTE LTD          |                        |   |
| <b>5a. Remarks</b>   |                |                              |                        |   |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.  |                |                              |                        |   |
| <b>5b. Estimate Days of Repair</b>   |                |                              |                        |   |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |                |                              | <b>10 Working Days</b> |   |



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDZ 1669E

| Qty | Description of Parts                   | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|----------------------|---------------------------|-------------------|
|     | <b>REPLACEMENT OF PARTS</b>            |                      |                           |                   |
| 1   | FRONT BONNET                           | TO REPAIR SEE LABOUR | 1,028.10                  | -                 |
| 2   | FRONT BONNET HINGE @\$55.90            | TO REPAIR SEE LABOUR | 111.80                    | -                 |
| 1   | FRONT BONNET RUBBER                    | NOT NECESSARY        | 27.70                     | -                 |
| 1   | FRONT BONNET INSULATOR                 | NOT NECESSARY        | 253.19                    | -                 |
| 6   | FRONT BONNET INSULATOR CLIPS @\$3.00   | NOT NECESSARY        | 18.00                     | -                 |
| 1   | FRONT BONNET LOCK                      | TO REPAIR SEE LABOUR | 128.90                    | -                 |
| 1   | FRONT GRILLE WITH EMBLEM               | CRACKED              | 442.95                    | 442.95            |
| 2   | FRONT HEADLAMP @\$2814.50              | CRACKED              | 5,629.00                  | 3,780.80          |
| 2   | FRONT HEADLAMP HID BULB @\$32.70       | NOT NECESSARY        | 65.40                     | -                 |
| 1   | FRONT BUMPER                           | DEFORMED             | 458.00                    | 458.00            |
| 1   | FRONT BUMPER LOWER CENTRE GRILLE       | CRACKED              | 132.90                    | 132.90            |
| 2   | FRONT BUMPER FOG LAMP @\$248.20        | NOT NECESSARY        | 496.40                    | -                 |
| 2   | FRONT BUMPER FOG LAMP COVER @\$133.90  | NOT NECESSARY        | 267.80                    | -                 |
| 2   | FRONT BUMPER SIDE RETAINER             | NECESSARY            | 55.90                     | 55.90             |
| 1   | FRONT BUMPER REINFORCEMENT             | BENT                 | 379.20                    | 379.20            |
| 1   | FRONT BUMPER UNDER COVER               | NOT NECESSARY        | 133.80                    | -                 |
| 10  | FRONT BUMPER UNDER COVER CLIPS @\$3.00 | NOT NECESSARY        | 30.00                     | -                 |
| 1   | FRONT SUPPORT PANEL                    | BENT                 | 788.60                    | 788.60            |
| 1   | FRONT BRACE PANEL                      | TO REPAIR SEE LABOUR | 120.90                    | -                 |
| 1   | FRONT AIR COND CONDENSER               | BENT                 | 1,048.20                  | 1,048.20          |
| 1   | FRONT RADIATOR                         | BENT                 | 1,490.20                  | 1,490.20          |
| 1   | FRONT RADIATOR FAN MOTOR               | NOT NECESSARY        | 362.00                    | -                 |
| 1   | FRONT RADIATOR FAN COWLING             | NOT NECESSARY        | 232.00                    | -                 |
| 1   | FRONT RADIATOR FAN BLADE               | NOT NECESSARY        | 129.30                    | -                 |
| 1   | REAR BOOT LID                          | BENT                 | 655.50                    | 655.50            |
| 1   | REAR BOOT LID EMBLEM                   | NECESSARY            | 52.15                     | 52.15             |
| 1   | REAR BOOT LID "COROLLA" NAME PLATE     | NECESSARY            | 42.35                     | 42.35             |
| 1   | REAR BOOT LID "ALTIS" NAME PLATE       | NECESSARY            | 44.15                     | 44.15             |
| 2   | REAR BOOT LID REFLECTOR @\$299.80      | CRACKED              | 599.60                    | 599.60            |
| 1   | REAR BOOT LID OUTER CHROME MOULDING    | CRACKED              | 301.00                    | 301.00            |
| 1   | REAR BOOT LID NO. PLATE LIGHT          | NOT NECESSARY        | 62.90                     | -                 |

Report Ref No. CS/SPF19017458/T1vd3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts                   | Condition                         | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|-----------------------------------|---------------------------|-------------------|
| 1   | REAR BOOT LID REVERSE CAMERA           | NOT NECESSARY                     | 350.00                    | -                 |
| 2   | REAR BOOT LID HINGE @\$60.20           | TO REPAIR SEE LABOUR              | 120.40                    | -                 |
| 1   | REAR BOOT LID INNER TRIM               | NOT NECESSARY                     | 349.00                    | -                 |
| 15  | REAR BOOT LID INNER TRIM CLIPS @\$3.00 | NOT NECESSARY                     | 45.00                     | -                 |
| 1   | REAR BOOT LID LOCK                     | BENT                              | 339.00                    | 339.00            |
| 1   | REAR BOOT LID RUBBER                   | TWISTED                           | 166.40                    | 166.40            |
| 2   | REAR TAIL LAMP @\$301.60               | CRACKED                           | 603.20                    | 603.20            |
| 2   | REAR TAIL LAMP LOWER BRACKET @\$83.60  | DEFORMED                          | 167.20                    | 167.20            |
| 1   | REAR BUMPER                            | DEFORMED                          | 482.00                    | 482.00            |
| 2   | REAR BUMPER REVERSE SENSOR @\$170.00   | NOT WORKING                       | 340.00                    | 200.00            |
| 2   | REAR BUMPER REFLECTOR @\$56.90         | N/S SCRATCHED / O/S NOT NECESSARY | 113.80                    | 56.90             |
| 1   | REAR BUMPER SIDE RETAINER              | NECESSARY                         | 92.33                     | 92.33             |
| 1   | REAR BUMPER REINFORCEMENT              | BENT                              | 301.60                    | 301.60            |
| 2   | REAR BUMPER INNER SHIELD @\$66.90      | NOT NECESSARY                     | 133.80                    | -                 |
| 1   | REAR END PANEL                         | BENT                              | 581.20                    | 581.20            |
| 1   | REAR END PANEL TOP TRIM                | DEFORMED                          | 229.40                    | 229.40            |
| 2   | REAR FENDER @\$1028.00                 | N/S BUCKLED / O/S NOT NECESSARY   | 2,056.00                  | 1,028.00          |
| 2   | REAR FENDER INNER SHIELD @\$108.20     | CUT                               | 216.40                    | 216.40            |
| 20  | REAR FENDER INNER SHIELD CLIPS @\$4.00 | NECESSARY                         | 80.00                     | 40.00             |
| 1   | REAR FENDER INNER TRIM                 | CUT                               | 355.20                    | 355.20            |
| 20  | REAR FENDER INNER TRIM CLIPS @\$3.10   | NECESSARY                         | 62.00                     | 62.00             |
| 1   | SPARE TYRE PANEL                       | TO REPAIR SEE LABOUR              | 702.93                    | -                 |
| 1   | SPARE TYRE TOP COVER                   | CRACKED                           | 254.90                    | 254.90            |
| 1   | EXHAUST SILENCER                       | BENT                              | 782.00                    | 782.00            |
|     | LESS 25% DISCOUNT                      |                                   | -6,127.91                 | -4,057.31         |
|     |  |                                   | 18,383.74                 | 12,171.92         |
|     | <b><u>SPECIAL NETT ITEMS</u></b>       |                                   |                           |                   |
| 1   | FRONT NO. PLATE (SN)                   | BENT                              | 40.00                     | 40.00             |
| 1   | REAR WINDSCREEN GLASS GUM (SN)         | NECESSARY                         | 60.00                     | 60.00             |
| 1   | REAR NO. PLATE (SN)                    | BENT                              | 40.00                     | 40.00             |
|     |  |                                   | 140.00                    | 140.00            |

Report Ref No. CS/SPF19017458/T1vd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty   | Description of Parts   | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|--|---------------|---------------------------|-------------------|
|   | <b>LABOUR</b>  |               |                           |                   |
|   | TO REMOVE AND REFIX REAR WINDSCREEN.   | NOT NECESSARY | 150.00                    | 120.00            |
|   | TO REMOVE AND REFIX PETROL TANK.   |               | 150.00                    | -                 |
|   | TO REMOVE AND REFIX SEAT CUSHION AND ROOF LINING.  |               | 180.00                    | 60.00             |
|   | TO REFILL AIR COND GAS.  |               | 120.00                    | 100.00            |
|   | TO REPAIR REAR AND FRONT DAMAGES. INCLUSIVE OF THE REPAIR OF FRONT BONNET, FRONT BONNET HINGE, FRONT BONNET LOCK, FRONT BRACE PANEL, REAR BOOT LID HINGE AND SPARE TYRE PANEL. |               | 1,800.00                  | 1,400.00          |
|   | TO SPRAY PAINTING (PEARL).   |               | 1,800.00                  | 1,600.00          |
|   |  |               | 4,200.00                  | 3,280.00          |
|   | <b>GRAND TOTAL</b>   |               | <b>22,723.74</b>          | <b>15,591.92</b>  |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |  |               |                           | <b>12,500.00</b>  |

Report Ref No. CS/SPF19017458/T1vd3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$12,500-\$13,000

RECOMMENDED REPAIR DAYS : 10  
WEEKEND : 2  
TOTAL DAYS : 12

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.