

22/03/2002

ASS. REC. BY:

REF:

CS/SPF/19017460/71sd321

Special Instruction:

Surveyor 7/10/19

ASSIGNMENT (Office)

From (Person): Hafizul Farhan

of

SPF

Date/Time: 31/10/19 @ 9:59am

Estimated Cost:

Bill to:

OD (TP) WS+TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLZ 4633T

Insured:

SDZ 1669E

at Workshop m/s

Vint Motor

Tel:

6453 2121

of

160 Sin Ming Drive # 08-09

Policy No:

Claim No:

AEND/105/009/2019/097

Sum Insured:

Excess:

Make of Veh.

D.O.A.

02/10/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:30am @ 31/10/19

Person Contacted:

Reymund

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate	
	SLZ 4633T - CVI / VAL 18015 3.34 / BS	DOA: 21/5/2018
	SDZ 1669E - CS/SPF/19017458/71W3	DOA: 2/10/2019

Do Not Finalise

No
photo
upload.
7/10

ASS. REC. BY:

Taufher

REF: SPF

ASSIGNMENT

From

Date:

3/10/19

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SL2 4633T

at Workshop m/s

Vin's Motor

of

160 Sin Ming Drive #08-09

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

\$ 89K

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Imp

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SL24633T

Yr Regn:

2018 May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Freed Hybrid c.c 1496

Colour:

Green

A/C: Insured / Std / NI / NA

Sp. Reading

13413

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

9B71064054

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Vin's Auto. 3/10/19P547

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$6,000/- - \$7,000/-

Range - \$5,000/- - \$6,000/-

\$6,450/-

RECEIVED 12 NOV 2019

12/11/19

Submit HS \$5,850/- @ 6 days

(\$6,174.32 Red - 49%)

Recommended repair days: 6

Weekends: 2

Total Days: 8

Do Not Final!

12/11/2019

Date/Time, File Pass to?

12/11/19

1)

Typ: 4

Date/Time, File Return to?

2)



: Prel. Report



: Final Report

Days Of Repair:

6

Resurvey No. of Trip:

2

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Insp (\$)



: Weekend (\$)

Survey Fee:

220

Transportation:

3 + RS \$1

Photos

Others

TOTAL

220

Report Format:

Lump Sum / 10% / 20%

\$6,450/- 45

Nivitha (LKK Auto)

From: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>
Sent: Thursday, 3 October 2019 9:59 AM
To: Admin-D (LKKAuto); assignments
Cc: Frankie THAY (SPF)
Subject: FW: Accident Involving Vehicles SLZ4633T & SDZ1669E & GBC963G DOA: 02/10/2019
Attachments: SAS2679290.PDF

Message Classification: Unclassified

Ref: AEMD/105/009/2019/097

Hi,

Kindly arrange for survey for the vehicle **SLZ4633T**

DOA: 02/10/2019

Location:
Sin Ming Autocity
160 Sin Ming Drive #08-09
Singapore 575722

Tel: 64532121

Best Regards,

Hafizul Farhan Bin Rahmat
AEMD / PLD
Singapore Police Force
DID: (65) 6478 4840 | FAX: (65) 6478 4848



WARNING "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Admin @ VAuG <admin@vinsautogroup.com.sg>
Sent: Wednesday, 2 October 2019 5:20 PM
To: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>
Cc: Frankie THAY (SPF) <Frankie_THAY@spf.gov.sg>
Subject: Accident Involving Vehicles SLZ4633T & SDZ1669E & GBC963G DOA: 02/10/2019

Good afternoon,

Please help us to arrange for survey for the vehicle SDZ1669E

DOA: 02/10/2019

Location:

Sin Ming Autocity
160 Sin Ming Drive #08-09
Singapore 575722

Thanks!


Best Regards

--



Sin Ming AutoCity
160 Sin Ming Drive
Singapore 575722
Showroom/Office: #03-03
Workshops: #08-08/09/10
Tel: 64532121 (4 lines)
Fax: 64599795
Website: www.vinsautogroup.com.sg
Email: admin@vinsautogroup.com.sg

Follow us on :



** w.e.f 15th May 2017, we have shifted location! **

** w.e.f 20th November 2017, we have changed our email address! **

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	217B
Vehicle Details	
Vehicle No.:	SLZ4633T
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Oct 2019
Vehicle Make:	HONDA
Vehicle Model:	FREED HYBRID 1.5G AUTO
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	LEB5596426
Chassis No.:	GB71064054
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$25,675.00
Original Registration Date:	04 May 2018
First Registration Date:	04 May 2018
Transfer Count:	0
Actual ARF Paid:	\$17,945.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 May 2028
PARF Rebate Amount:	\$13,458.00
Intended COE Rebate Details	
COE Expiry Date:	03 May 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,322.00
COE Rebate Amount:	\$36,313.00
Total Rebate Amount:	\$49,771.00

The information contained herein is correct as at 03 Oct 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/10/2019 13:19
Date Of Accident	02/10/2019 12:15
Exact Location Of Accident	ALONG TELOK BLAGAH RD TWDS WEST COAST HIGHWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLZ4633T
Insured/Policyholder	
Name Of Registered Owner	HO PECK CHENG KAREN
NRIC No	S7623217B
Email Address	FATFROG1@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-93682445
Alternative Phone No	OFFICE-93682445

Vehicle Particulars

Manufacturer	HONDA
Model	FREED HYBRID-1.5 G (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	LIM KAK WAN
NRIC No	S7817613Z
Date Of Birth	22/06/1978
Occupation	INDOOR
Date Of Driving Pass	04/07/1998
Driving Experience	21 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97462058
Fax Number	
Contact Number	
Email Address	FATFROG1@SINGNET.COM.SG

Address	B/10 JALAN BATU #12-08
Postcode	431010
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Same as sketch plan

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDZ1669E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LOH WEI HENG
NRIC/Passport Number	S8243805Z
Contact Number	93273226
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBC963G
-----------------------------	---------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

GOVERNMENT

Name of Driver

DANIAL

NRIC/Passport Number

S9921437F

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 02nd of October 2019, at about 1215 hrs. I was stationary along Telok Blangah Rd towards West Coast Highway at the second right lane due to the red lights. All of a sudden, I felt an impact from my rear. I realized the vehicle SDZ1669E hit onto my vehicle. After I alighted from my vehicle, I realized the van, hit onto the vehicle SDZ1669E, and the impact caused the vehicle SDZ1669E moved forward and hit onto my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:





AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : TP/102019/4078
Accident date: 2/10/2019
Your Ref : GBC963G

Tax Invoice :
Date : 3/10/2019

SPF Accident Claims Section
Automotive Engineering & Management Division
Police Logistic Department
1 Mount Pleasant Rd
Block 8 Old Police Academy #02-12
Singapore 298333

ESTIMATE COST OF REPAIRS TO

Vehicle No. : SLZ4633T
Model : HONDA FREED HYBRID-1.5 G (A)

1 pc	Rear tail gate	\$ 1,413.70	bt ✓
1 pc	Rear tail gate glass moulding	\$ 120.00	net ✓
2 pcs	Rear tail gate reflector @ \$360.00	\$ 720.00	?
1 pc	Rear tail gate emblem	\$ 32.80	net ✓
1 pc	Rear tail gate "Freed" name plate	\$ 55.00	net ✓
1 pc	Rear tail gate "Hybrid" name plate	\$ 75.00	net ✓
1 pc	Rear tail gate outer chrome moulding	\$ 320.40	net ✓
2 pcs	Rear tail gate no. plate light @ \$38.50	\$ 77.00	*?
1 pc	Rear tail gate reverse camera	\$ 1,100.60	x
1 pc	Rear tail gate inner lock	\$ 157.10	?
1 pc	Rear tail gate inner trimboard	\$ 288.00	*?
2 pcs	Rear tail gate absorber @ \$135.00	\$ 270.00	x
2 pcs	Rear tail gate hinge @ \$50.00	\$ 100.00	x R
1 pc	Rear tail gate wiper motor	\$ 320.00	x
1 pc	Rear tail gate rubber	\$ 168.00	?
2 pcs	Rear tail lamp @ \$580.00	\$ 1,160.00	x
1 pc	Rear bumper	\$ 925.00	de ✓
2 pcs	Rear bumper reflector @ \$42.80	\$ 85.60	x
2 pcs	Rear bumper side retainer @ \$24.90	\$ 49.80	?
1 pc	Rear bumper towing cover	\$ 18.50	x
	Balance C/F	\$ 7,456.50	



AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : TP/102019/4078
Accident date: 2/10/2019
Your Ref : GBC963G

Tax Invoice :

Date : 3/10/2019

Balance B/F \$ 7,456.50

1 pc	Rear end panel	\$ 623.80 ?
1 pc	Rear end panel inner trim	\$ 311.70 ?
2 pcs	Rear fender inner trim @ \$511.20	\$ 1,022.40 x
1 pc	Rear tool box	\$ 481.90 ?
1 pc	Rear exhaust silencer	\$ 588.00 Ry
1 pc	Rear keyless sensor	\$ 85.00 ?
		<u>\$ 10,569.30</u>
Less: 20%		<u>\$ (2,113.86)</u>
		<u>\$ 8,455.44</u>

1 set	Rear bumper reverse sensor	\$ 280.00 N 200mm
1 pc	Rear windscreen gum	\$ 60.00 N 1st
1 pc	Rear no. plate	\$ 40.00 N 1st

To remove and refix rear windscreen	\$ 150.00 120.
To repair rear damages	\$ 980.00 600
To spray painting	\$ 980.00 600.

\$ 10,945.44

[Signature]
7/10/19
Taufik 97445744
-wp-

VIN'S MOTOR PTE LTD

[Signature]

3/10/19 @ 545
Resurvey before paint
sure tomorrow
5-6 days



AUTOMOTIVE GROUP

Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722

6453 2121 (4 lines) / 6458 1111 (24 hrs)

6459 9795 / 6459 0433

admin@vinsautogroup.com.sg

www.vinsautogroup.com.sg

Our Ref : TP/102019/4078

Accident date: 2/10/2019

Your Ref : GBC963G

Tax Invoice :

Date : 3/10/2019

SPF Accident Claims Section

Automotive Engineering & Management Division

Police Logistic Department

1 Mount Pleasant Rd

Block 8 Old Police Academy #02-12

Singapore 298333

Rasul
Rui

02/10/19 @ 1530

ESTIMATE COST OF REPAIRS TO

Vehicle No. : SLZ4633T

Model : HONDA FREED HYBRID-1.5 G (A)

1 pc	Rear tail gate	\$	1,413.70 <i>bt ✓ 1100</i>
1 pc	Rear tail gate glass moulding	\$	120.00 <i>net ✓</i>
2 pcs	Rear tail gate reflector @ \$360.00 <i>can ✓</i>	\$	720.00 <i>? can ✓</i>
1 pc	Rear tail gate emblem	\$	32.80 <i>net ✓</i>
1 pc	Rear tail gate "Freed" name plate	\$	55.00 <i>net ✓</i>
1 pc	Rear tail gate "Hybrid" name plate	\$	75.00 <i>net ✓</i>
1 pc	Rear tail gate outer chrome moulding	\$	320.40 <i>net ✓</i>
2 pcs	Rear tail gate no. plate light @ \$38.50 <i>X</i>	\$	77.00 <i>* Xnn.</i>
• 1 pc	Rear tail gate reverse camera <i>cut - ?</i>	\$	1,100.60 <i>X 250 dis ✓</i>
1 pc	Rear tail gate inner lock <i>can ✓</i>	\$	157.10 <i>? can ✓</i>
1 pc	Rear tail gate inner trimboard <i>can ✓</i>	\$	288.00 <i>* ? can ✓</i>
2 pcs	Rear tail gate absorber @ \$135.00	\$	270.00 <i>X un</i>
2 pcs	Rear tail gate hinge @ \$50.00	\$	100.00 <i>X R.</i>
1 pc	Rear tail gate wiper motor	\$	320.00 <i>X un</i>
1 pc	Rear tail gate rubber <i>cut ✓</i>	\$	168.00 <i>? cut ✓</i>
• 2 pcs	Rear tail lamp @ \$580.00 <i>?</i>	580 \$	1,160.00 <i>X LHX, RH-can ✓</i>
1 pc	Rear bumper	\$	925.00 <i>de ✓ 783.70</i>
2 pcs	Rear bumper reflector @ \$42.80	\$	85.60 <i>X nn</i>
2 pcs	Rear bumper side retainer @ \$24.90 <i>as ✓</i>	\$	49.80 <i>? de ✓</i>
1 pc	Rear bumper towing cover	\$	18.50 <i>X nn</i>
	Balance C/F	\$	7,456.50

Vin's

AUTOMOTIVE GROUP

Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722

6453 2121 (4 lines) / 6458 1111 (24 hrs)

6459 9795 / 6459 0433

admin@vinsautogroup.com.sg

www.vinsautogroup.com.sg

Our Ref : TP/102019/4078

Accident date: 2/10/2019

Your Ref : GBC963G

Tax Invoice :

Date : 3/10/2019

Balance B/F

\$ 7,456.50

- 1 pc Rear end panel *bt*
- 1 pc Rear end panel inner trim *del*
- 2 pcs Rear fender inner trim @ \$511.20 ?
- 1 pc Rear tool box *X*
- 1 pc Rear exhaust silencer
- 1 pc Rear keyless sensor *X*

\$ 623.80 *? bt 488.90*
\$ 311.70 *? del 182.40*
511.20 \$ 1,022.40 *x LH-Rm, RH-del*
\$ 481.90 *X nh*
\$ 588.00 *Ry*
\$ 85.00 *? X nh*
\$ 10,569.30 *5885.30*
\$ (2,113.86) *4708.24*
\$ 8,455.44

Less: 20%

- 1 set Rear bumper reverse sensor
- 1 pc Rear windscreen gum
- 1 pc Rear no. plate

\$ 280.00 *N 200mm*
\$ 60.00 *N nel*
\$ 40.00 *N bt*
300.

To remove and refix rear windscreen

\$ 150.00 *120.*

To repair rear damages

\$ 980.00 *600*

To spray painting

\$ 980.00 *600.*

12,624.32 \$ 10,945.44 *1320.*

Tauplin 97445744/67418434
-wp

VIN'S MOTOR PTE LTD

LIK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

3/10/19 545
Resurvey before paint
surv@vinsauto.com
5-6 days



AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : TP/102019/4078

Accident date: 2/10/2019

Your Ref : GBC963G

Tax Invoice :

Date : 7/10/2019

SPF Accident Claims Section
Automotive Engineering & Management Division
Police Logistic Department
1 Mount Pleasant Rd
Block 8 Old Police Academy #02-12
Singapore 298333

SUPPLEMENTARY COST OF REPAIRS TO

Vehicle No. : SLZ4633T

Model : HONDA FREED HYBRID-1.5 G (A)

- 1 pc Rear floor panel *64-*
1 pc Rear carpet *de-*
2 pcs Rear end panel bracket @ \$46.30 *64-*

Less: 20%

\$ 1,056.00	<i>856.</i>
\$ 950.00	<i>300 700</i>
\$ 92.60	
\$ 2,098.60	
\$ (419.72)	<i>1248.60</i>
<u>\$ 1,678.88</u>	<i>998.88</i>

VIN'S MOTOR PTE LTD

4708.24

300

1320

998.88

7327.12

458550#
6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

I acknowledge by Repairer



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF19017460/T1sd3e2	
ACCIDENT CLAIM SECTION SPORE POLICE FORCE) MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333 ATTN : HAFIZUL FARHAN		Date : 25-11-2019	
		Code : SPF	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SDZ 1669E	Veh. Inspected
			SLZ 4633T
	Policy No.		Coverage (\$)
			0.00
	Claim No.	AEMD/105/009/2019/097	Excess (\$)
			0.00
	Assign From	HAFIZUL FARHAN	Assign Date
			03/10/2019
2. Vehicle Particulars & Condition			
	Make & Model	HONDA FREED HYBRID	c.c
			1496
	Engine No.	HIDDEN	Year of Reg.
			2018
	Chassis No.	GB71064054	Colour
			GREY
	Odometer	13413	Steering
			IN ORDER
	Brakes	IN ORDER	Modification
			SPORTS RIM
	General	GOOD	
3. Conditions of Tyres			
		Size	Make
			Balance
	R/H Front Tyre	185/65 R15	DUNLOP
			6 mm
	L/H Front Tyre	185/65 R15	DUNLOP
			6 mm
	R/H Rear Tyre	185/65 R15	DUNLOP
			6 mm
	L/H Rear Tyre	185/65 R15	DUNLOP
			6 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.		
	DAMAGES SEE DETAILS.		
5. General Information			
	Accident Date	02/10/2019	Inspection Date
			03/10/2019
	Survey held at	160 SIN MING DRIVE #08-09	
	Repairer	VIN'S MOTOR PTE LTD	
5a. Remarks			
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.		
	B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 4633T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TAIL GATE	BENT	1,413.70	1,100.00
1	REAR TAIL GATE GLASS MOULDING	NECESSARY	120.00	120.00
2	REAR TAIL GATE REFLECTOR @\$360.00	CRACKED	720.00	720.00
1	REAR TAIL GATE EMBLEM	NECESSARY	32.80	32.80
1	REAR TAIL GATE "FREED" NAME PLATE	NECESSARY	55.00	55.00
1	REAR TAIL GATE "HYBRID" NAME PLATE	NECESSARY	75.00	75.00
1	REAR TAIL GATE OUTER CHROME MOULDING	CUT	320.40	320.40
2	REAR TAIL GATE NO. PLATE LIGHT @\$38.50	NOT NECESSARY	77.00	-
1	REAR TAIL GATE REVERSE CAMERA	CUT / DISTORTED	1,100.60	250.00
1	REAR TAIL GATE INNER LOCK	CRACKED	157.10	157.10
1	REAR TAIL GATE INNER TRIMBOARD	CRACKED	288.00	288.00
2	REAR TAIL GATE ABSORBER @\$135.00	NOT NECESSARY	270.00	-
2	REAR TAIL GATE HINGE @50.00	TO REPAIR SEE LABOUR	100.00	-
1	REAR TAIL GATE WIPER MOTOR	NOT NECESSARY	320.00	-
1	REAR TAIL GATE RUBBER	CUT	168.00	168.00
2	REAR TAIL LAMP @\$580.00	CRACKED	1,160.00	1,160.00
1	REAR BUMPER	DEFORMED	925.00	783.70
2	REAR BUMPER REFLECTOR @\$42.80	NOT NECESSARY	85.60	-
2	REAR BUMPER SIDE RETAINER @\$24.90	DEFORMED	49.80	49.80
1	REAR BUMPER TOWING COVER	NOT NECESSARY	18.50	-
1	REAR END PANEL	BENT	623.80	488.90
1	REAR END PANEL INNER TRIM	DEFORMED	311.70	182.40
2	REAR FENDER INNER TRIM @\$511.20	N/S NOT NECESSARY / O/S DEFORMED	1,022.40	511.20
1	REAR TOOL BOX	NOT NECESSARY	481.90	-
1	REAR EXHAUST SILENCER	TO REPAIR SEE LABOUR	588.00	-
1	REAR KEYLESS SENSOR	NOT NECESSARY	85.00	-
1	REAR FLOOR PANEL (ADDITIONAL)	BENT	1,056.00	856.00
1	REAR CARPET (ADDITIONAL)	DEFORMED	950.00	700.00
2	REAR END PANEL BRACKET @\$46.30 (ADDITIONAL)	BENT	92.60	92.60
	LESS 20% DISCOUNT		-2,533.58	-1,622.18
			10,134.32	6,488.72

Report Ref No. CS/SPF19017460/T1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER REVERSE SENSOR (SN)	NOT WORKING	280.00	200.00
1	REAR WINDSCREEN GUM (SN)	NECESSARY	60.00	60.00
1	REAR NO. PLATE (SN)	BENT	40.00	40.00
			380.00	300.00
	<u>LABOUR</u>			
	TO REMOVE AND REFIX REAR WINDSCREEN.		150.00	120.00
	TO REPAIR REAR DAMAGES. INCLUSIVE OF THE REPAIR OF REAR TAIL GATE HINGE AND REAR EXHAUST SILENCER.		980.00	600.00
	TO SPRAY PAINTING.		980.00	600.00
			2,110.00	1,320.00
	GRAND TOTAL		12,624.32	8,108.72
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,450.00

Report Ref No. CS/SPF19017460/T1sd3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000

RECOMMENDED REPAIR DAYS : 6
WEEKEND : 2
TOTAL DAYS : 8

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.