

LOH HENG

Automotive Repair Services
Accident Insurance Claims

1-Oct-19

AXA INSURANCE CO. LTD

Singapore

Attn. : Motor Claim Department

Re : Estimated Quotation SJF360K

NOT Notarised
Lump & ?
Resurvey After Paint
10 days

S/N	Description	Amount (\$S)
A	PART REPLACEMENT	
	Front bonnet	\$ 1,458.00
	Front bonnet insulator	\$ 98.00
	Front bumper	\$ 830.00
	Front right spoiler	\$ 96.00
	Front grille	\$ 390.00
	Front grille chrome ring	\$ 145.00
	Front lower right chrome (Air intake chrome)	\$ 68.00
	Tow cover	\$ 76.00
	No. plate garnish (grille panel)	\$ 45.00
	Front right spot lamp	\$ 320.00
	front right headlamp	\$ 2,350.00
	Front headlamp chrome ring (bonnet)	\$ 78.00
	Front headlamp bracket	\$ 80.00
	Front right fender	\$ 548.00
	Front right inner fender cowling	\$ 145.00
	Front right wheel arch	\$ 158.00
	Front side skirt (lower)	\$ 276.00
	HID bulb module	\$ 843.00
	HID bulb resistor	\$ 910.00
	Washer tank	\$ 125.00
	Front inner cowling cover (2x\$78)	\$ 156.00
	Front right door	\$ 1,180.00
	Front door hinges (\$115x2)	\$ 230.00
	Front right door inner lock	\$ 430.00
	front lower weather stripe	\$ 98.00
	Rear right door	\$ 1,180.00
	Rear door weather stripe	\$ 98.00
	Doors clips (15 x \$7.5)	\$ 112.50
	Rear door hinges (\$118x2)	\$ 236.00
	Rear right wheel arch	\$ 286.00
	Rear right door arch	\$ 108.00
	front right door glass regulator gear	\$ 390.00
	Front right door power winder motor	\$ 298.00
	front right door weather stripe	\$ 190.00

Handwritten checkmarks and 'x' marks in the right margin of the table, indicating approval or rejection of items.

Block 176 #03-08 Sin Ming Autocare
Sin Ming Drive
Singapore 575721
Tel : 64532237 / 64530797
Fax : 64556384

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LOH HENG

Automotive Repair Services
Accident Insurance Claims

Front right drive shaft		\$ 1,850.00	?
front lower arm	<i>Pr</i>	\$ 385.00	?
Steering rack		\$ 3,200.00	?
Tie rod end right		\$ 98.00	?
Front shock absorber	<i>Pr</i>	\$ 785.00	?
Front right wheel bearing	<i>Pr</i>	\$ 540.00	?
Front right knuckle	<i>Pr</i>	\$ 630.00	?
Front right ABS sencor	<i>Pr</i>	\$ 225.00	X
Steering angle sencor	<i>Pr</i>	\$ 950.00	X
Rear wheel bearing		\$ 450.00	?
road rim (\$750x2)	<i>Pr</i>	\$ 1,500.00	?
Anti ro bar		\$ 325.00	X
		\$ 24,969.50	
Less 5%		\$ 23,720.50	
1pc tyre (nett)	<i>Pr</i>	\$ 250.00	70% <i>Pr</i>
Tow charges		\$ 60.00	50%
Labour Charges			
To dismantle all damaged parts and refix new parts. restriaghten door pillar,door alignment,reconfirge door systems.		\$ 1,500.00	1000%
Remove undercarriage suspension,and replace with new parts.		\$ 150.00	✓
To do 4 wheels alignment.		\$ 100.00	80%
To remove steering rack and replace.		\$ 200.00	?
To tranfer all electrical wiring		\$ 80.00	30%
To tranfer all doors window channel,door glass,motor,module,door lock to new door.		\$ 200.00	120%
To putty ,grinding and respraying on all new parts.		\$ 1,500.00	1200%
To do programming and clear all fault codes appear.		\$ 350.00	?
GRAND TOTAL		\$ 28,110.50	

Block 176 #03-08 Sin Ming Autocare
Sin Ming Drive
Singapore 575721
Tel : 64532237 / 64530797
Fax : 64556384