



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2004930
INV Date 14/07/2020
Reference CC4/EQI19017465/Kpa3q2
Code EQI



PROFESSIONAL SERVICE FEE

Vehicle No. FX 1394J
Insured Veh. GBG 6674E
Claim No. DM19HO02650-JG
Policy No. DMCPHQ18-006535
Accident Date 20/09/2019
Inspection Date 04/10/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQ19017465/Kpa3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 14-07-2020



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBG 6674E	Veh. Inspected	FX 1394J
Policy No.	DMCPHQ18-006535	Coverage (\$)	0.00
Claim No.	DM19HO02650-JG	Excess (\$)	0.00
Assign From	JOEL GOH	Assign Date	02/10/2019

2. Vehicle Particulars & Condition

Make & Model	PIAGGIO VESPA	c.c	150
Engine No.	HIDDEN	Year of Reg.	2003
Chassis No.	MH2S1X2BA2K346238	Colour	SILVER
Odometer	48095	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	3.50X10	MICHELIN	3 mm
L/H Front Tyre			mm
R/H Rear Tyre	3.50X10	MICHELIN	6 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION AND N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/09/2019	Inspection Date	04/10/2019
Survey held at	10 AMK IND PARK 2A #05-34		
Repairer	KIM KEAT MOTOR CO.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FX 1394J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT FENDER	BENT	185.00	185.00
1	FRONT WHEEL RIM	SERVICEABLE	85.00	-
1	FRONT FORK COMPLATE	SERVICEABLE	680.00	-
1	SHOCK ABSORBER FRONT	BENT	255.00	255.00
1	ARM COVER	CRACKED	45.00	45.00
1	SET STEERING BEARING ASSY	SERVICEABLE	95.00	-
1	BEADING	TORN	85.00	85.00
1	COMPARTMENT BOX	BUCKLED	380.00	380.00
1	STEP RUBBER MAR LH	CUT	85.00	85.00
1	MUD GUARD LOWER	SERVICEABLE	85.00	-
1	SIGNAL LAMP REAR LH	BROKEN	85.00	85.00
	LESS 10% DISCOUNT		-206.50	-112.00
			1,858.50	1,008.00
<u>SPECIAL NETT ITEMS</u>				
1	NUMBER PLATE FRONT (SN)	BENT	10.00	10.00
1	NUMBER PLATE REAR (SN)	BENT	12.00	12.00
1	CARRIAGE BOX (SN)	BENT / DENTED	280.00	280.00
1	RACK (SN)	BENT	180.00	180.00
			482.00	482.00
<u>LABOUR</u>				
	TO REPAIR FRONT BODY FRAME.		250.00	150.00
	TO RESPRAY FRONT FENDER ,COMPARTMENT BOX,BODY FRAME AND SIDE COVER LH .		650.00	320.00
	LABOUR.		380.00	150.00
			-	-
			-	-
			-	-
			1,280.00	620.00
GRAND TOTAL			3,620.50	2,110.00



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,600.00
---	--	--	-----------------

Report Ref No. CC4/EQ119017465/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FX 1394J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

