

**KIM KEAT MOTOR CO**  
 Blk 10 Ang Mo Kio Industrial Park 2A  
 Avenue5 #05-34 AMK Autopoint  
 Singapore 568047  
 Tel: 64833167 Fax: 64835764  
 Email: kkmotor@singnet.com.sg

*Not withash  
 U/Lay 87  
 Runway After Paint  
 5 days*

26 Sept 2019

EQ Insurance Company Ltd  
 Survey Dept.

**Re: Quotation for damaged to FX1394J.**

<u>Item</u>	<u>Description of Parts</u>	<u>Qty</u>	<u>Amount</u>	
1.	Front Fender	1pc	\$ 185.00	✓
2.	Front Wheel Rim	1pc	85.00	?
3.	Front Fork Complete	1pc	680.00	?
4.	Shock Absorber Front	1pc	255.00	✓
5.	Arm Cover	1pc	45.00	✓
6.	Steering bearing Assy	1set	95.00	?
7.	Beading	1pc	85.00	✓
8.	Compartment Box	1pc	380.00	✓
9.	Step Rubber Mat LH	1pc	85.00	✓
10.	Mud Guard Lower	1pc	85.00	X
11.	Signal Lamp Rear LH	1pc	85.00	✓
			Total \$	2065.00
			Less 10%	- 206.50
			Sub-total \$	1858.50
<b><u>Nett Item</u></b>				
12.	Number Plate Front	1pc	\$ 10.00	✓
13.	Number Plate Rear	1pc	12.00	✓
14.	Carriage Box	1pc	280.00	✓
15.	Rack	1pc	180.00	✓
16.	To Repair Front Body Frame		250.00	1501
17.	To Respray Front Fender, Compartment Box, Body Frame and Side Cover LH		650.00	3201
18.	Labour		380.00	1501
			Grand Total	\$ 3620.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: