

KIM KEAT MOTOR CO
Blk 10 Ang Mo Kio Industrial Park 2A
Avenue 5 #05-34 AMK Autopoint
Singapore 568047
Tel: 64833167 Fax: 64835764
Email: kkmotor@singnet.com.sg

*Not Authorised
 Ulu & 7
 Resurvey After Paint
 5 days*

26 Sept 2019

EQ Insurance Company Ltd
 Survey Dept.

Re: Quotation for damaged to FX1394J.

<u>Item</u>	<u>Description of Parts</u>	<u>Qty</u>	<u>Amount</u>	
1.	Front Fender	1pc	R1 \$ 185.00	✓
2.	Front Wheel Rim	1pc	SVL 85.00	✗
3.	Front Fork Complete	1pc	SVL 680.00	✗
4.	Shock Absorber Front	1pc	R1 255.00	✓
5.	Arm Cover	1pc	CM 45.00	✓
6.	Steering bearing Assy	1set	SVL 95.00	✗
7.	Beading	1pc	T1 85.00	✓
8.	Compartment Box	1pc	R1 380.00	✓
9.	Step Rubber Mat LH	1pc	M 85.00	✓
10.	Mud Guard Lower	1pc	SLC 85.00	✗
11.	Signal Lamp Rear LH	1pc	R1 85.00	✓
			Total \$ 2065.00	
			Less 10%	- 206.50
			Sub-total \$ 1858.50	
<u>Nett Item</u>				
12.	Number Plate Front	1pc	\$ R1 10.00	✓
13.	Number Plate Rear	1pc	R1 12.00	✓
14.	Carriage Box	1pc	R1/R2 280.00	✓
15.	Rack	1pc	R1 180.00	✓
16.	To Repair Front Body Frame		250.00	1501
17.	To Respray Front Fender, Compartment Box, Body Frame and Side Cover LH		650.00	3201
18.	Labour		380.00	1501
Grand Total			\$ 3620.50	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: