

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #08-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 04 Oct 2019

**Preliminary Advice**

Vehicle No	: FBK6195A	Accident Date	: 01/10/2019
Make	: HONDA CB400SF	Policy No.	: 1700073770
Assignment Date	: 04/10/2019	Excess	: S\$0.00
Date of Inspection	: 04/10/2019	Est. Duration of Repair	: 3 days
Inspection At	: Bike Production Pie Ltd (HQ) 610 SERANGOON ROAD Singapore 218216		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion, o/s & n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,560.90
Revised Amount	:S\$	2,710.50
Check Items (Estimated)	:S\$	4,221.70
Total	:S\$	6,932.20
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	13,000.00
COE / PARF Rebate	:S\$	3,779.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,221.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :