



簡 福 星 啤 啤 工 廠

KAN FOOK SING MOTOR WORKSHOP

61 Defu Lane 12, Singapore 539147

Tel : (65) 6747 9560, 6858 2126, 6858 4361

Fax : (65) 6748 1006, 6281 8428

E-mail: kanfs@pacific.net.sg • Website: www.carparts.com.sg

INSURER: **Lonpac Insurance Bhd (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z/19/VC00/104833	Date of Loss:	02/10/2019
Vehicle Reg. No.:	YN978J	Driveable?	
Driver Age/Info:	23 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES

Insured/Claimant: **NAT AIRE & DISTRIBUTION PTE LTD**

Driver: **HAQUE MD ANATUL**

Make/Model: **MITSUBISHI FE83BEOSRDEA, 3.0 Vehicle Reg. Date: 16/03/2010 D B31 (A)**

Vehicle Colour: **WHITE**

Engine No: **4M42A54709**

Chassis No: **FE83BEA10827**

Odometer: **0 KM**

Paint Type:

Total Loss? **NO**

Est. Duration of Repair (day) **5**

Description of Accident/Loss: **REFER WITH ATTACH.**

Present Location: **KAN FOOK SING MOTOR WORKSHOP (DEFU)**

*not authorized
Alan
9/10/19
447*

54005?

COST OF CLAIMS

	Amount
Parts	3,674.25
Miscellaneous Items	30.00
Labour	1,080.00
Paintwork Labour	600.00
Towing	0.00
Gross Total (\$\$)	5,384.25
Acknowledged by Repairer Signature: + GST 7.00% (\$\$)	376.90
Date: Nett Amount (\$\$)	5,761.15

This claim is handled by: **ALICE CHAU**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 04 Oct 2019)**Parts:** N/A MITSUBISHI FE83BEOSRDEA 3.0 D B31 (A) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Kan Fook Sing Motor Workshop/YN978J/04/10/2019 10:16**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BODY PANEL <i>~</i>	0.00	0.00	*550.00 F <i>X</i>
2	1		*FRONT GRILLE <i>Cne</i>	0.00	0.00	*350.00 F <i>—</i>
3	1		*FRONT GRILLE (FUSO) <i>me</i>	0.00	0.00	*65.00 F <i>—</i>
4	1		*HEADLAMP RH <i>11</i>	0.00	0.00	*370.00 F <i>X</i>
5	1		*HEADLAMP LH	0.00	0.00	*370.00 F <i>?</i>
6	1		*SIGNAL LAMP RH <i>11</i>	0.00	0.00	*140.00 F <i>X</i>
7	1		*SIGNAL LAMP LH <i>Cne</i>	0.00	0.00	*140.00 F <i>—</i>
8	1		*FRONT BUMPER <i>34</i>	0.00	0.00	*480.00 F <i>—</i>
9	1		*FRONT BUMPER BRACKET RH	0.00	0.00	*90.00 F <i>?</i>
10	1		*FRONT BUMPER BRACKET LH	0.00	0.00	*90.00 F <i>?</i>
11	1		*AIR CON BLOWER	0.00	0.00	*550.00 F <i>?</i>

F=Franchise part.

Sub Total (\$\$) **3,195.00**+ Margin on L,N Items 15.00% (\$\$) **479.25**Total Parts (\$\$) **3,674.25**

Kan Fook Sing Motor Workshop/YN978J/04/10/2019 10:16. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT NO. PLATE	30.00
			<i>30.00</i> <i>14</i>
Sub Total (S\$)			30.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAY PAINTING	New	600.00
			<i>400</i>
<u>Labour Items</u>			
2	REMOVE & REFIX FRONT WINDSCREEN	New	100.00
			<i>11</i> <i>100.00</i> <i>2</i>
3	REMOVE & REFIX DASHBOARD ASSY	New	250.00
			<i>11</i> <i>250.00</i> <i>X</i>
4	REMOVE & REFILL AIR CON GAS	New	80.00
			<i>80.00</i> <i>?</i>
5	REMOVE ALL NECESSARY AFFECTED PARTS FOR REPAIRS, WELD/ CUT, PANEL BEATING & RENEW PARTS	New	650.00
			<i>650.00</i> <i>550</i>
Gross Labour Cost (S\$)			1,680.00

Kan Fook Sing Motor Workshop/YN978J/04/10/2019 10:16. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >