

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 9006 TAMPINES ST 93 #01-204
SINGAPORE 528840
TEL : 67853933 FAX: 67883933
R.O.C No. 200104141D GST Reg No. 20-0104141-D

TO : S8736188H
NADIAH BINTE KAMSANI
BLK 333C ANCHORVALE LINK
07-318
SINGAPORE 543333
TEL : FAX :
PH : 97402475
ATTN :

ESTIMATE BILL

Number : EBK0000286
Date : 01/10/2019
Case No : ADK0000360
Vehicle No : SJM1061E
Chassis : JMYSRCY2A9U003326
Year of Mfr : 2008
Policy No :
Model : MITSUBISHI
LANCER

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	RR BUMPER <i>do/pe</i>	1.0	831.00	10	747.90
2	RR BUMPER SIDE RETAINER LH RH <i>AA</i>	2.0	18.00	10	32.40
3	RR BUMPER BRACKET LH RH <i>AA</i>	2.0	18.00	10	32.40
4	RR BUMPER CLIPS <i>der</i>	10.0	3.00	10	27.00
5	RR END PANEL <i>~</i>	1.0	508.00	10	457.20
6	RR END PANEL TOP GARNISH <i>AA</i>	1.0	155.00	10	139.50
Nett Price - Parts Sub Total					1,436.40
Parts Total					1,436.40
7	RR BOOTLID REPAIR <i>~x</i>	1.0			
8	LABOUR TO REMOVE AND REFIT NECESSARY PARTS	1.0	600.00	0	600.00
9	SPRAY PAINT ON THE AFFECTED AREAS	1.0	600.00	0	600.00
Labour 1 Sub Total					1,200.00
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date: <i>not added</i> <i>1/5 #1700</i> <i>2 dy.</i> <i>Chaphe Adh 1/1</i> <i>4/10/19</i>					<i>30.</i> <i>40.</i> <i>P- 1950</i> <i>102</i> <i>1257</i> <i>2455</i> <i>302</i> <i>1718</i>
SINGAPORE DOLLARS : TWO THOUSAND EIGHT HUNDRED TWENTY AND CENTS NINETY-FIVE ONLY			Less Excess		0.00
			SUBTOTAL		2,636.40
			GST 7.00%		184.55
			TOTAL		2,820.95

Date of accident : 30/09/2019 06:50 AM. Place : SENGKANG EAST ROAD

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE