

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 9006 TAMPINES ST 93 #01-204
SINGAPORE 528840
TEL: 67853933 FAX: 67883933
R.O.C No. 200104141D GST Reg No. 20-0104141-D

TO : S8736188H
NADIAH BINTE KAMSANI
BLK 333C ANCHORVALE LINK
07-318
SINGAPORE 543333
TEL : FAX :
PH : 97402475
ATTN :

ESTIMATE BILL

Number : EBK0000286
Date : 01/10/2019
Case No : ADK0000360
Vehicle No : SJM1061E
Chassis : JMYSRCY2A9U003326
Year of Mfr : 2008
Policy No :
Model : MITSUBISHI
LANCER

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	RR BUMPER <i>do/2e</i>	1.0	831.00	10	747.90
2	RR BUMPER SIDE RETAINER LH RH <i>Am</i>	2.0	18.00	10	32.40
3	RR BUMPER BRACKET LH RH <i>#1</i>	2.0	18.00	10	32.40
4	RR BUMPER CLIPS <i>her</i>	10.0	3.00	10	27.00
5	RR END PANEL <i>2</i>	1.0	508.00	10	457.20
6	RR END PANEL TOP GARNISH <i>11</i>	1.0	155.00	10	139.50
Nett Price - Parts Sub Total					1,436.40
Parts Total					1,436.40
7	RR BOOTLID REPAIR <i>2x</i>	1.0			
8	LABOUR TO REMOVE AND REFIT NECESSARY PARTS	1.0	600.00	0	600.00
9	SPRAY PAINT ON THE AFFECTED AREAS	1.0	600.00	0	600.00
Labour 1 Sub Total					1,200.00
SINGAPORE DOLLARS : TWO THOUSAND EIGHT HUNDRED TWENTY AND CENTS NINETY-FIVE ONLY					
Less Excess					0.00
SUBTOTAL					2,636.40
GST 7.00%					184.55
TOTAL					2,820.95

Date of accident : 30/09/2019 06:50 AM. Place : SENGKANG EAST ROAD

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE