

BODYFIX

NO 10 ANG MO KIO INDUSTRIAL PARK 2A #04-06

AMK AUTOPOINT SINGAPORE 568047

Tel No. : 62571289 Fax No. : 64837432

E-Mail : bodyfix@singnet.com.sg

Tax Reg. No. : 53010635C Buss. Reg. No. : 53010635C

AXA INSURANCE PTE LTD
8 SHENTON WAY #27-01
AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department
Contact : 3387288 Fax No. : 8804838

Estimate : ES191007

Date : 08/10/2019
Vehicle Num. : SKQ 8849 X
Make/Model : BMW 520-2013
Chassis/Eng# : WBA5A32040D334538
Accident Date : 18/09/2019
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1 PC	LIST ITEMS :		
2.	1 PC	FRONT BUMPER		1,380.00
3.	10 PCS	FRONT BUMPER SIDE RETAINER - RH		38.00
4.	1 PC	FRONT BUMPER CLIPS	3.50	35.00
5.	1 PC	FRONT BUMPER SENSOR		490.00
6.	1 PC	FOG LAMP (FRONT -RH)		530.00
7.	1 PC	FOG LAMP GRILLE RH		45.00
		FOG LAMP COVER RH		89.00

List TotalS\$:

LABOUR :

RUST-PROOFING ON THE ACCIDENT AFFECTED PORTIONS

50.00 X

LABOUR TO REPLACE ABOVE PARTS, PANEL BEAT, REPAIR &
RE-ALIGN DAMAGE PARTS

200 600.00

SPRAY PAINT FRONT BUMPER & AFFECTED AREAS

200 500.00

Labour Total S\$:

1,150.00

SingDollars : Three Thousand Seven Hundred Fifty-Seven Only

E. & O.E.

Total S\$: 3,757.00


for BODYFIX

3 Days.

1ump sum repair.

After repair photos.

Gao Qiang - 82880282

08/10/19.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: