

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: YN2040B190701

Estimate

Customer

Name: AIG Asia Pacific Insurance Pte Ltd

Address: Motor Claims Department

78 Shenton Way #07-16

AIG Building

Singapore 079120

Date: 08-10-19

Vehicle No: YN2040B

Model/Make: Hino
FD8JPKA

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Door View Mirror	\$ 421.50	X
2	Door Signal Lamp	\$ 206.30	X
	To check all wiring & electrical component for proper function	\$ 50.00	X
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 500.00	X
	To putty & spray painting & including touch up paint on accident affected	\$ 800.00	X

Total Parts & Labour of estimate for damaged vehicle

\$ 1,977.80

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

not followed
lowerthe are other rep-
4/10/19P/P 700
3 dy.LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: