

Satwant Singh
Pritam Singh
Khong Zi-Wei

SATWANT & ASSOCIATES

ADVOCATES & SOLICITORS • COMMISSIONER FOR OATHS • NOTARY PUBLIC

An Official Member of The Lawyer Network, an international network of law firms

(Please quote our Ref. when replying to our office at Toa Payoh)

Your Ref : To be advised

Our Ref: PD/DL/1801656 (sp)
(sophia@satwantlaw.com.sg)

8 weeks

30 NOV 2018

**WITHOUT PREJUDICE
BY HAND/ BY EMAIL**

SPF ACCIDENTS CLAIMS SECTION


Automotive Engg & Mgmt Duv

No.1 Mount Pleasant Road

#02-12 Block 8 Old Police Academy

Singapore 298333

Attention: Mr. Abdul Rahmand / Mr. Frankie / Motor Claims



Dear Sirs,

ACCIDENT INVOLVING SJG8524Y & QX782Z ALONG PAYA LEBAR ROAD TRAVELLING TOWARDS PIE ON 20/09/2018 @ 18:00

We act for Mr Wong Yit Long, whose motor vehicle No. SJG8524Y was damaged in the above accident by your insured motor vehicle No. QX782Z.

Our investigations reveal that you are the Insurer of motor vehicle No. QX782Z at the material time of the accident and that the said accident was caused solely by the negligence of the driver of your insured motor vehicle.

We enclose herewith copy each of the following: -

1. Motor Accident Statement/Police Report;
2. LTA searches;
3. Vehicle Insurance Certificate;
4. Repair Bill;
5. Survey report, photographs and invoice.

We are instructed to claim the following: -

- | | |
|--------------------------------------|---------------------------------------|
| 1. Cost of Repairs (Lump Sum) | \$ 9,798.93 (\$5,128.93 + \$4,670.00) |
| 2. Loss of Use (12 days x \$100/day) | \$ 1,200.00 (Inclusive of 2 days PRI) |
| 3. LTA Fees | \$ 7.49 |
| 4. Surveyor report fees | \$ 100.00 |
| 5. Incidentals | \$ 200.00 |
| 6. Costs (at this stage) | \$ 1,000.00 |

Total: \$ 12,306.42

MAIN OFFICE:

3 Jalan Bingka
Singapore 588896

Tel: 6299 9470 Fax: 6299 5541

CONVEYANCING BRANCH OFFICE:

450 Lorong 6 Toa Payoh #02-03 Harsing Centre
Singapore 319394

Tel: 6221 6114 Fax: 6266 6925

This document is intended for the addressee(s) only and may contain confidential information and/or may be subject to legal privilege. If you have received this is error, please contact us immediately and destroy the original message.

Kindly let us know whether you are prepared to settle our client's claim amicably within 8 weeks from the receipt of this letter, failing which, we shall commence legal proceedings without further reference to you as instructed.

We look forward to hearing from you.

Yours faithfully

A handwritten signature in blue ink that reads "Satwant & Associates". The signature is written in a cursive, flowing style.

SATWANT & ASSOCIATES

encs

cc client



Xin Yun Auto Private Limited

幸运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

LOD

Your reference: AEMD/105/009/2018/117

Our reference: SJG8524Y

TO: SPF Accidenets Claims Section
Automotive Engg & Mgmt Duv
No.1 Mount Pleasant Road
#02-12 BLOCK 8 Old Police Accademy Singapore 298333

Attn: Mr. Abdul Rahmand / Mr. Frankie / Motor Claims
Dear Sirs,

WONG YIT LONG
BLK 710 Clementi West St2 #09-241 (120710)



We are instructed by the abovenamed to claim damages against you in connection with an accident on 20/09/2018 at about 18:00 hours along Paya Lebar Road Travelling Towards PIE, involving our client's vehicle no. **SJG8524Y** and vehicle registration number **QX782Z**. As result of the accident, our client's vehicle **SJG8524Y** was damaged and our client had been put to loss and expense, particulars of which are as followings:

Damage

a) Cost of Parts Replacement	\$5,128.93
b) Cost of Repair Labour	\$4,670.00
c) Loss of use 10days+2days PRI X\$100 per day	\$1,200

Cost

d) LTA Search	\$7.49
e) Surveyor Estimate Report by Skycam Surveyor	\$100

Total Cost	\$11,106.42
-------------------	--------------------

Workshop Information:

Workshop Name: Xin Yun Auto Private Limited

Address: Blk8 Kaki Bukit Ave4 #05-23 Premier @Kaki Bukit Singapore 415875

Contact Email: xinyunauto1@gmail.com

Contact No.: Operation Manager Fabian 98391666



Xin Yun Auto Private Limited

幸运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

2018/11/12

Estimate cost of repairs for SJG 8524Y/ Chassis no: JHMGD185085214763

Parts Replacement:

S/no	Parts Description	Qty	Parts Price	Remarks
1	Front bumper	1	\$627.50	
2	Front bumper reinforcement	1	\$154.80	
3	Front bonnet	1	\$464.70	
4	Front grille emblem (H)	1	\$27.42	
5	Front grille	1	\$ 121.60	
6	Front bumper LH dust cover	1	\$27.10	
7	F/LH fog lamp	1	\$257.10	
8	F/RH fog lamp	1	\$257.10	
9	Front bumper lower grille	1	\$121.60	
10	Front bumper LH Side vent cover	1	\$26.00	
11	Front bumper RH Side vent cover	1	\$26.00	
12	Front LH Headlamp	1	\$486.20	
13	Front RH Headlamp	1	\$486.20	
14	Front LH Headlamp bracket	1	\$26.70	
15	Front RH Headlamp bracket	1	\$26.70	
16	Rear tailgate	1	\$997.40	
17	Rear tailgate LH shock absorber	1	\$123.20	
18	Rear tailgate RH shock absorber	1	\$123.20	
19	Rear tailgate inner trim cover	1	\$330.20	
20	Rear tailgate weather strip	1	\$ 50.50	
21	Rear tailgate Honda emblem	1	\$27.10	
22	Rear tailgate Jazz emblem	1	\$31.60	
23	R/L taillamp assy	1	\$283.60	
24	R/R taillamp assy	1	\$283.60	
25	Rear tailgate lock assy	1	\$119.40	
26	Rear tailgate lock catch	1	\$29.00	
27	Rear tailgate weathers trip	1	\$97.20	
28	Rear bumper	1	\$690.80	
29	Rear bumper tow cover	1	\$37.10	
30	Rear end panel	1	\$299.40	
31	Rear end panel top garnish	1	\$120.40	
32	Rear end panel back garnish	1	\$63.10	
33	R/H fender inner garnish cover	1	\$168.60	
34	R/R fender inner garnish cover	1	\$168.60	
35	Rear spare tyre compartment box	1	\$380.20	
36	Rear silencer	1	\$580.80	
Sub Total			\$ 8,141.72	
Less 20%			\$ 1,628.34	
Parts Total			\$ 6,513.38	



Xin Yun Auto Private Limited

幸运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

S/no	Nett Parts			
1	Front bumper clips		\$ 40.00	
2	Rear bumper clips		\$ 40.00	
3	Rear end panel top garnish clips		\$ 40.00	
4	Windscreen sealant		\$ 150.00	
5	Reverse sensors		\$ 240.00	
Sub Total			\$ 510.00	
Parts Grand Total			\$ 7,023.38	

Estimate cost of repairs for SJG 8524Y/ Chassis no: JHMGD185085214763

Labour Charges

S/no	Labour Charges	Repairer Estimate	Remarks
1	To labour charges for removing front bumper assy, front bonnet out to facilitate repairs and replacement of damaged parts and include straightening of radiator support panel	\$1,000	
2	To labour charge for respraying font bonnet, front bumper and support panel	\$1,000	
3	To labour charge for removing rear tailgate, rear bumper, end panel and spare tyre panel out to facilitate repairs and replacement of damaged parts	\$1,800	
4	To labour charge for removing and fixing rear tailgate glass	\$240	
5	To labour charge for respraying rear tailgate, rear bumper, end panel and spare tyre compartment	\$1600	
6	To labour charge for removing rear silencer out to facilitate repair and replacement of damaged parts	\$180	



Xin Yun Auto Private Limited

幸运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

7	To labour charge for removing rear reverse sensors out to facilitate replacement of damaged parts	\$200	
8	To supply body sealant and apply anti-rust on all parts damaged area	\$140	
9	To supply font and back number plate	\$80	
Labour Grant Total		\$6240	
Grade Total for Parts and Labour		\$13,263.38	