

REF: CS1SPF180173041 d3-1
 ASSIGNMENT (Office)
 From (Person): Hafizul Farhan
 Estimated Cost: SPF
 Date/Time: 04/10/2019
 OD / ☒ WS / TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: SJG 8524Y Insured: QX7822
 at Workshop on: Xin Yun Auto Tel: 9839 1666
 of: 8 Kaki Bkt Ave 4 #05-23
 Policy No: Claim No: AEMD/105/009/2018/117
 Sum Insured: Excess:
 Make of Veh: D.O.A: 20/09/2018
 (Client's Record)
 CA / REV / REP. / REV 24 HRS (up)
 Date/Time: 12:23pm 24/9/18 Person Contacted: Fabian Vehicle IN/OUT: ☒ OUT
 H.O.D. Endorsement:
 Date/Time Action/Instruction (✓) Estimate Pls provide the upper range repair cost.
 SJG 8524Y-X
 QX 7822-X
 8/10 12:04pm Confirmed with Hafizul that this case only need indicate the upper range repair cost in our report. No paper survey and RI required. *Alvin 8/10/19*
 Submit L/S \$7000 @ 10 days
 Ref: \$6263.38, 477.

Do Not Finalise

SWYDUR

Xen

REF:

SPF

1950F

ASSIGNMENT

(-2023)

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / CD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s: **Xin Yun Auto**

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$28K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

24/9 Estimate Give later

2/10 Repair limit \$10K

2/10 Email marking to repairer

RECEIVED 10 OCT 2018

Veh No:

SJG8524Y

Yr Regn:

17 Ju/2008

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Jazz

cc 1339

Colour:

yellow

A/C: Insured / Std / NI / NA

Sp Reading:

183117

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHM6D1850 8S 214763

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In/Out / Jammed / Leaked / Burnt or

Brake: In/Out / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/45 R16
R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

D.O.I.

24-08-09-18

Survey held at

w/s

3:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Cost/Taxi, File Fees etc?

☐

Prel. Report

1)

typist

☒

Final Report

Date/Time, File Return Int?

2)

Days Of Repair:

10

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

) S + RS: \$

) Phone

) Cover

)

TOTAL

Report Format :

TP

Lump Sum / LB: (\$

7,000.00

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Insp (\$

☐

Weekend (\$

280

280

Nivitha (LKK Auto)

From: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>
Sent: Thursday, 3 October 2019 5:44 PM
To: Admin-D (LKKAuto); assignments
Cc: Frankie THAY (SPF)
Subject: POST survey of SJG 8524Y
Attachments: Annex B (LOD-SJG8524Y) 2018-117.pdf

Message Classification: Unclassified

Your ref: CS/SPF/18017304/Grd3e2

Our ref: AEMD/105/009/2018/117

Hi,

Kindly conduct Re-survey of SJG 8524Y. Please see attached for the third party surveyor.

We need to close the gap on their cost of repair which is \$9,798.93

Can you also provide the upper range repair cost.

Thank you.

Best Regards,

Hafizul Farhan Bin Rahmat

AEMD / PLD

Singapore Police Force

DID: (65) 6478 4840 | FAX: (65) 6478 4850



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



This email has been checked for viruses by AVG antivirus software.

www.avg.com