

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road
159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



Steve (CLKK)
8322 8813

WZ N/A
P/P
Ry Ak Sm

7 day
4/10/19, 2.00 pm

GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BG 4375	Page No. : 1 of 3
Date Estimated : 04/10/2019	
Prepared By : Andy Ooi Lee Keong	

- ESTIMATE REPAIR FOR - Margaret Chye Sze Yeen Mrs Ee Kim M 1 QUEEN'S ROAD #10-189 #10-189 SINGAPORE 260001	- ACCOUNT - 35 India Int'l Insurance Pte Ltd 64 Cecil Street #04/05 IOB Building Singapore 049711
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLG5358G	WF04XXGCC4GR44473	04/10/2016	Foc 1.0 4Dr	0

DESCRIPTION	VALUE
TO CONDUCT TP CLAIM-INDIA INT' AGAINST-SH6124U. DOA.29/9/2019 .	0.00
SUNDRIES	30 150.00
LABOUR TO REMOVE, REPLACE, REPAIR, REALIGN FRONT BUMPER, FRONT FENDER LH, FRONT DOOR LH REAR DOOR LH, LH ROCKER PANEL SIDE GARNISH, LH FRONT DOOR PILLAR AND ALL AFFECTED AREA.	2100 4,200.00
LABOUR TO PUTTY AND RESPRAY FRONT BUMPER, FRONT FENDER LH, FRONT DOOR LH, FRONT DOOR PILLAR LH, REAR DOOR LH, ROCKER PANEL GARNISH LH AND ALL AFFECTED AREA	3000 4,200.00
TO TRANSFER AND REFIT FRONT DOOR FITTING, GLASS, TRIM AND MECHANICAL COMPONENT LH.(NETT)	300.00
TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES, RESTORE ALL PROGRAMME MODULE. (NETT)	600.00
COMPUTERISED 4 WHEEL ALIGNMENT .	300.00
LABOUR TO REMOVE AND REPLACE FRONT KNUCKLE ARM LH, FRONT SHOCK ABSORBER LH, FRONT LOWER ARM LH, FRONT KNUCKLE ARM BEARING LH, STEERING RACK END PINION, FRONT DRIVESHAFT LH.	1000 1,500.00
TO SUPPLY 1PCS TYRE (MICHELIN) 205/55R16. TN / 70%	250.00
TO REMOVE AND REPLACE LHF TYRE AND WHEEL RIM INCLUDING BALANCE WHEEL.(NETT)	40.00
Total Labour 1:	11,540.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
F1EB17757AJX	FRONT BUMPER X R	1	1,530.00	10.00	1,377.00
WAA					
F1EB13006BF	HEADLAMP ASSY LH X	1	2,893.00	10.00	2,603.70
BM51A10155AL	MOULDING ROCKER LH / CH	1	225.00	10.00	202.50
PBM51A16009A	LHF FENDER ASSY / 01	1	562.00	10.00	505.80
G					

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

ESTIMATE

Estimate No. : BG 4375
Date Estimated : 04/10/2019
Prepared By : Andy Ooi Lee Keong

Page No. : 2 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLG5358G	WF04XXGCC4GR44473	04/10/2016	Foc 1.0 4Dr	0

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
AM51R16115BG	INNER SHEILD-LH FRT FENDER / CRV	1	277.00	10.00	249.30
BM51A237A05B	LHF FOIL-DOOR SEALING-PLASTIC X	1	113.00	10.00	101.70
C					
BM51A23943JV	FRONT DOOR LH X BB	1	1,050.00	10.00	945.00
1FKY					
BM5AA21813D	GLATCH, LH (Trim) X	1	560.00	10.00	504.00
BM51A221A00A	FRONT DOOR LOCK CABLE ASSY LH X	1	60.00	10.00	54.00
B					
BM51A16003BF	LHF DR FRAME QTR MOULDING / MJS	1	360.00	10.00	324.00
F1EBA21511BB	SEAL-LH FRT DOOR GLASS RUN X	1	265.00	10.00	238.50
F1EBA21411AA	F/LH DOOR GLASS X	1	290.00	10.00	261.00
BM51A23201BF	LHF DR REGULATOR ASSY - F11 ?	1	770.00	10.00	693.00
6CP114A389L3	MOTOR ASSY-LHF POWER WINDOWS ?	1	285.00	10.00	256.50
C					
PBM51A20125B	DOOR-LESS HINGE LHF (R th Door LH) X VB / DN	1	1,801.00	10.00	1,620.90
F					
AM51U22801AE	HINGE ASSY - LHF/LHR UPPER DOOR X BT	1	105.00	10.00	94.50
AM51U22811AE	HINGE-DOOR LHF X BT	1	105.00	10.00	94.50
BM51A23500AA	CHECK ARM - RH/LH FRT DOOR X	1	102.00	10.00	91.80
BM51A20530AF	WEATHERSTIP - BODY RH/LH FRT DOOR / APC	1	220.00	10.00	198.00
PBM51A24631B	DOOR - LESS HINGE LH REAR X R (Rear door)	1	1,612.00	10.00	1,450.80
F					
HV6C3D070ME	GEAR - RACK AND PINION STEERING / BT	1	4,225.00	10.00	3,802.50
AV613K171DAC	KNUCKLE FRT WHEEL, LH ?	1	1,250.00	10.00	1,125.00
AV611104BAG	HUB-WHEEL ?	1	950.00	10.00	855.00
BV6118K001	FRONT SHOCK ABSORBER LH ?	1	550.00	10.00	495.00
F1F13B437PB	LHF DRIVESHAFT X ?	1	2,220.00	10.00	1,998.00
F1F13A424AAB	FRT LWR ARM LH ?	1	555.00	10.00	499.50
F1EC1007B1B	ALLOY WHEEL ASSY (7.0XR16) / CVT	1	702.00	10.00	631.80
EV6T1A180DD	KIT - TPMS SENSOR ((-)-ST) / APC	1	130.00	10.00	117.00
AU5A13B375AA	W/MIRROR BOTTOM LAMP LH - M08 X	1	60.00	10.00	54.00
BM5117K747AB	WING MIRROR OUTER COVER LH X	1	280.00	10.00	252.00
ZJAC					
8M5113B381AC	LAMP WING MIRROR, LH X	1	138.00	10.00	124.20
BS7117K741GA	WING MIRROR GLASS LH X	1	230.00	10.00	207.00
BM5117683RG	WING MIRROR ASSY LH W/O GLASS X	1	620.00	10.00	558.00
8V411K018AB	FRT HUB BRG - ECO2.0 ST,F11 ?	1	400.00	10.00	360.00

Total Parts : 22,945.50

REGENT MOTORS

(A Division of Vantage Automotive Limited)

Business Registration No. 53055563L GST Registration No. M2-0000551-1

305 Alexandra Road

159942 Singapore

Tel : 6477 7400

Fax : 6477 7398



GST Registration No. M2-0000551-1

E S T I M A T E

Estimate No. : **BG 4375**
Date Estimated : **04/10/2019**
Prepared By : **Andy Ooi Lee Keong**

Page No. : **3 of 3**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLG5358G	WF04XXGCC4GR44473	04/10/2016	Foc 1.0 4Dr	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Customer Name & Signature / Company Stamp

Date

Labour 1	:	11,540.00
Parts	:	22,945.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,413.99
Grand Total	:	36,899.49

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval. This estimate is valid for a period of 30 days only.