



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com

Website: www.nhtmotor.com

Tel: 6747 9241

Fax: 6741 7276

UEN: 201718370K

LOH CHEE LAN

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

04/10/2019

TP Con Pac.

Asher.

Accident date: 02/10/2019

Estimated repair cost for vehicle no: SKZ6673B HONDA VEZEL 1.5 X A '16

CHASSIS: RU11108637

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Distorted.</i>		\$1,100.90 ✓
2	2	Rear Boot Lid Hinges <i>Bent</i>	\$68.10	\$136.20 ✓
3	2	Rear Boot Lid Shock Absorbers <i>Damaged.</i>	\$180.90	\$361.80 ✓
4	1	Rear Boot Lid Emblem Logo <i>New</i>		\$45.10 ✓
5	1	Rear Boot Lid Vezel Logo <i>New</i>		\$56.30 ✓
6	1	Rear Boot Lid Camera (Special Nett) <i>Damaged.</i>		\$550.00 <i>400(SN)</i> ✓
7	1	Rear Boot Lid Number Plate <i>Bent.</i>		\$50.00 ✓
8	2	Rear Boot Lid Number Plate Lamp <i>Not new</i>	\$38.50	\$77.00 ✗
9	2	Rear Boot Lid Side Reflector <i>Cracked.</i>	\$284.60	\$569.20 ✓
10	1	Rear Boot Lid Inner Lock <i>Damaged.</i>		\$185.60 ✓
11	1	Rear Boot Lid Inner Rubber <i>Wt</i>		\$135.25 ✓
12	1	Rear Boot Lid Inner Trim Board <i>Cracked</i>		\$355.75 ✓
13	1	Rear Boot Lid Inner Trim Board Side Handle Cover <i>Del-d</i>		\$55.80 ✓
14	1	Rear Boot Lid Wiper Motor <i>Damaged.</i>		\$205.00 ✓
15	1	Rear Boot Lid Wiper Arm <i>Wt</i>		\$122.00 ✓
16	1	Rear Boot Lid Windscreen <i>Shattered.</i>		\$1,150.70 ✓
17	1	Rear Boot Lid Windscreen Seal <i>New</i>		\$151.70 ✓
18	2	Rear Boot Lid Windscreen Side Moulding <i>Cracked</i>	\$75.00	\$150.00 ✓
19	2	Rear Tail Lamp <i>Cracked.</i>	\$474.60	\$949.20 ✓
20	2	Rear Tail Lamp Panel <i>Rgr</i>	\$135.70	\$271.40 ✗
21	4	Rear Tail Lamp Clips <i>New</i>	\$8.00	\$32.00 <i>10.</i>
22	2	Rear Tail Lamp Lower Bracket <i>New</i>	\$18.10	\$36.20 ✗
23	2	Rear Tail Lamp Lower Cover <i>Del-d.</i>	\$198.70	\$397.40 ✓
24	1	Rear Bumper <i>Distorted.</i>		\$801.70 ✓
25	2	Rear Bumper Side Retainer <i>New</i>	\$29.20	\$58.40 ✓
26	2	Rear Bumper Side Reflector <i>RH cracked</i>	\$148.40	\$296.80 <i>148.40</i>
27	1	Rear Bumper Reverse Sensor (Special Nett) <i>Damaged</i>		\$350.00 <i>200(SN)</i>

28	1	Rear End Panel Distorted		\$595.60	✓
29	1	Rear End Panel Top Garnish Deformed		\$122.30	✓
30	1	Rear End Panel Lock Sensor Cnld		\$98.10	✓
31	1	Rear End Panel Buzzer Missing		\$85.50	✓
32	2	Rear Fender Not New	\$931.80	\$1,863.60	X
33	2	Rear Fender Protector Wt Cnld	\$150.20	\$300.40 150.20	X
34	2	Rear Fender Cowling 2 new	\$105.30	\$210.60	+
35	12	Rear Fender Cowling Clip	\$6.50	\$78.00	+
36	2	Rear Fender Inner Trim Board Cnld	\$325.25	\$650.50	✓
37	16	Rear Fender Inner Trim Board Clip New	\$6.50	\$104.00 60	X
38	1	Rear Spare Tyre Panel Buckled		\$662.20	✓
39	2	Rear Spare Tyre Side Panel Repair	\$125.70	\$251.40	X
40	1	Rear Spare Tyre Panel Top Cover Deformed		\$306.65	✓
41	1	Rear Spare Tyre Panel Lower Cover Repainted		\$190.90	X
42	1	Rear Spare Tyre Panel Foam Tool Box Cnld		\$226.70	✓
43	1	Rear Spare Tyre Under Cover Deformed		\$190.90	✓
44	8	Rear Spare Tyre Under Cover Clips New	\$6.50	\$52.00 30	X
45	1	Rear Exhaust Bent		\$868.00	✓
46	1	Rear Center Exhaust Bent		\$986.00	✓
47	4	Rear Exhaust Mounting Not New	\$25.60	\$102.40	X
48	1	Rear Exhaust Aluminum Cover Not New		\$105.00	X
49	1	Boot Lid Outer Garnish Cnld	335.80	✓	
50	1	Boot Lid Top Spoiler Cnld	830.70	✓	
51	2	Boot Lid Inner Side Trim Board	135.40	250.80	
			Subtotal :-		\$16,702.15

13590.55

10872.44 S.N: 600

Labour charges

To remove & refit cushion & trim board	\$280.00 250
To remove & refit reverse sensor	\$100.00 50
To remove & refit reverse camera	\$180.00 60
To remove & refit rear & center exhaust	\$380.00 160
To remove & refit rear windscreen	\$120.00 ✓
Gum	\$50.00 ✓
To check wiring	\$100.00 30
Tuff kote	\$150.00 120.
Towing fee	3520 \$150.00 x
Panel beating	\$2,400.00 1400
Spray painting	\$2,000.00 1200
To transfer tool lid fittings 150 80	
Subtotal :-	<u>\$5,910.00</u>
Total:-	<u>\$22,612.15</u>

total: 14892.44

H/S: 12K
10 Days.

12K 10 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: