

Ashley

COMFORTDELGRO
ENGINEERINGComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156Our Job Ref No 305338513
Date : 07.10.19

FINALIZATION FORM

To : LKK
Attn : Mr KALVIN ANG
Vehicle Reg No. SHC8397S CTPL

Fax :

03.10.19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA 686 516SP
2. The finalized amount shall be:
- (a) Spare Parts after List discount
- (b) Labour Charges
- Total for Part-By-Part Repair Cost**
- (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$1,300.00
Final Lumpsum Repair cost \$1,300.00

3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and
finalized amountSignature : AK
Name : LIM KWOK ENG
Tel : 62148316
Fax : 65468156Signature : Kalvin
Name : Kalvin
Date : 8/10/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

REPAIR ESTIMATE*

VEHICLE NO : SHC 8397S

MAKE :

MODEL : HYUNDAI i40

DATE 3/10/2019 15:07

LKK

CHINA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper / ca			\$ 553.00	
	Rear Bumper Clip 10 pcs / ne			\$ 22.00	
	Rear Bumper Bracket X sue		\$ 35.60	\$ 71.20	
	Rear Bumper Under Cover X sue			\$ 228.00	
	Rear Bumper Reflector Lamp (LH) X sue			\$ 30.60	
	Rear Bumper X repair				
	SUB TOTAL			\$ 904.80	
	LESS 20%			\$ 180.96	
	DISCOUNTED TOTAL			\$ 723.84	
	Rear Bumper Advertisement Logo / ne			\$ 50.00	Nett
	Rear Bumper Rubber Mat / ne			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) / ne		\$ 100.00	\$ 200.00	Nett
	Rear Bumper Adhesive sticker / ne			\$ 70	
				\$ 300.00	
	Labour Charge				
	Panel Beating			\$ 300.00 420	
	Spray Painting Charge			\$ 300.00 400	
	Wiring Charge			\$ 50.00 X 2	
	Remove/Refix Reverse Sensor			\$ 80.00 70	
	TOTAL LABOUR			\$ 730.00	
	ESTIMATE TOTAL			\$ 1,753.84	
	Kalan (LKK)				
	3/10/19 1535L				
	2 Days				
	4/5				
	After Repair photo				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

