

# Massive Trading & Auto

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225  
H/p 91082728

Fax : 64816131

Ng Han Song  
Blk 776 Woodlands Crescent  
#06-56  
Singapore 730776

Vehicle No : SFE 3822 C  
Make/Model : Subaru Forester 2.0 X  
Year : 2018

*Not withered  
11 days @ 1050k  
Resurvey After Paint  
2 days*

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

## Estimate Cost Of Repair

1 pc	Rear bumper
1 pc	Rear bumper reinforcement

*nd 1cm*  
\$855.70 ✓  
*n* \$455.70 X  
\$1,311.40  
Less 15%  
*20%* \$196.71  
\$1,114.69

## S Nett

1 pc	Rear reverse sensor
1 pc	Rear bumper top sticker

*n* \$200.00 X  
*n* \$250.00 ✓

## Labour Charges

Remove/renew the above accident parts including knocking, welding & cutting.

\$500.00 *200d*

To putty and spray paint on rear portion.

\$500.00 *220d*

Check & reconnect wiring.

*nn* \$30.00 X  
\$2,594.60

Total

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: