From (Person)	Marcus Crysal La	ASSIGNMI of MS	ENT (Office)	Dete/Fir	ne: 4.10.19	4.31 1.4
Estimated Tos		OI	Bill to:	Date/III	no.	
/)	TP RES / OD RES / EV	A / INV / MV / A				
	nicle No: S1 2 4-894			Insured:	UP64514	
	als Precise Auto			Tel: 67		
of NOI ka	BUED Ave 6	F02-33 /34	136		-	
	28966472mKG		Claim No:	608015		
Sum Insured:			Excess:			
Make of Veh	100			DOA	3/10/19	
	REP. / REV 24 HRS	"" erson Contacted:	Arine	H.O.D.	Endorsement:	
Date/Time:) Estimat	0 .			
Date/Time:	Action/Instruction (E 200 11 11 10 10 10 10 10 10 10 10 10 10 1	· · · · · · · · · · · · · · · · · · ·			
	Action/Instruction (V	6150151911	unda pres	20/08/2015		
	YN 5729D COSINS	615015196/s	vbd2 Dr	20/08/2015		
	104	615015194/ ₁	ivbd2 Da	20/08/2015		

MEF:

(X)

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

MSIG Insurance (Singapore) Pte. Ltd. From: LKK Auto Consultants Pte Ltd To: 51 Ubi Ave 1 #01-25 4 Shenton Way #21-01 SGX Centre 2 Paya Ubi Industrial Park Singapore 408933 Singapore 068807 13 Nov 2019 Date: Attn: Fievel Foo Wenyao **Preliminary Advice** Insured Vehicle No : YN5729D Accident Date : 03/10/2019 TP Vehicle No : SJZ4898U : 07/10/2019 : TOYOTA COROLLA ALTIS Assignment Date Est, Duration of Repair 1 Date of Inspection : 16/10/2019 : PRECISE AUTO SERVICES (HQ) Inspection At NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883 Point of Impact / General Description of Damages The vehicle sustained impact / damages n/s front mirror and parts claimed are consistent to the accident. Repairer's Estimate (Gross) :S\$ 1,122.20 700.00 (LUMP SUM) :S\$ Revised Amount Check Items (Estimated) :S\$ 0.00 :S\$ 700.00 Total Lump Sum Repair :S\$ **Total Loss Consideration** New for Old Value :S\$:\$\$ Pre-Accident Value COE / PARF Rebate :S\$:S\$ Salvage Value Margin for Repair :S\$ Remarks The vehicle is economical/not economical for repair.

The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	ACKING Est Submitted	Adi Assigned	Adl Rpt	Adj Subi	nitted In	is Auth'ed	Status	
Main	04 Oct 2019		07 Oct 2019 10:44 Edit Adj Rpt					Report Cancel Case	urvey
	Main	R	eference		Claim Details		Documents		Show All
CLAIM SU	BFOLDER I	DETAILS	And I have been successful.			[Created I	oy insurer]		
Insured:	Brands	chutz Fire Techno	logy Pte Ltd,	o. Reg. No.:	201005890R				
Main Claimant:		E CAR RENTAL P							
Vehicle Re	g. SJZ48	98U			Date of Loss:	[106 Month	16:00 - :59 ns and 3 Days Fro		(Man Yr)]
Claim Type	: TP / 6	08015			Policy/Cover Note No.:		28966472MKC (Comprehensive) Coverage: 03/07/2019 - 02/07/2020		
Vehicle Re	YN5729	YN5729D			Policy No. (Claimant):				
(Insured):					Excess:				
Repairer:	Precise	Auto Services (H	Q) NO.1 KAKI BI	JKIT AVE 6	#02-34/36, 4178	83 Kaki Buki	t - Tel:		
Handling Insurer:	MSIG I	nsurance (Singap	ore) Pte. Ltd. (HQ) - Tel: +	65 6827 7888	[Handled by	Fievel Foo We	nyao - 6643 131	.6] 2/10/20191
Adjuster:	LKK Au	to Consultants Pi	e Ltd (HQ) - Tel	: 6256-3561	[Handled by	MARCUS CH	UA] [IMM./	esion: Marcus C	hua from LKK
Adj Asg. Remarks:	on WP. Auto Co	Manual assigned to nsultants Pte Ltd. (LKK via email on Contact: Arine @	04/10/19. (6745 7367.	Manual Assign).	Liab: unclear	, Agree on SJE. A	issign. Harcus C	nda from Ext
ASSOCIA	TED MAIL	RECEIVED					V	riew All Comp	ose Case Mail
There are	no mail for t	his case.							
ALL ASS	OCIATED T	ASKS [⊡]				View All	Search Tasks	Create New Task	Complete
Due Da	te Prior		k Group Sul	oject Ha	ndler Assig	ned By	Completed On	Created C	n Done

View Sent Message

This mail is associated with:

*SJZ4898U (608015) [YN5729D]

TP
JOYRIDE CAR RENTAL PTE LTD
Oct 3 2019 4:00PM
[Brandschutz Fire Technology Pte Ltd]
Precise Auto Services

Resend View Recipients Print Message Delete Message Forward

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 17/10/2019 11:32 AM.

To MSI_CLSC

Subject TP SURVEY SJZ 4898U

Dear Crystal,

Please be informed that we have inspected the vehicle SJZ 4898U on 16/10/2019.

We are pending workshop estimate from repairer.

Best Regards,

Veron Chen

DOCUMENTS SUMMARY

There are no documents.

Summer Lee (LKK Auto)

From:

Crystal Lee <crystal_lee@sg.msig-asia.com>

Sent:

Friday, 4 October, 2019 4:31 PM Admin-D (LKKAuto); assignments

To: Cc:

Ong Zi Hui

Subject:

Survey Request - Manual Assigned

Attachments:

04102019132853.pdf

Importance:

High

Manual Assigned

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you & Best regards, Crystal Lee Admin Officer, Claims Services (In-House Survey) D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220



A Member of MS&AD INSURANCE GROUP

From: Helene Phua

Sent: Friday, 4 October, 2019 3:32 PM

To: Crystal Lee <crystal_lee@sg.msig-asia.com>; Ong Zi Hui <zihui_ong@sg.msig-asia.com>

Subject: FW: Pre-repair Inspection for SJZ 4898U (Your Insured Veh no: YN 5729D)

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg

A Member of MS&AD INSURANCE GROUP

From: Helene Phua

Sent: Friday, 4 October, 2019 3:32 PM

To: 'Precise Auto Service' < Support@preciseauto.sg > Cc: Fievel Foo <Fievel Foo@sg.msig-asia.com>

Subject: RE: Pre-repair Inspection for SJZ 4898U (Your Insured Veh no: YN 5729D)

Hi,

Thank you for your selection.

We will proceed to assign Marcus Chua from LKK Auto Consultants Pte Ltd via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion. Any arrangement or appointment of surveyor must come from MSIG.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg

A Member of MS&AD INSURANCE GROUP

From: Precise Auto Service [mailto:Support@preciseauto.sg]

Sent: Friday, 4 October, 2019 3:23 PM

To: Helene Phua <helene phua@sg.msig-asia.com> Cc: Fievel Foo <Fievel Foo@sg.msig-asia.com>

Subject: Re: Pre-repair Inspection for SJZ 4898U (Your Insured Veh no : YN 5729D)

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Sir.

We refer to your email on dated 04-10-2019. Please be informed that we would like to select Mr. Marcus Chua from LKK Auto Consultancy as our SJE.	
Thank You.	
Best Regards Arine	
On Fri, 4 Oct 2019 at 14:39, Helene Phua < helene phua@sg.msig-asia.com > wrote:	
Hi,	
We refer to your email dated 04/10/2019.	
Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:	
1) LKK Auto Consultants Pte Ltd	
2) Formteam Consultancy Pte Ltd	
3) A-PAC Adjusters & Surveyors Pte Ltd	
4) STA Inspection Pte Ltd	
5) Appraisal VP Pte Ltd	
6) AutoProbe Consultants	
7) MSIG In-House Surveyors	
This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor	
To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).	
If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability	•

1)	Kalvin Ang	6) Chow Bo Xiong	
2)	Kenneth Kong	7) E C Looi	

3) Marcus Chua	8) Daniel Chan	
4) Ng You Han	9) Victor Png	
5) Gary Soon	10) Samuel Phun	

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB:

- (a) *Fast lane settlement is not applicable for cases that liability is in dispute*
- (b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msig-asia.com

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg

A Member of MS&AD INSURANCE GROUP

From: Precise Auto Service [mailto:Support@preciseauto.sg] Sent: Friday, 4 October, 2019 1:36 PM
To: Motor Survey <motorsurvey@sg.msig-asia.com></motorsurvey@sg.msig-asia.com>
Subject: Pre-repair Inspection for SJZ 4898U (Your Insured Veh no : YN 5729D)
Timeson Tuni B. (1. 1 Hely and links or open any attachment(s)
EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).
Dear Sir,
We refer to the above matter. Herewith attached 2 days PRI notice for your attention.
The state of the s
Kindly arrange a date and time to do PRI for our client vehicle (SJZ 4898U) in our workshop ASAP.
Thank You.
Best Regards
Arine
Affile
I
T: 6745 7367 F: 6841 3390
E: support@preciseauto.sg
W: www.preciseauto.sg
A: No.1 Kaki Bukit Ave 6, #02-33/34/36 AutoBay @ Kaki Bukit, Singapore 417883

.,	*
Follow us	on social media:
	https://www.instagram.com/preciseautosvs/
	https://twitter.com/preciseautosvs
	https://www.facebook.com/PreciseAutoService/
	TY NOTICE uding any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any an the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intend and the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intend and the intended recipient is not a waiver of the email and do not copy, distribute or disclose its contents.
<u>.</u>	
E : support@p	F: 6841 3390 preciseauto.sg ciseauto.sg Bukit Ave 6, #02-33/34/36 AutoBay @ Kaki Bukit, Singapore 417883

Follow us on social media:

https://www.instagram.com/preciseautosvs/
https://twitter.com/preciseautosvs
https://www.facebook.com/PreciseAutoService/



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

wner ID Type:	Company
Owner ID:	065H
/ehicle Details	
/ehicle No.:	SJZ4898U
/ehicle to be Exported:	No
ntended Deregistration Date:	16 Oct 2019
/ehicle Make:	TOYOTA
/ehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	1ZRX033229
Chassis No.:	MR053REE104104195
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$16,446.00
Original Registration Date:	30 Nov 2010
First Registration Date:	30 Nov 2010
Transfer Count:	1
Actual ARF Paid: Intended PARF Rebate Details	\$16,446.00 fre
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Nov 2020
PARF Rebate Amount:	\$9,045.00
Intended COE Rebate Details	
COE Expiry Date:	29 Nov 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$34,001.00
COE Rebate Amount:	\$3,806.00
Total Rebate Amount:	\$12,851.00

The information contained herein is correct as at 16 Oct 2019

ОК

PRECISE AUTO SERVICE

NO. 1 KAKI BUKIT AVE 6 #02-33/34/36 SINGAPORE 417883

TEL: 67457367 FAX: 68413390

CO. REG. NO.: 35766600C

GST REG. NO.: 35766600C

08-11-19

Date Of Accident: 03-10-19

OUR REF: SLZ 4898U/T/19

Date Injurts 16-10-19 to 19-10-19

Joyride Car Rental Pte Ltd

1 Kaki Bukit Ave 6 #02-34 (BLK D) Singapore 417883

> ESTIMATE BILL ON VEH. NO.: SLZ 4898U MODEL: TOYOTA ALTIS

CHASSIS NO.: MR053REE104104195

LIST ITEM

Side Mirror M A(S

Side Mirror Cover 1

997.30

152.30

Less Discount 25%:

1.149.60 287.40 862.20

LABOUR CHARGE

To Replace Side Mirror & Aligned

To Respray Painting

130.00

130.00

GST 7%:

1,122.20 78.55

TOTAL AMOUNT:

1,200.75

LKK Auto Consultants hence notify the Repairer of the following:

= To dispute demanded part(s) during resulting / 10/1/. Parts of the are subject to confirmation. 25%

a success to final approval from Insurance Construction

718.01

Not Allocal 241 18/10/19 2/5# 700

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG19017532/UVF3N2

Date:

14/11/2019

REFERENCE

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

28966472MKC

Claimant

SJZ4898U

Insured Vehicle No:

YN5729D

Vehicle No: Date of Loss:

03/10/2019

Nature of Claim:

TP

Claim No: 608015

MR053REE104104195

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SJZ4898U

Make & Model:

TOYOTA COROLLA ALTIS, 1.6 (A) 30/11/2010 (Man. Year: 2010)

Engine No: Chassis No: Odometer:

1ZRX033229

200286 km

Reg. Date: Colour:

Silver

Engine Capacity:

1598 cc

Market Value/New Car

N/A

Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

195/65R15

Rear Tyre Size:

195/65R15

Front Left Side:

Michelin 6 mm

Rear Left Side: Rear Right Side: Michelin 6 mm Michelin 6 mm

Michelin 6 mm Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	862.20	758.85	103.35	11.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	260.00	140.00	120.00	46.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,122.20	898.85	223.35	19.90
Approved Total (Overridden) (S\$)		700.00		
(S\$)	1,122.20	700.00	422.20	37.62
+ GST 7.00/7.00% (S\$)	78.55	49.00	29.55	37.62
Nett Amount (S\$)	1,200.75	749.00	451.75	37.62

INSPECTION

Date of Assignment:

07/10/2019

Date Inspected:

16/10/2019 Inspected At:

Precise Auto Services (HQ)

NO.1 KAKI BUKIT AVE 6 #02-34/36

Singapore 417883

Estimated Period of Repair:

1.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Nov 2019)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJZ4898U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommende	ed Par	ts
------------	--------	----

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	4		*SIDE MIRROR N/S	Cracked	997.30 FL	*866.50 FL
2	1		*SIDE MIRROR COVER N/S	Broken	152.30 FL	*145.30 FL
F=Fra	anchise	part. L=ListItem	- List Item Discount on L It	Sub Total (S\$) ems 25.00/25.00% (S\$)	1,149.60 287.40	1,011.80 252.95
				Total Parts (S\$)	862.20	758.85
_			Panert was unsubmitte	d during this print out		

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
our Items	New	130.00	80.00
TO REPLACE SIDE MIRROR & ALIGNED			
TO RESPRAY PAINTING	New	130.00	60.00
	Gross Labour Cost (S\$)	260.00	140.00
Report was I	insubmitted during this print-out.		
	Particulars Our Items TO REPLACE SIDE MIRROR & ALIGNED TO RESPRAY PAINTING	Particulars Dur Items TO REPLACE SIDE MIRROR & ALIGNED TO RESPRAY PAINTING Gross Labour Cost (S\$)	Particulars Lab.Type Repairer's Dur Items TO REPLACE SIDE MIRROR & ALIGNED TO RESPRAY PAINTING New 130.00 New 130.00

< END OF ESTIMATES >