

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

cost plus 15%

TO : SXXX3650H
SON JOO HO
BLK 70 BAYSHORE ROAD
#12-09
SINGAPORE 469987
TEL : FAX :
PH : 90067496
ATTN :

not allocated
7/10/19
take photo before painting.
Tony.

ESTIMATE BILL

Number : EB00005292
Date : 07/10/2019
Case No : AD00010712
Vehicle No : SMH3822D
Chassis : GM41207357
Year of Mfr : 2018
Policy No : 5107162680
Model : HONDA GRACE
HYBRID 1.5DX AUTO

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	BOOTLID <i>Body</i>	1.0	675.20	20	540.16
2	BOOTLID HINGE RH <i>11</i>	1.0	68.40	20	54.72
3	BOOTLID HINGE LH <i>11</i>	1.0	68.40	20	54.72
4	BOOTLID EMBLEM <i>new</i>	1.0	27.40	20	21.92
5	BOOTLID LOGO - GRACE <i>new</i>	1.0	45.00	20	36.00
6	BOOTLID LOGO - HYBRID <i>new</i>	1.0	66.20	20	52.96
7	BOOTLID CHROME	1.0	220.30	20	176.24
8	BOOTLID LAMP RH	1.0	326.80	20	261.44
9	BOOTLID LAMP LH <i>one</i>	1.0	326.80	20	261.44
10	TAIL LAMP RH	1.0	416.00	20	332.80
11	TAIL LAMP LH <i>Sub</i>	1.0	416.00	20	332.80
12	TAIL LAMP CLIP <i>11</i>	8.0	4.30	20	27.52
13	BOOTLID LOCK <i>121</i>	1.0	151.80	20	121.44
14	BOOTLID INNER TRIMBOARD <i>11</i>	1.0	99.70	20	79.76
15	BOOTLID RUBBER <i>121</i>	1.0	91.60	20	73.28
16	TAIL LAMP PANEL LH	1.0	98.00	20	78.40
17	END PANEL <i>Body</i>	1.0	395.60	20	316.48
18	END PANEL TOP GARNISH <i>121</i>	1.0	86.40	20	69.12
19	SPARE TYRE PANEL <i>new</i>	1.0	855.00	20	684.00
20	SPARE TYRE PANEL SPONGE <i>11</i>	1.0	168.30	20	134.64
21	SPARE TYRE PANEL TOP GARNISH <i>new</i>	1.0	254.30	20	203.44
22	REAR BUMPER <i>Body</i>	1.0	937.70	20	750.16
23	REAR BUMPER RETAINER RH	1.0	14.90	20	11.92
24	REAR BUMPER RETAINER LH	1.0	14.90	20	11.92
25	REAR BUMPER BRACKET RH	1.0	17.00	20	13.60
26	REAR BUMPER BRACKET LH	1.0	17.00	20	13.60
27	REAR BUMPER REFLECTOR LH	1.0	48.00	20	38.40
28	REAR BUMPER REFLECTOR GRILLE LH <i>De</i>	1.0	43.60	20	34.88
29	REAR BUMPER INNER CENTER GRILLE <i>De</i>	1.0	40.20	20	32.16
30	REAR CENTER LOCK SENSOR	1.0	85.80	20	68.64
31	HYBRID BATTERY (REAR)	1.0	8,500.00	20	6,800.00
32	REAR POWER SPLIT DEVICE ELECTRIC MOTOR	1.0		20	
List Price - Parts Sub Total					11,688.56
33	REAR NUMBER PLATE	1.0	30.00	0	30.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

* N = Item not subjected to GST

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX3650H
SON JOO HO
BLK 70 BAYSHORE ROAD
#12-09
SINGAPORE 469987
TEL : FAX :
PH : 90067496
ATTN :

ESTIMATE BILL

Number : EB00005292
Date : 07/10/2019
Case No : AD00010712
Vehicle No : SMH3822D
Chassis : GM41207357
Year of Mfr : 2018
Policy No : 5107162680
Model : HONDA GRACE
HYBRID 1.5DX AUTO

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
34	REAR NUMBER PLATE HOLDER	1.0	30.00	0	30.00
35	REVERSE SENSOR	1.0	280.00	0	280.00
36	REVERSE CAMERA	1.0	580.00	0	580.00
37	REAR FENDER RH - REPAIR	1.0			
38	REAR FENDER LH - REPAIR	1.0			
Special Nett Price - Parts Sub Total					920.00
Parts Total					12,608.56
39	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	1,500.00	0	1,500.00
40	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,200.00	0	1,200.00
41	ANTI-RUST COATING	1.0	300.00	0	300.00
42	WIRING	1.0	80.00	0	80.00
43	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
44	COMPUTERISED SETTING	1.0	500.00	0	500.00
Labour 1 Sub Total					3,730.00
SINGAPORE DOLLARS : SEVENTEEN THOUSAND FOUR HUNDRED EIGHTY-TWO AND CENTS TWENTY-SIX ONLY					
Less Excess					0.00
SUBTOTAL					16,338.56
GST 7.00%					1,143.70
TOTAL					17,482.26

Date of accident : 07/10/2019 09:36 AM. Place : PIE > TUAS

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

* N = Item not subjected to GST