

LKK Kammt
 710 - 11.30
 Video footage to LKK
 Admining
 #5122

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
 SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
 Business Regn No: 269436/00J

Not Notified
 W Lee @
 1.2.1
 4 days

05, OCT 2019

China Taiping Insurance (S) PL
 105 Cecil Street #18-00
 The Octagon
 S 069534

Attn: Motor claim dept-3rd party claim
 Claiming against your insured vehicle no: YK4527S
 Accident involving vehicle no: SKU2916D/YK4527S
 DOA: 02/10/2019 AT Marine Parade slip road twds ECP-Still Rd South

Dear officer incharge
 Re: estimate cost of repair for vehicle no: SKU2916D
 To supply—

Description	Qty	Amount
Front bumper	1	458.00 ✓
Bumper retainer	1	89.20 ✓
Front fender	1	761.45 ✓
Fender VVTI emblem	1	38.40 ✓
Fender cowling	1	163.40 X
Cowling clip		42.00 X
Bumper clip		38.00 ✓
Bonnet	1	1,028.10 X
Headlamp w HID	1	2,804.00 ✓
Headlamp top chrome	1	137.70 ✓
Bumper foglamp	1	248.20 X
Foglamp cover	1	112.90 X
Parts		6,011.35
Parts less 25%		1,502.83
		4,508.52

To check/rectify headlamp wiring, check /focus headlamp 80.00 2cl
 To remove damaged parts and attachments.
 Repair/reshape dented areas
 Replace/align above parts into position. 900.00 50cl
 To spray paint 1,100.00 60cl

 6,588.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: