

23/03/2013

ASS. REC. BY:

REF: 183/INC 19015594 / Ust3-1

Special Instruction:

SUBJECT: Marcus

ASSIGNMENT (Office)

From (Person): Motor Incomeof INCDate/Time: 5/10/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKZ 4065UInsured: SKIC 3114Yat Workshop m/s Bluwel AutomotiveTel: 67452028of Bte 1 Kaki Buit Ave C 401-24

Policy No:

Claim No: MT/1060579-001

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 31.8.2019

CA / REV / REP. / REV 24 HRS

Date/Time: 2.9.19. 5.45 pm

Person Contacted:

Sally

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time

Action/Instruction (☒) EstimateSKZ 4065U9/10/19Subtotal 2/5 \$11,500 - 8%
CF 2,200/- Red - 16%John
9/10/2019

200

REF: INC

ASSIGNMENT

From: 3.9.2019

Estimated Cost

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No: SKZ 4065 U

at Workshop n/s Bluwel Automotive

at

Insured

Policy No

Claims No

Sum Insured


Excess

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value:

686.

IDAC Accident Report

Consistent? : Yes or No

GIA / PR. Seen:

Consistent? : Yes or No

Est. repairs

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SKZ 4065 U Yr Regn: 1/16

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: mazda 5

c.c. 1998

Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 100034

T/Radio: Insured / Std / NI / NA

EngNo:

C/No: JM6CW10716012307

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Judder / Jammed / Leaked / Burnt or

Brake: Judder / Jammed / Leaked / Burnt or

Modi: Nil / 8/Run / STD A/Rim or

Tyre Size: F: 205/55-R16 R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

LOYD / YCKO or

Front

Rear

R/Bal: 7 mm

R/Bal: 7 mm

L/Bal: 7 mm

L/Bal: 7 mm

D.O.A: 3/8/19

D.O.I: 3/9/19 9.20

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rd, N/S 50 by 6

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

No fault pos LIA 48947
Lys. 4th. Rep 9h. net 19053
resulting on 11-9-19

Quoted Time / File Pass to?

☐ : Prel. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time / File Return to?

2)

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. frws (\$)

☐ Weekend (\$)

Report Format:

Lump Sum / L.B.I. (\$)

Survey Fee:

Transportation

3 + 100 50

Phone

Other

TOTAL

Nivitha (LKK Auto)

From: do_not_reply@income.com.sg
Sent: Saturday, 5 October 2019 10:00 AM
To: assignments@lkkauto.com
Subject: MT/1060472-002 - Claim Involving SKK3114Y / SKZ4065U on 31 Aug 2019
Attachments: Survey Report(for Tablet).PDF; color photos(LOD2).PDF;
EBGI-300002963-0000012470-1570210889848_EBAOGICLM_DLET_MT.pdf

Dear Sir / Madam,

We refer to the above claim.

Enclosed is the letter / document for your necessary attention.

Yours sincerely

Motor Insurance
Income

Note: This is a system generated email. Please do not reply to this email.

MARCUS

03/09/2019 TUE 10:21 FAX

001/005

MSM1911038 / 038: Motor Pte Ltd - Basic Rule
 ENTRY DATE & TIME: 03/09/2019 17:32
 SUBMITTED BY: Chai Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GUA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 02/09/2018 17:32
 Date Of Accident 31/08/2019 15:45
 Exact Location Of Accident RAFFLES BOULEVARD
 Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKZ4065U
 Insured/Policyholder
 Name Of Registered Owner TAN YU KHI
 NRIC No S8217251C
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-97567607
 Alternative Phone No OFFICE-97567607

Vehicle Particulars

Manufacturer MAZDA
 Model 5
 Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken

THIRD PARTY
 PRIVATE CAR

Insurance Company

Name of Insurance Company FWD SINGAPORE PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number FNPV2018-00001088-01
 Cover Note Number

Driver

Name of Driver NG CHUN KIAT
 NRIC No S7833431B
 Date Of Birth 04/11/1978
 Occupation OUTDOOR
 Date Of Driving Pass 21/02/2013
 Driving Experience 6 YEARS AND 6 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-97964623
 Fax Number
 Contact Number
 Email Address NOEMAIL

02/09 2019 TUE 10:21 FAX

002/005

Address BLK 17B CIRCUIT ROAD #10-214
 Postcode 372017
 Was driver an employee of the Insured's Company? NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (including Driver) 2
 Passenger 1

NAME : JACQUELINE
 GENDER : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON THE STATED DATE AND TIME, AT THE STATED VENUE, MY VEHICLE A (SK24065U) WAS TRAVELLING STRAIGHT ON MY RIGHTFUL LANE ON THE EXTREME RIGHT LANE. SUDDENLY, VEHICLE B (SKK3114Y) TRAVELLING ON MY LEFT CUT INTO MY LANE AND HIT ONTO MY FRONT LEFT PORTION, THEN HE MOVED FORWARD, HIS REAR RIGHT PORTION HIT ONTO MY FRONT LEFT PORTION AGAIN. TOTAL DOUBLE IMPACT ON MY FRONT LEFT PORTION OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKK3114Y
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name

03/09 2019 TUE 10:21 FAX

003/005

Nature Of Damage

No. Of Passenger (Including Driver)

03/09 2019 TUE 10:22 FAX

0004/005

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report specifically the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GRI Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 2/8/19, 4pm

Driver's Signature

(If driver is not the policyholder)

Date & Time: 2/8/19, 4pm

Reporting Centre Personnel's Signature

Name:

NRIC/Fin No.:

BMMB

[Signature]


03/09 2019 TUE 10:22 PAX

0005/005

Sketch Plan #2 Pg. 1

SKETCH PLAN

Raffles Boulevard



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, at the stated venue my vehicle 'A' SKZ 40654 was travelling straight on my rightful lane on the extreme right lane. Suddenly vehicle 'B' SKK 31147 travelling on my left cut onto my lane and hit onto my front left portion, then he moved forward his rear right portion hit onto my front left portion again. Total double impact on my front left portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

31/8/19, 4pm

BURNING SKILL/INFORM_173

Driver's Signature

(If driver is not the policyholder)

Date & Time:

31/8/19, 4pm

Reporting Centre Personnel's Signature

Name:

NRIC/IN No.:

MC-COY

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

Billing Name & Address

Tan Yu Khi
c/o No.1 Kaki Bukit Ave 6
#01-53/55 AutoBay@ Kaki Bukit
Singapore 417883

Invoice No 19002-09/AY

Date 23 Sep 2019

Vehicle No : SKZ 4065 U

Model : Mazda 5

Item	Descriptions	Amount S\$
1	Date of inspection : <u>3 Sep 2019</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Develop photographs - Storage of digital photographs - Submission of photographs <u>191</u> copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection	
	Total	<u>\$ 1066.00</u>
	SDLS : ONE THOUSAND AND SIXTY-SIX ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Mc-Coy Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

E & O. E

MC-COY

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6633 Fax: 67471017 Registration No: 200723252D

Report Reference : TP / 19002-09/AY / 2019
Date of Report : 23 Sep 2019

Tan Yu Khi
c/o No.1 Kaki Bukit Ave 6
#01-53/55 AutoBay@ Kaki Bukit
Singapore 417883

THIRD PARTY SURVEY ACCIDENT HAPPENED ON 31 Aug 2019

Workshop Address : Bluwel Automotive Service Pte Ltd
No.1 Kaki Bukit Ave 6
#01-53/55 AutoBay@ Kaki Bukit
Singapore 417883

As per your instruction dated **3 Sep 2019** with regard to the above matter. We have carried out a physical inspection on the said vehicle **SKZ 4065 U**. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No	: SKZ 4065 U	Engine No	: PE10290055
Model	: Mazda 5	Mileage	: 100034
Year / Capacity	: 2016/1998	Colour	: Grey
Chassis No	: JM6CW1071G0123017		

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S	: 205/55 R16	Michelin	6.00 mm	Sport
REAR O/S	: 205/55 R16	Toyota	6.00 mm	Sport
FRONT N/S	: 205/55 R16	Michelin	6.00 mm	Sport
REAR N/S	: 205/55 R16	Toyota	6.00 mm	Sport



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417683
Tel: 6748 6655 Fax: 67471017 Registration No: 200723252D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the n/s portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 9 working days to complete.
5. Enclosed number of photograph : 191 copies.
6. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
7. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: SKZ 4065 U
Report No: TP/ 19002-09/AY / 2019

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
2	Front headlamps	Sc R/CN Damage	\$ 2822.80	\$ 2822.80
1	Front grille inner garnish	Ym1 Damage	\$ 186.00	\$ 186.00
1	Front bumper	D/S Damage	\$ 1055.40	\$ 1055.40
1	Front bumper centre grille	CNE Damage	\$ 689.90	\$ 689.90
1	Front bumper reinforcement	R Repair	\$ 506.20	\$ 506.20
1	Front n/s fender	BUL Damage	\$ 307.00	\$ 307.00
1	Front n/s fender inner shield	To, n Damage	\$ 206.00	\$ 206.00
1	Front n/s wheel hub	Int Damage	\$ 159.90	\$ 159.90
1	Front n/s wheel hub bearing	Int Necessary	\$ 146.40	\$ 146.40
1	Front n/s shock absorber	Int Damage	\$ 253.10	\$ 253.10
1	Front n/s knuckle arm	Int Damage	\$ 368.40	\$ 368.40
1	Front n/s lower arm	Int Damage	\$ 391.30	\$ 391.30
1	Front steering rack	Int Damage	\$ 1735.80	\$ 1735.80
1	Front steering rack cross member	Int Damage	\$ 1873.80	\$ 1873.80
1	Front stabilizer bar	Int Damage	\$ 325.50	\$ 325.50
1	Front stabilizer bar n/s link	Int Damage	\$ 93.10	\$ 93.10
1	Front n/s drive shaft	Int Damage	\$ 1467.30	\$ 1467.30
1	Front n/s door	Int Damage	\$ 1204.40	\$ 1204.40
1	Front n/s door inner board	Int Intact	\$ 870.80	\$ 870.80
1	Front n/s door lock	Int Damage	\$ 467.10	\$ 467.10
1	Front n/s door outer handle	Int Intact	\$ 133.50	\$ 133.50
1	Front n/s door regulator	Int Damage	\$ 155.80	\$ 155.80
1	Front n/s door regulator motor	Int Damage	\$ 320.90	\$ 320.90
1	Front n/s door regulator support	Int Damage	\$ 320.90	\$ 320.90
1	Front n/s door rubber	Int Necessary	\$ 80.40	\$ 80.40
1	Front n/s door side mirror	Int Damage	\$ 529.40	\$ 529.40
1	N/s rocker panel	Int Repair	\$ 1367.50	\$ 1367.50
1	N/s rocker panel side skirt	Int Damage	\$ 1104.90	\$ 1104.90
1	Front bumper inner sponge	Int Damage	\$ 75.40	\$ 75.40
1	Front bumper n/s fog lamp	Int Intact	\$ 340.00	\$ 340.00
1	Front bumper n/s fog lamp cover	Int Damage	\$ 78.20	\$ 78.20
Discount 20.0%			\$ 19637.10	\$ 16419.10
			\$ 3927.42	\$ 3283.82
			\$ 15709.68	\$ 13135.28
<u>Special Nett Items</u>				
1	Front n/s fender inner shield clip (1 set)	Int Necessary	\$ 28.00	\$ 28.00
1	Front n/s tyre (depreciation)	Int Damage	\$ 400.00	\$ 240.00
1	Front n/s sport rim	Int Damage	\$ 650.00	\$ 650.00
			\$ 1078.00	\$ 918.00
Spare Parts Total			\$ 16787.68	\$ 14053.28

Vehicle No: SKZ 4065 U
Report No: TP/ 19002-09/AY / 2019

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total	\$ 16787.68	\$ 14053.28
1	To remove and refit damage parts, test for proper functioning and focus of headlamps.	\$ 50.00	\$ 40.00 20
2	To remove and refit front undercarriage.	\$ 300.00	\$ 200.00 ✓
3	To check and re-adjust (Computerized) all wheel alignment.	\$ 200.00	\$ 120.00 80
4	To remove and refit the door lock mechanism, regulator gear, window glass, handle, inner board, hinges, channel to facilitate the repairs.	\$ 200.00	\$ 120.00 60
5	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1600.00	\$ 1250.00 680
6	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1600.00	\$ 1250.00 80
7	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 150.00	\$ 90.00 60
Total		<u>\$ 20887.68</u>	<u>\$ 17123.28</u>

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 13700.00

14491.2
1182

SDLS: THIRTEEN THOUSAND SEVEN HUNDRED ONLY


Qualified Appraiser

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref : CS3/INC19015594/Usf3s2-1

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date : 10-10-2019

189556



Code : INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKK 3114Y	Veh. Inspected	SKZ 4065U
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1060472-002	Excess (\$)	0.00
Assign From	MOTOR INCOME	Assign Date	05/10/2019

2. Vehicle Particulars & Condition

Make & Model	MAZDA 5	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JM6CW1071GG0123017	Colour	GREY
Odometer	100034	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	MICHELIN	7 mm
L/H Front Tyre	205/55 R16	MICHELIN	7 mm
R/H Rear Tyre	205/55 R16	MICHELIN	7 mm
L/H Rear Tyre	205/55 R16	MICHELIN	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND N/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	31/08/2019	Inspection Date	03/09/2019
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 4065U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	FRONT HEADLAMPS	SCRATCHED / CRACKED	2,822.80	2,822.80
1	FRONT GRILLE INNER GARNISH	TWISTED	186.00	186.00
1	FRONT BUMPER	DISTORTED	1,055.40	1,055.40
1	FRONT BUMPER CENTRE GRILLE	CRACKED	689.90	689.90
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	506.20	-
1	FRONT N/S FENDER	BUCKLED	307.00	307.00
1	FRONT N/S FENDER INNER SHIELD	TORN	206.00	206.00
1	FRONT N/S WHEEL HUB	BENT	159.90	159.90
1	FRONT N/S WHEEL HUB BEARING	NECESSARY	146.40	146.40
1	FRONT N/S SHOCK ABSORBER	BENT	253.10	253.10
1	FRONT N/S KNUCKLE ARM	BENT	368.40	368.40
1	FRONT N/S LOWER ARM	BENT	391.30	391.30
1	FRONT STEERING RACK	BENT / TWISTED	1,735.80	1,735.80
1	FRONT STEERING RACK CROSS MEMBER	BENT	1,873.80	1,873.80
1	FRONT STABILIZER BAR	BENT	325.50	325.50
1	FRONT STABILIZER BAR N/S LINK	BENT	93.10	93.10
1	FRONT N/S DRIVE SHAFT	TWISTED	1,467.30	1,467.30
1	FRONT N/S DOOR	DENTED / BENT	1,204.40	1,204.40
1	FRONT N/S DOOR INNER BOARD	SERVICEABLE	870.80	-
1	FRONT N/S DOOR LOCK	SERVICEABLE	467.10	-
1	FRONT N/S DOOR OUTER HANDLE	SERVICEABLE	133.50	-
1	FRONT N/S DOOR REGULATOR	SERVICEABLE	155.80	-
1	FRONT N/S DOOR REGULATOR MOTOR	SERVICEABLE	320.90	-
1	FRONT N/S DOOR REGULATOR SUPPORT	SERVICEABLE	320.90	-
1	FRONT N/S DOOR RUBBER	NECESSARY	80.40	80.40
1	FRONT N/S DOOR SIDE MIRROR	CRACKED	529.40	529.40
1	N/S ROCKER PANEL	TO REPAIR SEE LABOUR	1,367.50	-
1	N/S ROCKER PANEL SIDE SKIRT	DISTORTED	1,104.90	1,104.90
1	FRONT BUMPER INNER SPONGE	SERVICEABLE	75.40	-
1	FRONT BUMPER N/S FOG LAMP	SERVICEABLE	340.00	-
1	FRONT BUMPER N/S FOG LAMP COVER	SCRATCHED	78.20	78.20



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-3,927.42	-3,015.80
			15,709.68	12,063.20
	SPECIAL NETT ITEMS			
1	SET FRONT N/S FENDER INNER SHIELD CLIP (SN)	NECESSARY	28.00	28.00
1	FRONT N/S TYRE (SN)	SERVICEABLE	400.00	-
1	FRONT N/S SPORT RIM (SN)	DAMAGED	650.00	500.00
			1,078.00	528.00
	LABOUR			
	TO REMOVE AND REFIT DAMAGE PARTS, TEST FOR PROPER FUNCTIONING AND FOCUS OF HEADLAMPS.		50.00	20.00
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE.		300.00	200.00
	TO CHECK AND RE-ADJUST (COMPUTERIZED) ALL WHEEL ALIGNMENT.		200.00	80.00
	TO REMOVE AND REFIT THE DOOR LOCK MECHANISM, REGULATOR GEAR, WINDOW GLASS, HANDLE, INNER BOARD, HINGES, CHANNEL TO FACILITATE THE REPAIRS.		200.00	60.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT AND N/S ROCKER PANEL.		1,600.00	680.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POILISHING AND WAXING ARE ALSO AVAILABLE.		1,600.00	800.00
	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION.		150.00	60.00
			4,100.00	1,900.00
	GRAND TOTAL		20,887.68	14,491.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			11,500.00

Report Ref No. CS3/INC19015594/Usf3s2-1

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.