

ASS. REC. BY:

REF:

03/FCT/9017580/ K1 d3ⁿ²

Special Instruction:

SUBJECT

Kenneth

ASSIGNMENT (Office)

(WS)

From (Person):

Sithern

of

FCT

Date/Time:

4/10/19 6:03pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKS 4267R

Insured:

SHC 7092C

at Workshop m/s

Lai Hwat (Meng Kee)

Tel:

64538110

of

160 San Ming Drive # 0401

Policy No:

Claim No:

D19006365 MF SH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

2/10/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

(DS)

H.O.D. Endorsement:

Date/Time:

10:02am 7/10/19

Person Contacted:

Jenny

Vehicle-IN (OUT)

Date/Time

Action/Instruction (/) Estimate

SKS 4267R x

SHC 7092C - 08/8MO/2019 5:19:1 / M1gh3ed

D.O.A. 14/3/2019

11/10/19

Sent Prel. by email

ASS. REC. BY:

REF:

1041

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

1-B1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKS 4267R Yr Regn: 04, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Peugeot 3008 cc 1560

Colour:

M.P. White

A/C: Insured / Std / NI / NA

Sp. Reading

65201

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF 30491408 ES199P70

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/50R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

2/10/19

D.O.A.

7/10/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 File pass to

23/12/19 PIP \$3662-49 (Red \$1107-20, 23%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 23/12/19 Typist

Report Format:

Lump Sum / I.B.I. (\$) :

PIP \$3662-49

Days Of Repair:

3

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Fees:

Others:

TOTAL

124

90

90

17

242



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19006365MFSH

Date: 11 Oct 2019

Our Ref: CS/FCI19017580/Kyd3

The Motor Claims Department
MS First Capital Insurance Ltd

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKS4267R.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 07/10/2019 at the premises of M/s LAI HUAT (MENG KEE), and have the following to report:-

Workshop Estimate Amount	: S\$ <u>4,769.69</u>
Revised Estimate Amount	: S\$ <u>3,909.99</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:
The vehicle sustained damages
at the rear portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	04-10-2019	Our Ref No. D19006365MFSH
Accident Date	02-10-2019	Claim Type. Third Party
Insured Vehicle	SHC7092C	Third Party Vehicle. SKS4267R
Survey Location	160 SIN MING DRIVE #04-01/#04-02/#07-03 SIN MING AUTOCITY	
Contact Person.	JENNY LIM	
Contact No.	64538110/ 0	Fax No. 64596267
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LAI HUAT (MENG KEE) MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Friday, October 11, 2019 11:52 AM
To: 'CWS Motor Claims'
Cc: 'Sithara'; SUR
Subject: SURVEY ASSESSMENT - D19006365MFSH/1
Attachments: SKS4267R DOA 02102019 REVERT.pdf

Dear Sir/ Madam

Enclosed preliminary revised of vehicle SKS4267R
Date of survey : 07/10/2019
Number of days : 3 days

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Monday, October 07, 2019 10:06 AM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D19006365MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer will arrange.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Friday, 4 October 2019 6:03 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19006365MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

萊發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267

GST No: M2-0128609-3

UEN: 199407592C

ESTIMATE

EST. No EST0023436

Ng Kwee Hin

Page 1 of 1
Your ref. TP-SHC 7092C MS FC
Job No. 70917
Our ref. 19/10/08
Payment
Date 4/10/2019

Attn

Vehicle No SKS 4267R
Vehicle Model Peugeot 3008
Accident on 2/10/2019

*Not Withheld
Resurvey Repair
3 days*

Quantity	Unit	Description	Unit price	Disc. pct	Amount
Supply of Parts - Nett item					
1.00	Pc	Rear bumper (complete)	1,477.66		<i>Bu</i> 1,477.66 ✓
1.00	Pc	Rear bumper diffuser	600.33		<i>Bu</i> 600.33 ✓
1.00	Pc	Rear tailgate lower garnish	997.00		<i>D11</i> 997.00 ✓
1.00	Pc	Rear bumper tow cover	87.66		<i>An</i> 87.66 X
Special nett item					
1.00	Pc	Rear number plate	35.00		<i>Bu</i> 35.00 ✓
1.00	Set	Rear reversing camera + installation	250.00		<i>An</i> 250.00 X
Labour & Misc					
1.00		To transfer parking sensor	60.00		60.00 ✓
1.00		To dismantle + renew above parts	350.00		350.00 <i>300</i>
1.00		To spray paint (pearl white)	600.00		600.00 <i>440</i>

Sub-Total
GST 7.00%
Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Companies

4,457.65
312.04
4,769.69

Acknowledged by Repairer
Date

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

Ky

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No: EST0023436
Ng Kwee Hin

Page: 1 of 1
Your ref: TP-SHC 7092C MB FC
Job No: 70917
Our ref: 19.10.08
Payment Date: 4/10/2018

Attn:

Vehicle No: SKS 4267R
Vehicle Model: Peugeot 3008
Accident on: 21/10/2018

Not Notified

Peugeot 3008

83662.49 ✓ 3 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts - Nett item					
1.00	Pc	Rear bumper (complete)	1,477.00		<i>Bu</i> 1,477.00 ✓
1.00	Pc	Rear bumper diffuser	600.33		<i>Bu</i> 600.33 ✓
1.00	Pc	Rear tailgate lower garnish	997.00		<i>Bu</i> 997.00 ✓
1.00	Pc	Rear bumper tow cover	57.55		<i>Bu</i> 57.55 X
Special nett item:					
1.00	Pc	Rear number plate	35.00		<i>Bu</i> 35.00 ✓
1.00	Set	Rear reversing camera installation	250.00		<i>Bu</i> 250.00 X
Labour & Misc:					
1.00		To transfer parking sensor	60.00		60.00 ✓
1.00		To dismantle + renew above parts	350.00		350.00 <i>3 days</i>
1.00		To spray paint (pearl white)	600.00		600.00 <i>4 days</i>
Sub-Total					4,457.65
GST 7.00%					312.04
Total					S\$ 4,769.69

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。此外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19017580/Kyd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 24-12-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7092C	Veh. Inspected	SKS 4267R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19006365MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	04/10/2019	
2. Vehicle Particulars & Condition				
Make & Model	PEUGEOT 3008 (A)	c.c	1560	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	VF30U9HD8ES199970	Colour	METALLIC PEARL WHITE	
Odometer	65201	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	DUNLOP	7 mm	
L/H Front Tyre	225/50 R17	DUNLOP	7 mm	
R/H Rear Tyre	225/50 R17	DUNLOP	7 mm	
L/H Rear Tyre	225/50 R17	DUNLOP	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/10/2019	Inspection Date	07/10/2019	
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 4267R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (COMPLETE) (N)	BUCKLED	1,477.66	1,477.66
1	REAR BUMPER DIFFUSER (N)	BENT	600.33	600.33
1	REAR TAILGATE LOWER GARNISH (N)	DISTORTED	997.00	997.00
1	REAR BUMPER TOW COVER (N)	SERVICEABLE	87.66	-
	LESS 10% DISCOUNT		-	-307.50
			3,162.65	2,767.49
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN)	BENT	35.00	35.00
1	SET REAR REVERSING CAMERA + INSTALLATION (SN)	SERVICEABLE	250.00	-
			285.00	35.00
LABOUR				
	TO TRANSFER PARKING SENSOR.		60.00	60.00
	TO DISMANTLE + RENEW ABOVE PARTS.		350.00	300.00
	TO SPRAY PAINT (PEARL WHITE).		600.00	440.00
	TO REMOVE + REFIX REVERSING CAMERA. (ADDITIONAL)		60.00	60.00
			1,070.00	860.00
GRAND TOTAL			4,517.65	3,662.49
RECOMMENDED COST OF REPAIRS				3,662.49

Report Ref No. CS/FCI19017580/Kyd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.