

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Oct 2019 Edit Reg		07 Oct 2019 00:00 Edit Adj Rpt	S\$4,603.60 Edit Estimates	S\$4,603.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: NEC SING TRADING , Co. Reg. No.: -									
Main Claimant: NG CHOON TECK MELVYN , ID: S9302574A									
Vehicle Reg. No.:	SMM2585T	Date of Loss:	04/10/2019 16:00 - :59 [3 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2638860911SG	Policy/Cover Note No.:	1700070029 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLT6407Z	Policy No. (Claimant):	5110537539						
		Excess:							
Repairer:	Premium Carz Services Pte Ltd (HQ) 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki, 417883 Kaki Bukit - Tel: 66369100								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 16/10/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (02/07/2020): Alert - Adj Mandate Approved (S\$5211.05) - SMM2585T - Claim Handler: Chan, Kian ... - AIG_SG_EXPRESS (16/04/2020): Alert - Adj Mandate Approved (S\$5111.05) - SMM2585T - Claim Handler: Chan, Kian ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMM2585T (2638860911SG)**
[SLT6407Z]
TP
NG CHOON TECK MELVYN
Oct 4 2019 4:00PM
[NEC SING TRADING]
Premium Carz Services Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Letters/Correspondences				
			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit
Assessment Reports				
			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	25/02/20 12:04	Adjuster Immediate Advice		Load HTM
2	24/04/20 11:56	Adjuster Immediate Advice		Load HTM
Photos/Images				
			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	25/11/19 17:30	General View		Load JPG ☒
2	25/11/19 17:30	General View		Load JPG ☒
3	25/11/19 17:30	General View		Load JPG ☒
4	25/11/19 17:30	General View		Load JPG ☒
5	25/11/19 17:30	General View		Load JPG ☒
6	25/11/19 17:30	General View		Load JPG ☒
7	25/11/19 17:30	General View		Load JPG ☒
8	25/11/19 17:30	General View		Load JPG ☒
9	25/11/19 17:30	General View		Load JPG ☒
10	25/11/19 17:30	General View		Load JPG ☒
11	25/11/19 17:30	General View		Load JPG ☒
12	25/11/19 17:30	General View		Load JPG ☒
13	25/11/19 17:30	General View		Load JPG ☒
14	25/11/19 17:30	General View		Load JPG ☒
15	25/11/19 17:30	General View		Load JPG ☒
16	25/11/19 17:30	General View		Load JPG ☒
17	25/11/19 17:30	General View		Load JPG ☒
18	25/11/19 17:30	General View		Load JPG ☒
19	25/11/19 17:30	General View		Load JPG ☒
20	25/11/19 17:30	General View		Load JPG ☒
21	25/11/19 17:30	General View		Load JPG ☒
22	25/11/19 17:30	General View		Load JPG ☒
23	25/11/19 17:30	General View		Load JPG ☒
24	25/11/19 17:30	General View		Load JPG ☒
25	25/11/19 17:30	General View		Load JPG ☒
26	25/11/19 17:30	General View		Load JPG ☒
27	25/11/19 17:31	Reinspection Photo		Load JPG ☒
28	25/11/19 17:31	Reinspection Photo		Load JPG ☒
29	25/11/19 17:31	Reinspection Photo		Load JPG ☒
30	25/11/19 17:31	Reinspection Photo		Load JPG ☒
31	25/11/19 17:31	Reinspection Photo		Load JPG ☒
32	25/11/19 17:31	Reinspection Photo		Load JPG ☒
33	25/11/19 17:31	Reinspection Photo		Load JPG ☒

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
34	25/11/19 17:31	Reinspection Photo		Load JPG	☒
35	25/11/19 17:31	Reinspection Photo		Load JPG	☒
36	25/11/19 17:31	Reinspection Photo		Load JPG	☒
37	25/11/19 17:31	Reinspection Photo		Load JPG	☒
38	25/11/19 17:31	Reinspection Photo		Load JPG	☒
39	25/11/19 17:31	Reinspection Photo		Load JPG	☒
40	25/11/19 17:31	Reinspection Photo		Load JPG	☒
41	25/11/19 17:31	Reinspection Photo		Load JPG	☒
42	25/11/19 17:31	Reinspection Photo		Load JPG	☒
43	25/11/19 17:31	Reinspection Photo		Load JPG	☒
44	25/11/19 17:31	Reinspection Photo		Load JPG	☒
45	25/11/19 17:31	Reinspection Photo		Load JPG	☒
46	25/11/19 17:31	Reinspection Photo		Load JPG	☒
47	25/11/19 17:31	Reinspection Photo		Load JPG	☒
48	25/11/19 17:31	Reinspection Photo		Load JPG	☒
49	25/11/19 17:31	Reinspection Photo		Load JPG	☒
50	25/11/19 17:31	Reinspection Photo		Load JPG	☒
51	25/11/19 17:31	Reinspection Photo		Load JPG	☒
52	25/11/19 17:31	Reinspection Photo		Load JPG	☒
53	25/11/19 17:31	Reinspection Photo		Load JPG	☒
54	25/11/19 17:31	Reinspection Photo		Load JPG	☒
55	25/11/19 17:31	Reinspection Photo		Load JPG	☒
56	25/11/19 17:31	Reinspection Photo		Load JPG	☒
57	25/11/19 17:31	Reinspection Photo		Load JPG	☒
58	25/11/19 17:31	Reinspection Photo		Load JPG	☒
59	25/11/19 17:31	Reinspection Photo		Load JPG	☒
60	25/11/19 17:31	Reinspection Photo		Load JPG	☒
61	25/11/19 17:31	Reinspection Photo		Load JPG	☒
62	25/11/19 17:31	Reinspection Photo		Load JPG	☒
63	25/11/19 17:31	Reinspection Photo		Load JPG	☒
64	25/11/19 17:31	Reinspection Photo		Load JPG	☒
65	25/11/19 17:31	Reinspection Photo		Load JPG	☒
66	25/11/19 17:31	Reinspection Photo		Load JPG	☒
67	25/11/19 17:31	Reinspection Photo		Load JPG	☒
68	25/11/19 17:31	Reinspection Photo		Load JPG	☒
69	25/11/19 17:31	Reinspection Photo		Load JPG	☒
70	25/11/19 17:31	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/10/19 14:21	TP GIA REPORT		Load PDF	
2	07/01/20 15:22	LETTER TO OI		Load PDF	
3	25/02/20 11:51	TP ESTIMATE-MARKED-FINAL		Load PDF	
4	02/04/20 15:11	TP LOD		Load PDF	
5	24/04/20 11:39	Email from TP reject offer		Load PDF	
6	20/07/20 14:40	Authorisation to Act		Load PDF	
7	20/07/20 14:40	LTA SEARCH		Load PDF	
8	20/07/20 14:40	Release Voucher		Load PDF	
9	20/07/20 14:40	RENTAL RECEIPT		Load PDF	
10	20/07/20 14:40	WORKSHOP INVOICE		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	09/10/19 14:10	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLT6407Z (Insd veh)	Model:	HONDA VEZEL 1.5 (A)
	SMM2585T (TP veh)		
Date of Accident:	04/10/2019		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:\$	12,457.02	
Final Repair Cost	:\$	4,603.60	
Loss of Use	:\$	days at \$0.00 per day	
Rental (if any)	:\$	600.00 6 days	
LTA / GIA Search Fee	:\$	7.45	
Others:	:\$		
	:\$		
Final Settlement Sum	:\$	5,211.05	
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability ____ 100 ____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: ____	
BOLA Liability: ____ (%)		Assessed Liability (*): ____ 0 ____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Premium Carz Services Pte Ltd	:\$	5,211.05
2)		:\$	
3)		:\$	
4)		:\$	

NUR SHAQILAH BTE ABDOL WAHAB

20 Jul
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG19017588/AKA3S2**Date:** 20/07/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700070029
Claimant Vehicle No :	SMM2585T	Insured Vehicle No :	SLT6407Z
Date of Loss:	04/10/2019	Nature of Claim:	TP
		Claim No:	2638860911SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM2585T	Engine No:	L15B5568753
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11318713
Reg. Date:	24/06/2019 (Man. Year: 2019)	Odometer:	8701 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,587.02	3,253.60	6,333.42	66.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,870.00	1,350.00	1,520.00	52.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	12,457.02	4,603.60	7,853.42	63.04
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,211.05		

INSPECTION

Date of Assignment:	07/10/2019	
Date Inspected:	07/10/2019	Inspected At: Premium Carz Services Pte Ltd (HQ) 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Dented	1,300.90 FL	*1,100.00 FL
2	2		*TAIL GATE ABSORBERS	Not Necessary	470.40 FL	*- FL
3	2		*TAIL GATE HINGES	Not Necessary	136.00 FL	*- FL
4	4		*TAIL GATE WINDSCREEN GLASS MOULDING	Necessary	261.60 FL	*261.60 FL
5	1		*TAIL GATE WEATHERSTRIP	Not Necessary	185.20 FL	*- FL
6	1		*TAIL GATE HODA LOGO	Not Necessary	55.60 FL	*- FL
7	1		*TAIL GATE VEZEL EMBLEM	Necessary	57.60 FL	*57.60 FL
8	1		*TAIL GATE GARNISH	Not Necessary	240.80 FL	*- FL
9	1		*TAIL GATE CHROME (NPA)	Not Necessary	0.00 FL	*- FL
10	1		*TAIL GATE REFLECTOR RH	Not Necessary	290.70 FL	*- FL
11	1		*TAIL GATE REFLECTOR LH	Not Necessary	290.70 FL	*- FL
12	1		*TAIL GATE LOCK	Damaged	180.40 FL	*180.40 FL
13	1		*TAIL GATE LOWER CATCH	Not Necessary	42.00 FL	*- FL
14	1		*TAIL GATE TRIMBOARD	Not Necessary	246.00 FL	*- FL
15	1		*TAIL LAMP RH	Cut	572.00 FL	*465.00 FL
16	1		*TAIL LAMP LH	Not Necessary	572.00 FL	*- FL
17	1		*TAIL LAMP GARNISH RH	Repair	296.00 FL	*- FL
18	1		*TAIL LAMP GARNISH LH	Not Necessary	296.00 FL	*- FL
19	1		*REAR BUMPER	Deformed	963.20 FL	*880.00 FL
20	1		*REAR BUMPER SIDE RETAINER RH	Necessary	33.60 FL	*33.60 FL
21	1		*REAR BUMPER SIDE RETAINER LH	Necessary	33.60 FL	*33.60 FL
22	1		*REAR BUMPER REFLECTOR RH	Cut	151.20 FL	*151.20 FL
23	1		*REAR BUMPER REFLECTOR LH	Not Necessary	151.20 FL	*- FL
24	2		*REAR NUMBER PLATE LAMP	Not Necessary	96.40 FL	*- FL
25	1		*REAR END PANEL	Repair	530.80 FL	*- FL
26	1		*REAR END PANEL GARNISH	Deformed	114.00 FL	*114.00 FL
27	1		*REAR END PANEL GARNISH CLIP	Necessary	4.30 FL	*4.30 FL
28	1		*BUZZER	Not Necessary	176.00 FL	*- FL
29	1		*SPARE TYRE PANEL	Repair	1,230.20 FL	*- FL
30	1		*SPARE TYRE BOARD	Not Necessary	450.20 FL	*- FL
31	1		*TOOLS FOAM (NPA)	Not Necessary	0.00 FL	*- FL
32	1		*EXHAUST SILENCER	Repair	721.10 FL	*- FL
33	1		*REAR NUMBER PLATE W/CASING	Not Necessary	70.00 FS	*- FS
34	10		*REAR BUMPER CLIP	Necessary	43.00 FS	*30.00 FS
35	8		*TAIL GATE TRIMBOARD CLIP	Not Necessary	34.40 FS	*- FS
36	1		*SET REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
37	1		*REVERSE CAMERA	Not Necessary	588.00 FS	*- FS
38	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
39	1		*REAR EXHAUST CHROME	Bent	176.30 FS	*120.00 FS
40	3		*SPOILER CLIP	Not Necessary	27.00 FS	*- FS
41	1		*REAR UNDER COVER	Deformed	273.20 FL	*273.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,671.60	3,964.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,084.58	710.90
Total Parts (\$\$)	9,587.02	3,253.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING.	New	60.00	30.00
2	PANEL BEATING CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS.	New	1,200.00	600.00
3	SPRAY PAINTING ALL AFFECTED PARTS & AREAS.	New	1,400.00	600.00
4	TO SPRAY ANTI-RUST UNDERCOAT.	New	90.00	0.00
5	TO REMOVE AND REFIT TAIL GATE GLASS.	New	120.00	120.00
Gross Labour Cost (\$\$)			2,870.00	1,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >