



Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel : 6636 9100 Fax : 6636 9113

Date : 05/10/2019

TO: **AIG Asia Pacific Insurance Pte Ltd**
AIG Building
78 Shenton Way #07-16
Singapore 079120

Ichanchou

Our Customer : Ng Choon Teck Melvyn

Vehicle No : SMM2585T

Model : Honda Vezel 1.5X CVT

Manufacture Year : 2019

Date of Accident : 04/10/2019

Total Estimate Repair Days : 10

Total Pages : 2

Attn : Motor Claims Department

Fax : 6415 3727

Re: Repair Estimate For Third Party Claim against SLT6407Z

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Tail gate <i>Painted</i>	1	\$1,300.90	\$1,300.90	<i>7100</i>
2	Tail gate absorbers <i>new</i>	2	\$235.20	\$470.40	<i>+</i>
3	Tail gate hinges <i>new</i>	2	\$68.00	\$136.00	<i>+</i>
4	Tail gate windscreen glass moulding <i>new</i>	4	\$65.40	\$261.60	<i>+</i>
5	Tail gate weatherstrip <i>new</i>	1	\$185.20	\$185.20	<i>+</i>
6	Tail gate "Honda" logo <i>new</i>	1	\$55.60	\$55.60	<i>+</i>
7	Tail gate "Vezel" emblem <i>new</i>	1	\$57.60	\$57.60	<i>+</i>
8	Tail gate garnish <i>new</i>	1	\$240.80	\$240.80	<i>+</i>
9	Tail gate chrome <i>new</i>	1			<i>+</i>
10	Tail gate reflector RH <i>new</i>	1	\$290.70	\$290.70	<i>+</i>
11	Tail gate reflector LH <i>new</i>	1	\$290.70	\$290.70	<i>+</i>
12	Tail gate lock <i>new</i>	1	\$180.40	\$180.40	<i>+</i>
13	Tail gate lower catch <i>new</i>	1	\$42.00	\$42.00	<i>+</i>
14	Tail gate trimboard <i>new</i>	1	\$246.00	\$246.00	<i>+</i>
15	Tail lamp RH <i>cut</i>	1	\$572.00	\$572.00	<i>465</i>
16	Tail lamp LH <i>new</i>	1	\$572.00	\$572.00	<i>+</i>
17	Tail lamp garnish RH <i>new</i>	1	\$296.00	\$296.00	<i>+</i>
18	Tail lamp garnish LH <i>new</i>	1	\$296.00	\$296.00	<i>+</i>
19	Rear bumper <i>new</i>	1	\$963.20	\$963.20	<i>880</i>
20	Rear bumper side retainer RH <i>new</i>	1	\$33.60	\$33.60	<i>+</i>
21	Rear bumper side retainer LH <i>new</i>	1	\$33.60	\$33.60	<i>+</i>
22	Rear bumper reflector RH <i>new</i>	1	\$151.20	\$151.20	<i>+</i>
23	Rear bumper reflector LH <i>new</i>	1	\$151.20	\$151.20	<i>+</i>
24	Rear number plate lamp <i>new</i>	2	\$48.20	\$96.40	<i>+</i>
25	Rear end panel <i>new</i>	1	\$530.80	\$530.80	<i>+</i>
26	Rear end panel garnish <i>new</i>	1	\$114.00	\$114.00	<i>+</i>
27	Rear end panel garnish clip <i>new</i>	1	\$4.30	\$4.30	<i>+</i>
28	Buzzer <i>new</i>	1	\$176.00	\$176.00	<i>+</i>
29	Spare tyre panel <i>new</i>	1	\$1,230.20	\$1,230.20	<i>+</i>
30	Spare tyre board <i>new</i>	1	\$450.20	\$450.20	<i>+</i>
31	Tools foam <i>new</i>	1			<i>+</i>
32	Exhaust silencer <i>new</i>	1			<i>+</i>
		<i>328130</i>	Total	\$9,428.60	
		<i>2625.04</i>	Less 20%	\$1,885.72	
			Sub Total 1	\$7,542.88	
A.	Spare Parts (S/Nett)				
1	Rear number plate w/casing <i>new</i>	1	\$70.00	\$70.00	<i>+</i>

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
2	Rear bumper clip <i>nu</i>	10	\$4.30	\$43.00	30
3	Tail gate trimboard clip <i>nu</i>	8	\$4.30	\$34.40	4.2
4	Reverse sensor (set) <i>Dangd</i>	1	\$250.00	\$250.00	200
5	Reverse camera <i>nu</i>	1	\$588.00	\$588.00	2
6	Tail gate windscreen sealant <i>nu</i>	1	\$60.00	\$60.00	✓
Sub-Total 2				\$1,045.40	
Total for Parts				\$8,588.28	
B.	Labour				
1	To check wiring.			\$60.00	30
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$1,200.00	600
3	Spray painting all affected parts & areas.			\$1,400.00	600
4	To spray anti-rust undercoat.			\$90.00	2
5	To remove and refit tail gate glass.			\$120.00	✓
Total Labour				\$2,870.00	
Total Repair Cost				\$11,458.28	

Supplementary 338.56

12,457.02#

Total: 4603.60
(part by part)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Yours faithfully,

Aun Teng
f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	Adrian L
Contact	96893735
Survey Date	07/10/19
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

0804p