

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email: mg3solution@gmail.com

TO	: AIG	DATE	: 4-Oct-19
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLQ9697Z	Jia Le	
MODEL	: MERCEDES BENZ S350	WDD2211562A344694	
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 3-Oct-19
		TIME	: 12:10HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>torn</i>	1	\$ 1,889.50	\$ 1,889.50 ✓
2	FRONT BUMPER SIDE RETAINER <i>RH 2pc</i>	2	\$ 130.00	\$ 260.00 ✓ 130
3	FRONT BUMPER INNER GARNISH <i>cracked</i>	1	\$ 180.00	\$ 180.00 ✓
4	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 1,180.00	\$ 1,180.00 ✗
5	FRONT BUMPER CENTRE SPONGE <i>new</i>	1	\$ 344.00	\$ 344.00 ✗
6	FRONT BUMPER SIDE SPONGE RH <i>cracked</i>	1	\$ 155.30	\$ 155.30 ✓
7	FRONT BUMPER FOGLAMP RH <i>new</i>	1	\$ 512.00	\$ 512.00 ✗
8	FRONT BUMPER SENSOR <i>new 1 piece dtd</i>	3	\$ 380.00	\$ 1,140.00 ✗ 260
9	FRONT GRILLE WITH CHROME <i>cracked</i>	1	\$ 980.30	\$ 980.30 ✓
10	FRONT HEADLAMP (HID) <i>cracked</i>	1	\$ 3,837.00	\$ 3,837.00 ✓ 3455
11	FRONT HEADLAMP NOZZEL WITH MOTOR <i>new</i>	1	\$ 566.30	\$ 566.30 ✗
12	FRONT HEADLAMP NOZZEL COVER <i>new</i>	1	\$ 80.30	\$ 80.30 ✓
13	FRONT FENDER <i>dented</i>	1	\$ 1,850.30	\$ 1,850.30 ✓ 1084
14	FRONT FENDER INNER COWLING <i>torn</i>	1	\$ 180.00	\$ 180.00 ✓

83944
755496

TOTAL PRICE	\$ 13,155.00
LESS 10%	\$ 1,315.50
SUB TOTAL PRICE	\$ 11,839.50

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP(SET) <i>new</i>	1	\$ 30.00	\$ 30.00 ✓
2	FRONT GRILLE CLIP(SET) <i>new</i>	1	\$ 30.00	\$ 30.00 20
3	FRONT FENDER INNER COWLING CLIP(SET) <i>new</i>	1	\$ 30.00	\$ 30.00 ✓
4	WHEEL RIM <i>lit</i>	1	\$ 1,800.00	\$ 1,800.00 700

780

TOTAL \$ 1,890.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,400.00	500	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	500	
3	WIRING CHECK	\$ 280.00	30	
4	REFOCUS HEADLAMP BEAM	\$ 80.00	x	
5	TUFF COAT	\$ 280.00	x	
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 380.00	100	

TOTAL

\$3,820.00

1130

TOTAL PARTS COST : \$ 13,729.50
TOTAL LABOUR COST : \$ 3,820.00
TOTAL REPAIR COST : \$ 17,549.50

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian King
2/s 04/10/19.

04 Days

total 9464.96
4/s 7.5K